

## CHAPTER 71 - LIST OF EFFECTIVE PAGES

<u>Chapter Section Subject</u>	<u>Task</u>	<u>Title</u>	<u>Pages</u>	<u>Date</u>
71		LIST OF EFFECTIVE PAGES	* 1 - 4	Apr. 15/2024
71		TABLE OF CONTENTS	1 - 4	Apr. 15/2023
71-00-06	INT-801-A01	TROUBLESHOOTING - INTRODUCTION	1 - 2	Apr. 15/2023
71-00-06	RPU-801-A01	FAILURES FOUND DURING OPERATION - LIST OF FAILURES OBSERVED DURING ENGINE OPERATION	101 - 102	Apr. 15/2023
71-00-06	RPM-801-A01	FAILURES FOUND DURING MAINTENANCE - LIST OF FAILURES OBSERVED DURING MAINTENANCE	101 - 102	Oct. 15/2022
71-00-06	811-801-A01	"FUEL P" (LOW FUEL PRESSURE) NOT DISPLAYED AT POWER UP - TROUBLESHOOTING	101 - 102	Oct. 15/2022
71-00-06	811-802-A01	"FUEL FLT" (FUEL FILTER PRE-BLOCKAGE) DISPLAYED AT POWER UP - TROUBLESHOOTING	101 - 102	Oct. 15/2022
71-00-06	811-803-A01	"ENG P" (LOW OIL PRESSURE) NOT DISPLAYED AT POWER UP - TROUBLESHOOTING	101 - 102	Oct. 15/2022
71-00-06	811-806-A01	UNJUSTIFIED FIRE SIGNAL - TROUBLESHOOTING	101 - 102	Aug. 30/2011
71-00-06	811-807-A01	ABORTED START - FLAMES AT THE EXHAUST - TROUBLESHOOTING	101 - 104	Apr. 15/2022
71-00-06	811-808-A01	ABORTED START - SLOW START OR STAGNATION - TROUBLESHOOTING	101 - 110	Apr. 15/2022
71-00-06	811-810-A01	ABORTED START - ENGINE FLAME-OUT AFTER IGNITION - TROUBLESHOOTING	101 - 104	Oct. 15/2021
71-00-06	811-811-A01	NO EXTINGUISHING OF THE LOW FUEL PRESSURE "FUEL P" DURING THE STARTING PHASE - TROUBLESHOOTING	101 - 104	Oct. 15/2022
71-00-06	811-812-A01	NO EXTINGUISHING OF THE LOW OIL PRESSURE "ENG P" DURING THE STARTING PHASE - TROUBLESHOOTING	101 - 104	Oct. 15/2023
71-00-06	812-801-A01	ABORTED START - GAS GENERATOR NOT DRIVEN - TROUBLESHOOTING	101 - 104	Apr. 15/2020

\* Page modified following update No. 50

# SAFRAN HELICOPTER ENGINES

## ARRIUS 2 F

MAINTENANCE MANUAL

<u>Chapter Section Subject</u>	<u>Task</u>	<u>Title</u>	<u>Pages</u>	<u>Date</u>
71-00-06	812-805-A01	ABORTED START - T4.5 OVERTEMPERATURE DURING START - TROUBLESHOOTING	101 - 106	Apr. 15/2023
71-00-06	812-816-A01	ABORTED START - NO IGNITION - TROUBLESHOOTING	101 - 108	Apr. 15/2022
71-00-06	813-801-A01	MTOP RATING (MAXIMUM TAKE-OFF POWER) NOT REACHED - TROUBLESHOOTING	101 - 102	Apr. 15/2018
71-00-06	813-802-A01	FLUCTUATION OF N1 AND T4.5 - TROUBLESHOOTING	101 - 102	Aug. 30/2011
71-00-06	813-803-A01	NO TORQUE INDICATION - TROUBLESHOOTING	101 - 102	Oct. 15/2021
71-00-06	813-804-A01	OIL TEMPERATURE TOO LOW ON THE DIAGRAM VALUES DISPLAY - TROUBLESHOOTING	101 - 102	Oct. 15/2022
71-00-06	813-805-A01	OIL PRESSURE TOO LOW ON THE DIAGRAM VALUES DISPLAY - TROUBLESHOOTING	101 - 104	Oct. 15/2022
71-00-06	813-806-A01	"ENG P" MESSAGE (LOW OIL PRESSURE) DURING ENGINE RUNNING - TROUBLESHOOTING	101 - 104	Oct. 15/2022
71-00-06	813-807-A01	CONTROLLED ENGINE SHUTDOWN NOT POSSIBLE - TROUBLESHOOTING	101 - 102	Aug. 30/2011
71-00-06	813-808-A01	NR DRIFT - TROUBLESHOOTING	101 - 106	Oct. 15/2019
71-00-06	813-810-A01	POWER ASSURANCE CHECK - INCORRECT MARGIN - TROUBLESHOOTING	101 - 108	Apr. 15/2022
71-00-06	813-811-A01	UNJUSTIFIED FIRE SIGNAL - TROUBLESHOOTING	101 - 102	Aug. 30/2011
71-00-06	813-812-A01	ENGINE PARAMETER OSCILLATIONS: TORQUE, NG, NR - TROUBLESHOOTING	101 - 104	Oct. 15/2019
71-00-06	813-813-A01	NONCOMPLIANT TEMPERATURE MARGIN - TROUBLESHOOTING	101 - 108	Apr. 15/2019
71-00-06	814-802-A01	ABNORMAL NOISES - TROUBLESHOOTING	101 - 104	Oct. 15/2022
71-00-06	814-804-A01	VIBRATIONS - TROUBLESHOOTING	101 - 102	Apr. 15/2018
71-00-06	814-806-A01	SURGE - TROUBLESHOOTING	101 - 104	Apr. 15/2018

\* Page modified following update No. 50

List of Effective Pages

**71**

Page 2  
Apr. 15/2024

<u>Chapter Section Subject</u>	<u>Task</u>	<u>Title</u>	<u>Pages</u>	<u>Date</u>
71-00-06	814-807-A01	SMELLS IN THE CABIN - TROUBLESHOOTING	101 - 108	Oct. 30/2018
71-00-06	814-808-A01	N1 OVERSPEED - TROUBLESHOOTING	101 - 102	Feb. 28/2013
71-00-06	814-809-A01	N2 OVERSPEED (FROM 104 % TO 110 %) - TROUBLESHOOTING	101 - 104	Feb. 28/2014
71-00-06	814-811-A01	TORQUE LIMITATIONS EXCEEDED - TROUBLESHOOTING	101 - 104	Feb. 28/2013
71-00-06	814-812-A01	T4.5 OVERTEMPERATURE DURING FLIGHT - TROUBLESHOOTING	101 - 104	Apr. 15/2023
71-00-06	814-813-A01	"FUEL PRESS" MESSAGE (LOW FUEL PRESSURE) - TROUBLESHOOTING	101 - 104	Mar. 30/2017
71-00-06	814-814-A01	"FUEL FILT" MESSAGE (PRE-BLOCKAGE OF THE FUEL FILTERING ELEMENT) - TROUBLESHOOTING	101 - 102	Oct. 15/2022
71-00-06	814-816-A01	NO N1 SPEED INDICATION - TROUBLESHOOTING	101 - 102	Feb. 28/2013
71-00-06	814-817-A01	NO N2 SPEED INDICATION - TROUBLESHOOTING	101 - 102	Feb. 28/2013
71-00-06	814-818-A01	NO T4.5 INDICATION - TROUBLESHOOTING	101 - 102	Feb. 28/2013
71-00-06	814-819-A01	T4.5 INDICATION ERRONEOUS - TROUBLESHOOTING	101 - 102	Feb. 28/2013
71-00-06	814-820-A01	TORQUE INDICATION ERRONEOUS - TROUBLESHOOTING	101 - 104	Oct. 15/2021
71-00-06	814-823-A01	OIL OVERTEMPERATURE ON THE DIAGRAM VALUES DISPLAY - TROUBLESHOOTING	101 - 104	Oct. 15/2022
71-00-06	814-826-A01	FLUCTUATING OIL PRESSURE - TROUBLESHOOTING	101 - 104	Aug. 30/2011
71-00-06	814-828-A01	OIL PRESSURE TOO HIGH - TROUBLESHOOTING	101 - 102	Apr. 15/2018
71-00-06	814-829-A01	"ENG CHIP" MESSAGE (MAGNETIC PARTICLES) - TROUBLESHOOTING	101 - 104	Oct. 15/2022
71-00-06	814-837-A01	N2 OVERSPEED (OVER 110 %) - TROUBLESHOOTING	101 - 102	Feb. 28/2014
71-00-06	814-842-A01	FIRE ALARM OR NO FIRE ALARM - TROUBLESHOOTING	101 - 104	Apr. 15/2020

\* Page modified following update No. 50

# SAFRAN HELICOPTER ENGINES

## ARRIUS 2 F

MAINTENANCE MANUAL

<u>Chapter Section Subject</u>	<u>Task</u>	<u>Title</u>	<u>Pages</u>	<u>Date</u>
71-00-06	815-804-A01	TESTING OF THE NOT COMPLIANT PREFERENCE INJECTOR - TROUBLESHOOTING	101 - 102	Aug. 30/2011
71-00-06	816-801-A01	DEFECTIVE AUTOMATIC CYCLE COUNTING - TROUBLESHOOTING	101 - 104	Feb. 28/2013
71-00-06	816-802-A01	EXHAUST FUMES AFTER ENGINE SHUTDOWN - TROUBLESHOOTING	101 - 106	Feb. 28/2012
71-00-06	816-805-A01	POPPING OUT OF THE VISUAL BLOCKAGE INDICATOR OF THE FUEL FILTERING ELEMENT - TROUBLESHOOTING	* 101 - 104	Apr. 15/2024
71-00-06	816-806-A01	LEAKAGE AT THE POWER-DRIVE DRAIN - TROUBLESHOOTING	101 - 104	Apr. 15/2023
71-00-06	816-806-B01	LEAKAGE AT THE POWER-DRIVE DRAIN - TROUBLESHOOTING	101 - 104	Apr. 15/2023
71-00-06	816-807-A01	POPPING OUT OF THE VISUAL BLOCKAGE INDICATOR OF THE OIL FILTERING ELEMENT - TROUBLESHOOTING	101 - 104	Aug. 30/2011
71-00-06	816-808-A01	OIL LEAKAGE AT THE STARTER POWER DRIVE - TROUBLESHOOTING	101 - 102	Oct. 15/2019
71-00-06	816-811-A01	OIL TRACES IN THE AIR INTAKE CASING - TROUBLESHOOTING	101 - 104	Apr. 15/2019
71-00-06	816-815-A01	OIL CONSUMPTION MORE THAN 0.3 L/HR - TROUBLESHOOTING	101 - 102	Aug. 30/2011
71-00-06	816-816-A01	EXTERNAL LEAKS AT ADJUSTED FUEL CONTROL UNIT ASSEMBLY - TROUBLESHOOTING	101 - 102	Aug. 30/2011
71-00-06	816-826-A01	ABNORMAL VIBRATION, ABNORMAL NOISE OR ACCESSORY DAMAGE - TROUBLESHOOTING	101 - 102	Apr. 15/2022
71-00-06	816-827-A01	INJECTION PROTECTION TEST NOT CONFORM - TROUBLESHOOTING	101 - 102	Oct. 15/2022

\* Page modified following update No. 50

List of Effective Pages

Page 4

**71**

Apr. 15/2024