

Aircraft Registration:	9M-BOB	Serial No:	11212	Date:	25/08/2023	Page No:	2
Aircraft Hours:	3839:03	Landings:	4445.00	Engine 1:	1063:53	Engine 2:	3042:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Repetitive SBs	ASB 109EP-177 NEW ISSUE PART II	ATA 62 - INSPECTION OF MAIN ROTOR SCISSOR CHAIN	-	-	25	APPLICABILITY: ALL A109E HELICOPTERS NOT FULFILLING PART I OR PART IV OR PART V REQUIREMENTS. PART II: EVERY 25 FH UNTIL REPLACEMENT OF AFFECTED COMPONENTS AS PER PART III.
Repetitive SBs	ASB 109EP-177 REV. A PART V (EASA AD No.: 2022-0037 PAR	ATA 62 - INSPECTION OF MAIN ROTOR SCISSOR CHAIN (EVERY 200)	3681:20	3881:20	200	APPLICABILITY: APPLICABLE TO ALL A109E HELICOPTER PART V: EVERY 200FH
Repetitive SBs	ASB 109EP-177 PART IV (EASA AD No.: 2022-0037 PARA (2)	ATA 62 - INSPECTION OF MAIN ROTOR SCISSOR CHAIN (EVERY 50FH)	3805:33	3855:33	50	APPLICABILITY: APPLICABLE TO ALL A109E HELICOPTER PART IV: EVERY 50FH LAST COMPLIED : 9M-BOB-12317 AJL 000029 26-DEC-22 3756:28 9M-BOB-14491 AJL 000064 21-MAR-23 3805:33
Repetitive SBs	ASB NO 109EP-176 // EASA AD NO. 2021-0067, NEW ISSUE	INSPECTION OF ROTOR BRAKE CONTROL CABLE P/N 109-0506-17-113	3751:58	3851:58	100	LAST COMPLIED: 9M-BOB-11253 AJL 000019 25-NOV-22 3751:58
Repetitive SBs	SB109EP-173 REV. A PART I (EASA AD 2022-0153)	ATA 53 - CENTRAL FUSELAGE FRAME ASSY AT STA 1815, INSPECTION (EVERY 100FH)	3751:58	3851:58	100	TIC-A109E-22-0026 LAST COMPLIED: 9M-BOB-11253 AJL 000019 25-NOV-22 3751:58
Repetitive SBs	SB109EP-085 REV. A (EASA AD NO.: 2020-0230	INSPECTION OF THE TIP CAP P/N 709-0103-29-109 OF THE MA)	3805:33	3855:33	50	LAST COMPLIED : 9M-BOB-11425 AJL 000029 3756:28 26-DEC-22 9M-BOB-14491 AJL 000064 3805:33 21-MAR-23
Repetitive SBs	SB109EP-158 REV. B PART II	ATA 53 - LEFT AND RIGHT COUNTERTORQUE CROSSBEAM FITTING	2983:00	4483:00	1500	LAST COMPLIED @ 2983 LANDINGS