GalaxyAerospace TECHNICAL INSTRUCTION COMPLIANCE TIC REF							TIC REF N	O TIC-AW139-21-0206			
maintenance, repair, overhaul	DATE ISSU									E 31 MAR 2021	
A. TECHNICAL PUBLICATION (To Fill Up as Necessary)											
PUBLICATION TITLE	LEONARDO HELICOPTERS - AW139 SERVICE BULLETIN										
	ATA 30	- V	VINDSHIELD WASHING								
REV NO	SB NO. 139-587, NEW ISSUE REV. DATE									25 MARCH 2021	
		Ø	AC TYPE:	✓ AC S/N:			☐ ENG. TYPE:			□ ENG. S/N:	
APPLICABLE TO			AW139		41356 41358 31807 31726 31731 31809 31855 31913 31289 31291 31899						
		PRO	OPELLER TYPE:	[	☐ PROPELLER S/N:		☐ APU TYPE:			☐ APU S/N:	
		CC	OMPONENT:					QUIPMENT:			
DISTRIBUTIONS	DISTRIBUTIONS POPERATOR PAMO PCAMO QUALITY					□ OTHER:					
B. TECHNICAL SER	RVICE (	٩p	plicability review pr	ior to	o sentencing as nece	essa	ıry)				
TIME LIMIT IMPOSED		]	ONE TIME INSPECTION		REPETITIVE INSPECTION		OPTIONAL REQUIREMENT			MODIFICATION REQUIRED	
SPECIAL TOOLS REQUI	IRED [	]	INFORMATION ONLY		NOT APPLICABLE		OTHER:				
REMARKS:  41356 - EFFECTIVITY: ALL AB139/AW139 HELICOPTERS EQUIPPED WITH WIPER ARM LH P/N 3G3040V00951 AND WIPER ARM RH P/N 3G3040V01051.  APPLICABILITY: NOT APPLICABLE SINCE THE WIPER ARM P/N IS NOT AFFECTED. REFER TO ATTACHMENT.  41358 - EFFECTIVITY: ALL AB139/AW139 HELICOPTERS EQUIPPED WITH WIPER ARM LH P/N 3G3040V00951 AND WIPER ARM RH P/N 3G3040V01051.  APPLICABILITY: NOT APPLICABLE SINCE THE WIPER ARM P/N IS NOT AFFECTED. REFER TO ATTACHMENT.								ı	NAME SIGNATURE & DATE  MOHD AMIRUL AIMAN SAMSUDDIN 6 APR 2021		

Page 1 of 6 GAM/CAMO-001R2

#### 31807 - APPLICABILITY:

Require physical inspection to confirm if helicopter installed wiper arm LH P/N 3G3040V00951 and wiper arm RH P/N 3G3040V01051.

### **REASON:**

This Service Bulletin is issued in order to provide the necessary instruction on how to perform the installation of kit windshield washing P/N 4G3040F00116.

### COMPLIANCE TIME:

At Customer's option.

#### 31726 - APPLICABILITY:

Require physical inspection to confirm if helicopter installed wiper arm LH P/N 3G3040V00951 and wiper arm RH P/N 3G3040V01051.

#### REASON:

This Service Bulletin is issued in order to provide the necessary instruction on how to perform the installation of kit windshield washing P/N 4G3040F00116.

### COMPLIANCE TIME:

At Customer's option.

### 31731 - APPLICABILITY:

Require physical inspection to confirm if helicopter installed wiper arm LH P/N 3G3040V00951 and wiper arm RH P/N 3G3040V01051.

#### REASON:

This Service Bulletin is issued in order to provide the necessary instruction on how to perform the installation of kit windshield washing P/N 4G3040F00116.

### **COMPLIANCE TIME:**

At Customer's option.

### 31809 - APPLICABILITY:

Require physical inspection to confirm if helicopter installed wiper arm LH P/N 3G3040V00951 and wiper arm RH P/N 3G3040V01051.

#### REASON:

This Service Bulletin is issued in order to provide the necessary instruction on how to perform the installation of kit windshield washing P/N 4G3040F00116.

### COMPLIANCE TIME:

At Customer's option.

## 31855 - APPLICABILITY:

Require physical inspection to confirm if helicopter installed wiper arm LH P/N 3G3040V00951 and wiper arm RH P/N 3G3040V01051.

## REASON:

This Service Bulletin is issued in order to provide the necessary instruction on how to perform the installation of kit windshield washing P/N 4G3040F00116.

## COMPLIANCE TIME:

At Customer's option.

# 31913 - APPLICABILITY:

Require physical inspection to confirm if helicopter installed wiper arm LH P/N 3G3040V00951 and wiper arm RH P/N 3G3040V01051.

## REASON:

This Service Bulletin is issued in order to provide the necessary instruction on how to perform the installation of kit windshield washing P/N 4G3040F00116.

## COMPLIANCE TIME:

At Customer's option.

Page 2 of 6 GAM/CAMO-001R2

Requ RH P REAS This S kit win COM At Cu 3129 Requ	Require physical inspection to confirm if helicopter installed wiper arm LH P/N 3G3040V00951 and wiper arm RH P/N 3G3040V01051.  REASON:  This Service Bulletin is issued in order to provide the necessary instruction on how to perform the installation of kit windshield washing P/N 4G3040F00116.  COMPLIANCE TIME:  At Customer's option.  B1291 - APPLICABILITY:  Require physical inspection to confirm if helicopter installed wiper arm LH P/N 3G3040V00951 and wiper arm RH P/N 3G3040V01051.									
kit wii	This Service Bulletin is issued in order to provide the necessary instruction on how to perform the installation of kit windshield washing P/N 4G3040F00116.  COMPLIANCE TIME:  At Customer's option.									
Requ RH P REAS This S kit wii	31899 - APPLICABILITY: Require physical inspection to confirm if helicopter installed wiper arm LH P/N 3G3040V00951 and wiper arm RH P/N 3G3040V01051. REASON: This Service Bulletin is issued in order to provide the necessary instruction on how to perform the installation of kit windshield washing P/N 4G3040F00116. COMPLIANCE TIME: At Customer's option.									
C. C	ONTINUING AIRWORTHINI	ESS	MANAGE	MENT (CAM) MAN	NAGI	ER / DEPUTY				
	MAINTENANCE SCHEDULE AMENT.   PUBLICATION AMENDMENT   PRE-PLANNED WORKSHEET					COMPONENT SEND OFF FOR COMPLIANCE				
REMARKS:  1) TO RAISE WORK ORDER FOR FURTHER EVALUATION OF SB APPLICABILITY TO COMPONENT INSTALLED ON ALL AW139 FLEET.										NAME SIGNATURE & DATE  AMIR ABDULLAH  16 APR 2021
D. C	AMO PLANNER									
	ENTRY TO MAINT. FORECAST			PREPARE WORK PACK	AGE			PLAN EME	BODIM	ENT
	□   SPARE ORDER   □   MANPOWER QUALIFICATION   □   TOOLING									
RFI	MARKS:									NAME

SIGNATURE & DATE

MOHD NOR AZLIZAN

Page 3 of 6 GAM/CAMO-001R2

Page 4 of 6 GAM/CAMO-001R2

(1)	OPTIONAL SB TO REVIEW WITH OPERATOR FOR COMPLIANCE IF APPLCABLE
-----	---

Page 5 of 6 GAM/CAMO-001R2

<sup>(2)</sup> PGU & JBPM FLEET WILL ISSUE WORK ORDER FOR PHYSICAL CHECK

<sup>(3)</sup> YTLPG - NOT APPLICABLE

<sup>(4)</sup> AERONET UPDATED AS OPTIONAL AND YTLPG AS NOT APPLICABLE

TIC COMPLIANCE CHECKLIST BY CAM MANAGER (Tick and Fill up as necessary)							
COMPLIANCE		REMARKS:	NAME CICNATURE & DATE				
YES	NO	OPTIONAL. TO UPDATE SECTION E UPON REVIEWED WITH	SIGNATURE & DATE				
	•	OPERATOR	ZATY NADHIRA MOHAMED ZUHARI 6 MAY 2021				

Page 6 of 6 GAM/CAMO-001R2