


A. TECHNICAL PUBLICATION (To Fill Up as Necessary)

PUBLICATION TITLE	EASA - EC120B AIRWORTHINESS DIRECTIVES			
	ATA 25 - EQUIPMENT / FURNISHINGS &€" EMERGENCY FLOATATION SYSTEM SUPPLY HOSE CONNECTION /			
	RETAINING RING &€" INSPECTION			
REV NO	AD NO. 2023-0166	REV. DATE	25 AUG 2023	
	NEW ISSUE			
APPLICABLE TO	<input checked="" type="checkbox"/> AC TYPE:	<input checked="" type="checkbox"/> AC S/N:	<input type="checkbox"/> ENG. TYPE:	<input type="checkbox"/> ENG. S/N:
	EC120B	1275 1487 1089		
	<input type="checkbox"/> PROPELLER TYPE:	<input type="checkbox"/> PROPELLER S/N:	<input type="checkbox"/> APU TYPE:	<input type="checkbox"/> APU S/N:
	<input type="checkbox"/> COMPONENT:	<input type="checkbox"/> EQUIPMENT:		
DISTRIBUTIONS	<input checked="" type="checkbox"/> OPERATOR	<input checked="" type="checkbox"/> AMO	<input checked="" type="checkbox"/> CAMO	<input type="checkbox"/> QUALITY <input type="checkbox"/> OTHER:

B. TECHNICAL SERVICE (Applicability review prior to sentencing as necessary)

<input checked="" type="checkbox"/> TIME LIMIT IMPOSED	<input checked="" type="checkbox"/> ONE TIME INSPECTION	<input type="checkbox"/> REPETITIVE INSPECTION	<input type="checkbox"/> OPTIONAL REQUIREMENT	<input type="checkbox"/> MODIFICATION REQUIRED
<input type="checkbox"/> SPECIAL TOOLS REQUIRED	<input type="checkbox"/> INFORMATION ONLY	<input type="checkbox"/> NOT APPLICABLE	<input type="checkbox"/> OTHER:	

<p>REMARKS:</p> <p>1275 - APPLICABILITY: NOT APPLICABLE DUE AIRCRAFT NO LONGER MANAGED BY GAM-CAMO</p> <p>REASON: THIS AD IS ISSUED TO PROVIDE INSTRUCTIONS FOR INSPECTION TO ENSURE RETAINING RING IS PRESENT IN ALL EFS. AD ALSO PROHIBITS REINSTALLATION OF AN AFFECTED PART.</p> <p>COMPLIANCE: NOT TO BE COMPLIED WITH</p> <p>SPARES/TOOLS: N/A</p> <p>1487 - APPLICABILITY: APPLICABLE DUE TO AIRCRAFT IS FITTED WITH FLOATS P/N 215674-2 AND 215675-2 ADN IS MANUFACTURED BEFORE JANUARY 2021 (2007)</p> <p>REASON: THIS AD IS ISSUED TO PROVIDE INSTRUCTIONS FOR INSPECTION TO ENSURE RETAINING RING IS PRESENT IN ALL EFS. AD ALSO PROHIBITS REINSTALLATION OF AN AFFECTED PART.</p> <p>COMPLIANCE:</p> <p>PARA 1: AT NEXT REMOVAL OF EFS OR WITHIN 19 MONTHS (08/04/2025)</p> <p>PARA 2: BFF IF DISCREPANCY FOUND DURING PARA 1</p> <p>PARA 3: FOR INFORMATION ONLY</p> <p>SPARES/TOOLS: N/A</p>	<p>NAME SIGNATURE & DATE</p>  <p>MUHAMMAD IHSAN MASRI 30 AUG 2023</p>
--	--

1089 - APPLICABILITY: NOT APPLICABLE DUE AIRCRAFT NOT FITTED WITH FLOAT

REASON: THIS AD IS ISSUED TO PROVIDE INSTRUCTIONS FOR INSPECTION TO ENSURE RETAINING RING IS PRESENT IN ALL EFS. AD ALSO PROHIBITS REINSTALLATION OF AN AFFECTED PART.

COMPLIANCE: NOT TO BE COMPLIED WITH

SPARES/TOOLS: N/A


C. CONTINUING AIRWORTHINESS MANAGEMENT (CAM) MANAGER / DEPUTY

<input type="checkbox"/> MAINTENANCE SCHEDULE AMENT.	<input type="checkbox"/> PUBLICATION AMENDMENT	<input checked="" type="checkbox"/> PRE-PLANNED WORKSHEET	<input type="checkbox"/> COMPONENT SEND OFF FOR COMPLIANCE
--	--	---	--

REMARKS:

1. CAMO PLANNER TO INCLUDE AD INSPECTION IN AERONET FOR COMPLIANCE & MONITORING AND RECORD AS APPLICABLE.

NAME
SIGNATURE & DATE



ZATY NADHIRA MOHAMED
ZUHARI
30 AUG 2023

D. CAMO PLANNER

<input type="checkbox"/> ENTRY TO MAINT. FORECAST	<input type="checkbox"/> PREPARE WORK PACKAGE	<input type="checkbox"/> PLAN EMBODIMENT
<input type="checkbox"/> SPARE ORDER	<input type="checkbox"/> MANPOWER QUALIFICATION	<input type="checkbox"/> TOOLING

REMARKS:

NAME
SIGNATURE & DATE

TIC COMPLIANCE CHECKLIST BY CAM MANAGER (Tick and Fill up as necessary)

COMPLIANCE		REMARKS:	NAME SIGNATURE & DATE
YES	NO		