



Publ. number	Issue Date	TC Holder	Type	Subject
2021-0049	2021-02-18	AIRBUS	A318, A319, A320, A321	Fire Protection - Operational Limitation Doors - Cargo Door Seals - Cleaning / Greasing / Replacement
CF-2021-04	2021-02-17	BOMBARDIER	BD-700	Powerplant - Engine Mount - Bushing Missing
2021-0039R2	2021-02-17	BOEING	737	Return to Service
2021-0047	2021-02-16	DASSAULT AVIATION	Falcon 2000, Falcon 7X, Falcon 900EX	Standard Practices and Structures - DECOMATIC Titanium Bolts - Replacement
2021-0048	2021-02-16	AIRBUS HELICOPTERS	AS 350 / EC 130, AS 355, SA/AS 365 / EC 155	Main Rotor - Pitch Rod Upper Links - Marking / Inspection
CF-2021-03	2021-02-16	AIRBUS CANADA LP	BD-500 (A220 Series)	Equipment/Furnishings - Mid Fuselage Insulation - Potential Damage to Insulation Blankets below Over Wing Emergency Exit Door (OWEED)
2021-0045	2021-02-16	AIRBUS	A318, A319, A320, A321	Equipment / Furnishings - 80VU Rack Attachments - Inspection / Repair
2021-0046	2021-02-12	AIRBUS HELICOPTERS	EC 120 B	Main Rotor - Hub Scissors / Attachment Bolts - Inspection / Replacement
BR-2021-02-01	2021-02-12	YABORA INDUSTRIA AERONAUTICA S.A.	ERJ 190	Airplane Flight Manual Change / Mid Electronic Bay and Backup Smoke Detectors Electrical Wiring - Modification
2018-0289R1	2021-02-10	AIRBUS	A318, A319, A320, A321	Fuselage - Service Door Stop Fitting Hole - Inspection / Repair
US-2020-26-16	2021-02-09	PIPER AIRCRAFT INC.	PA-28 (Archer), PA-28 (Cadet), PA-28 (Cherokee), PA-28 (Warrior), PA-28R (Arrow), PA-32 (Cherokee Six), PA-32R (Lance)	NOT ADOPTED - EASA DECISION ATTACHED