



Publ. number	Issue Date	TC Holder	Type	Subject
2022-0027	2022-02-18	FOKKER SERVICES	F28	Time Limits / Maintenance Checks - Airworthiness Limitations Section Part 2 - Airworthiness Limitations Items and Safe Life Items - Implementation
G-2022-0002	2022-02-18	BAE SYSTEMS (OPERATIONS) LTD	BAE146	Auto Flight - Autopilot Disconnect - Modification
G-2022-0003	2022-02-18	BAE SYSTEMS (OPERATIONS) LTD	HS748	Time Limits / Maintenance Checks - Environmental Damage Corrosion Prevention and Control Programme - Amendment
US-2022-04-05	2022-02-18	BOEING	757, 767	Aircraft Flight Manual - Limitations / Operating Procedures - Amendment
CF-2022-04	2022-02-16	AIRBUS CANADA LP	BD-500 (A220 Series)	Fuselage - Painted Radome Diverter Strips
2021-0002R1	2022-02-16	AIRBUS	A318, A319, A320, A321	Stabilizers - Rudder - Inspection
2022-0026	2022-02-16	AIRBUS	A319, A320, A321	Equipment / Furnishings - Galley / Container End Stop - Replacement
2017-0102R1	2022-02-16	SAFRAN HELICOPTER ENGINES	ARRIEL 2	Engine Fuel & Control - High Pressure / Low Pressure Fuel Pump Metering Unit - Inspection / Replacement
US-2022-03-19	2022-02-15	GENERAL ELECTRIC	Passport 20	Time Limits / Maintenance Checks - Airworthiness Limitations Section - Amendment
US-2022-03-16	2022-02-15	GENERAL ELECTRIC	GENx	Engine - Turbine Compressor Discharge Pressure Bolted Joint - Inspection
2022-0025	2022-02-15	AIRBUS	A330, A340	Landing Gear - Main and Centre Landing Gear Bogie Pivot Pins - Inspection / Replacement
US-2021-26-10	2022-02-15	BOEING	747	Equipment / Furnishings - BMS 8-39 Urethane Foam Fire-Retardant Seals - Replacement
US-2022-02-09	2022-02-15	INTERNATIONAL AERO ENGINES AG	V2500-()5	Engine - High-Pressure Turbine Disks - Inspection / Replacement
US-2022-03-23	2022-02-14	GARMIN INTERNATIONAL INC., TEXTRON AVIATION INC.	EASA STC 10033158, FAA STC SA01535WI-D, STC EASA.IM.A.S.03191, 300 (Super King Air)	Flight Controls - Rudder Yaw Servo Software - Update
US-2022-02-01	2022-02-11	SIKORSKY	S-92	Main Rotor - Swashplate Assembly - Inspection / Removal
2021-0283R1	2022-02-11	AIRBUS HELICOPTERS	AS 350 / EC 130	Fuselage - Rear Transmission Bearing Support - Inspection
US-2022-02-02	2022-02-09	BELL TEXTRON INC. (BTI)	204B, 205, 210, 212	[Correction] Main Rotor - Hub Strap Pins - Replacement



Publ. number	Issue Date	TC Holder	Type	Subject
BR-2022-02-01	2022-02-08	EMBRAER S.A.	ERJ 170	Time Limits / Maintenance Checks - Airworthiness Limitation Section / Maintenance Program - Revision
CF-2020-18R2	2022-02-08	BELL TEXTRON CANADA LTD (BTCL)	429	Indicating / Recording System - Rotorcraft Flight Manual - Prohibit the use of Map-Mode on Left Hand Side and Right Hand Side Display Units