



Publ. number	Issue Date	TC Holder	Type	Subject
2022-0204R1	2023-02-17	AIRBUS S.A.S.	A318, A319, A320, A321	[Correction] Landing Gear - Main Landing Gear Sliding Tube - Inspection / Replacement
2023-0040	2023-02-16	ROLLS-ROYCE DEUTSCHLAND Ltd & Co KG	RB211 TRENT 800	Engine - Intermediate Pressure Compressor Rotor Shaft - Inspection
CF-2023-09	2023-02-15	BOMBARDIER	BD-100	Pneumatic - Non-Conforming Bleed Air Leak Detection System Sensing Elements
CF-2023-07	2023-02-15	BOMBARDIER	CL-600 (Challenger)	Flight Controls - Uncommanded Flap Extension
G-2023-0001	2023-02-15	BRITTEN-NORMAN AIRCRAFT LTD	BN2, BN2A (Islander), BN2A Mark III (Trislander), BN2B (Islander), BN2T (Turbine Islander)	Landing Gear - Nose and Main Landing Gear - Recording of Life / Replacement
CF-2023-08	2023-02-14	AIRBUS CANADA LP	BD-500 (A220 Series)	Equipment / Furnishings - Connector Not To Specification - Emergency Power Supply Unit
2023-0038	2023-02-14	PILATUS AIRCRAFT LTD	PC-24	Airplane Flight Manual - Section Normal Procedures / Electrical Burning Smell in Cabin - Amendment
CF-2023-06	2023-02-13	BOMBARDIER	CL-600 (Challenger)	Oxygen System - Passenger Oxygen Mask Lanyard Improper Sleeve Loop Crimping and/or Ends not Sealed
2023-0036	2023-02-13	AIRBUS HELICOPTERS	EC 120 B	Main Rotor - Hub Scissors Assembly / Attachment Bolts - Inspection / Replacement
ISR-I-35-2022-12-9	2023-02-13	BOEING, ISRAEL AEROSPACE INDUSTRIES LTD	737, CAA Israel STC SA136, CAA Israel STC SA160, CAA Israel STC SA299, CAA Israel STC SA300, EASA STC 10015542, EASA STC 10016227, EASA STC 10079576, EASA STC 10079988, STC EASA.IM.A.S.01426, STC EASA.IM.A.S.02479	Supernumerary Oxygen System Mask Replacement
CF-2023-05	2023-02-13	BOMBARDIER	CL-600 (Challenger)	Pneumatic - Non-Conforming Bleed Air Leak Detection System Sensing Elements
2023-0035	2023-02-10	LEONARDO S.p.A. HELICOPTERS	A109/A119	Rotors Flight Control - Collective Stick Torque Tube Assembly - Inspection / Replacement
2023-0034	2023-02-08	AIRBUS S.A.S.	A380	Fuselage - Frame 80 Fairing Outboard End Fitting Assemblies - Inspection
2023-0033	2023-02-08	AIRBUS S.A.S.	A380	Fuselage - Frame 72 Fairing Hardpoints - Inspection
2023-0031	2023-02-08	AIRBUS S.A.S.	A380	Landing Gear - Body Landing Gear Rear Axle - Replacement



Publ. number	Issue Date	TC Holder	Type	Subject
2023-0032	2023-02-08	AIRBUS S.A.S.	A380	Fuselage - Frame 67 Belly Fairing Joints - Inspection
US-2023-02-02	2023-02-07	GULFSTREAM AEROSPACE CORPORATION	GV	NOT ADOPTED - EASA DECISION ATTACHED
US-2023-01-13	2023-02-07	BOEING	DC-9, MD-88	Wings - Centre Wing Lower Stringers - Replacement
US-2023-02-12	2023-02-07	CONTINENTAL AEROSPACE TECHNOLOGIES, INC.	GTSIO-520, IO-470, IO-520, IO-550, IOF-550, LIO-470, LIO-520, LTSIO-520, O-470, TSIO-470, TSIO-520, TSIO-550, TSIOF-550, TSIOL-550	Power Plant - Cylinder Assembly or Intake Valve - Inspection / Replacement
US-2021-26-02	2023-02-07	GULFSTREAM AEROSPACE CORPORATION	GV	NOT ADOPTED - EASA DECISION ATTACHED
CF-2023-04	2023-02-06	AIRBUS CANADA LP	BD-500 (A220 Series)	Time Limits / Maintenance Checks - Airworthiness Limitations - Implementation