



Publ. number	Issue Date	TC Holder	Type	Subject
CF-2021-05R2	2021-03-05	BELL TEXTRON CANADA LTD (BTCL)	505 (Jet Ranger X)	Rotorcraft Flight Manual - Amendment / Pilot Collective Stick and Grip Assembly - Inspection
2021-0063	2021-03-05	AIRBUS	A380	Oxygen - Steel Braided Polyurethane Flexible Hoses - Replacement
2021-0064	2021-03-05	FOKKER SERVICES	F28	Fuselage - Forward Pressure Bulkhead - Inspection
2021-0061	2021-03-05	AIRBUS	A350	Indicating / Recording Systems - Flight Warning System - Modification; Aircraft Flight Manual - Ram Air Turbine Performance - Amendment
2021-0062	2021-03-05	CFM INTERNATIONAL	CFM56-5B	Engine - Low Pressure Turbine Rear Frames - Inspection / Replacement
CF-2021-07	2021-03-04	AIRBUS CANADA LP	BD-500 (A220 Series)	Time Limits / Maintenance Checks - Airworthiness Limitations - Implementation
US-2021-01-07	2021-03-04	BOEING	737	Air Conditioning - Environmental Control System / Equipment Cooling System - Inspection / Installation / Modification
CF-2021-06	2021-03-03	BOMBARDIER	CL-600 (Challenger)	Ice and Rain Protection - Wing Anti-Ice System - Wing Stall Prior to Touchdown due to Wing Leading Edge Icing
2021-0060	2021-03-03	GE AVIATION CZECH	M601	Time Limits / Maintenance Checks - Airworthiness Limitations Section / 04-10 Limitations and 04-20 Inspections - Amendment
US-2021-02-19	2021-03-02	BOEING	787	Fire Protection - Cargo Compartment Bilge Barrier Decompression Panels - Inspection / Replacement
US-2021-02-16	2021-03-02	BOEING	717	Ice and Rain Protection - Air Data Heat System - Modification
BR-2021-02-02	2021-03-02	YABORA INDUSTRIA AERONAUTICA S.A.	EMB-135, EMB-145	[Correction] Main Landing Gear Side Arm Strut Lower Bearing - Inspection / Replacement
2021-0059	2021-03-02	FOKKER SERVICES	F28	Wings - Front Spar Lower Boom - Inspection
2021-0058	2021-03-01	SAAB AB	340	Lights - Emergency Cabin Lighting Circuit Breaker 2LN - Replacement
US-2021-04-07	2021-03-01	PIPER AIRCRAFT INC.	PA-46 (Malibu)	Vacuum - Stall Warning Heat Control - Modification
US-2021-03-09	2021-02-26	BOEING	727	Wings - Structural Significant Items - Inspection
2021-0051	2021-02-26	AIRBUS	A380	[Correction] Flight Controls - Rudder Electrical Backup Hydraulic Actuator and Elevator Servo Control Solenoid Valves - Replacement ; Master Minimum Equipment List / Airplane Flight Manual - Amendment
2021-0057-E	2021-02-26	GROB AIRCRAFT SE	G 115	Flight Controls - Control Surface Hinge Bracket Attachment Bolts - Inspection
2021-0055-E	2021-02-25	AUSTRO ENGINE GMBH	E4	Engine - Oil Pump - Replacement



Publ. number	Issue Date	TC Holder	Type	Subject
2021-0056	2021-02-25	ROLLS-ROYCE DEUTSCHLAND Ltd & Co KG	RB211 TRENT 900	Engine - Low Pressure Turbine Seal Panel - Inspection / Replacement [Life Limitation]
2021-0053	2021-02-25	AIRBUS	A350	Flight Controls - Slat Transmission Shafts / Slat Power Control Unit Torque Sensing Units - Inspection
US-2021-02-15	2021-02-25	BOEING	747	Wings - Inboard Foreflaps - Inspection / Replacement
CF-2020-51R1	2021-02-25	DE HAVILLAND AIRCRAFT OF CANADA LTD.	DHC-8	Nacelles/Pylons - Attachment Pin Corrosion
US-2021-03-02	2021-02-25	GENERAL ELECTRIC	CF6-80C	Engine Fuel & Control - Hydromechanical Unit/Main Engine Control Idler Adapter on the Accessory Gearbox Assembly - Inspection / Replacement
2021-0054	2021-02-25	LEONARDO S.p.A. HELICOPTERS	AB139/AW139	Equipment / Furnishings - Life Raft Reservoir and Actuator Cable - Replacement / Inspection
US-2021-05-51	2021-02-24	PRATT & WHITNEY	PW4070, PW4080, PW4090	Engine - 1st-Stage Low-Pressure Compressor Blades - Inspection
BR-2021-02-01	2021-02-24	YABORA INDUSTRIA AERONAUTICA S.A.	ERJ 190	[Correction] Airplane Flight Manual Change / Mid Electronic Bay and Backup Smoke Detectors Electrical Wiring - Modification
2021-0052	2021-02-24	GE AVIATION CZECH	M601	Engine - Propeller Shaft - Replacement [Life Limit]
US-2021-02-13	2021-02-24	BOEING	737	Fuselage - Forward Galley Door Fuselage Skin / Bear Strap - Inspection
US-2021-02-07	2021-02-24	GENERAL ELECTRIC	GE _{nx}	Engine Fuel & Control - Cushioned Loop Clamp and Outer Fuel Manifold - Inspection / Replacement
2021-0050	2021-02-23	AIRBUS HELICOPTERS DEUTSCHLAND	EC135/635	Tail Rotor - Blades - Replacement / Re-identification