



Publ. number	Issue Date	TC Holder	Type	Subject
2021-0096	2021-03-31	LEONARDO S.p.A. HELICOPTERS	A109/A119	Rotors Flight Control - Collective Stick Torque Tube Assembly - Inspection / Replacement
2021-0095	2021-03-31	AEROLITE AG, LEONARDO S.p.A. HELICOPTERS	EASA STC 10017231, STC EASA.R.S.01403, AB139/AW139	Placards and Markings - Stretcher Unit / Placard - Installation
2021-0094	2021-03-31	AUSTRO ENGINE GMBH	E4	Engine - Oil Pump - Replacement
2021-0097	2021-03-31	CFM INTERNATIONAL	LEAP-1A/-1C	Engine - High Pressure Turbine Case - Replacement
2020-0226R1	2021-03-31	HOFFMANN PROPELLER GmbH & Co. KG	HO-V 72	Propellers - Propeller Hub - Inspection
2018-0048R1	2021-03-31	ROLLS-ROYCE DEUTSCHLAND Ltd & Co KG	RB211 TRENT 900	Time Limits / Maintenance Checks - Engine Time Limits Manual - Amendment
US-2021-06-04	2021-03-31	GULFSTREAM AEROSPACE CORPORATION	GV	Fuselage - Floor Beam Support Link Lower Bushing - Inspection / Airworthiness Limitations Section Revision
2021-0093	2021-03-30	AIRBUS	A300-600	Time Limits / Maintenance Checks - Airworthiness Limitations Section Part 2 / Damage Tolerant Airworthiness Limitation Items - Amendment
CF-2021-11	2021-03-30	DE HAVILLAND AIRCRAFT OF CANADA LTD.	DHC-8	Pneumatic System - Wing Check Valve Bleed Air Leak - Replacement
US-2021-06-10	2021-03-30	BOEING	747, 767	Fuel - Refuel Valves / Fueling Shut-off Valve - Master Minimum Equipment List Dispatch Limitations
US-2021-05-11	2021-03-30	BOEING	757	Flight Controls - Spoiler Control Module - Operational Test
2021-0092	2021-03-30	AIRBUS	A380	Pneumatic - Cross-Bleed Ducts - Inspection / Replacement
ISR-I-24-2018-09-7R1	2021-03-30	GULFSTREAM (GALP)	G150	Electrical Power - Upper and Lower Front Relay Box Replacement
US-2021-05-14	2021-03-29	AIR TRACTOR	AT-250/-300/-400, AT-401/-402/-500, AT-600/-800	Flight Controls - Trailing Edge Flap Control System - Inspection / Replacement
US-2021-05-18	2021-03-26	INTERNATIONAL AERO ENGINES AG	V2500-()5, V2500-A1	Engine - Diffuser Case M-Flange - Inspection
US-2021-02-06	2021-03-25	BOEING	787	Fire Protection - Maintenance or Inspection Program Revision
CF-2021-05R3	2021-03-25	BELL TEXTRON CANADA LTD (BTCL)	505 (Jet Ranger X)	Rotors Flight Control - Collective Controls - Failure of Pilot Collective Stick and Grip Assembly



Publ. number	Issue Date	TC Holder	Type	Subject
2021-0086	2021-03-24	AIRBUS HELICOPTERS	SA 330 / AS 332 / EC 225	Rotors Flight Control - Yaw Control Damper Support - Inspection / Replacement
2021-0088	2021-03-24	SAFRAN HELICOPTER ENGINES	ARRIUS 2	Engine Fuel & Control - Digital Engine Control Unit - Software Update
2021-0087	2021-03-24	AIRBUS	A380	Engine Fuel & Control - Master Minimum Equipment List - Handling Bleed Valve Inoperative - Amendment
BR-2020-07-01R1	2021-03-23	YABORA INDUSTRIA AERONAUTICA S.A.	ERJ 190	Aircraft Flight Manual - Engine N1 Setting Limitation - Amendment / Electronic Engine Control Software Upgrade