



| Publ. number | Issue Date | TC Holder | Type | Subject |
|-----------------|------------|--|--|--|
| 2024-0104 | 2024-05-24 | LEONARDO S.p.A. HELICOPTERS | AB212/AB412 | Fuselage - Left Upper Cap Angle - Inspection |
| CF-2024-17 | 2024-05-24 | BOMBARDIER | BD-100 | Time Limits/Maintenance Checks - Airworthiness Limitations |
| CF-2024-16 | 2024-05-24 | BOMBARDIER | CL-600 (Challenger) | Time Limits/Maintenance Checks - Airworthiness Limitations |
| 2021-0169R1 | 2024-05-24 | ROLLS-ROYCE DEUTSCHLAND Ltd & Co KG | TRENT 7000 | Engine - High Pressure Turbine Blades - Inspection |
| US-2024-10-04 | 2024-05-23 | PIPER AIRCRAFT INC. | PA-28 (Archer), PA-28R (Arrow), PA-34 (Seneca), PA-44 (Seminole) | Wings - Rear Wing Spar Attachment Fitting - Inspection |
| CF-2023-37R1 | 2024-05-23 | AIRBUS CANADA LP | BD-500 (A220 Series) | Standard Practices / Structures - Verification of Aircraft Repairs and Damage Assessments |
| 2024-0097R1 | 2024-05-23 | AIRBUS S.A.S. | A318, A319, A320, A321 | Fuselage - Centre Fuselage / Main Landing Gear Door Keel Beam Hinge and Actuator Fittings - Inspection |
| 2024-0103-CN | 2024-05-22 | AIRBUS S.A.S. | A300-600ST (Beluga) | CANCELLED: Wings - Flaps Beams No 2 - Inspections |
| BR-2024-05-09 | 2024-05-21 | EMBRAER S.A. | ERJ 170 | Main Landing Gear Locking-Stay Bracket Assembly - Inspection / Replacement |
| BR-2023-05-03R2 | 2024-05-17 | EMBRAER | EMB-505 (Phenom 300) | Equipment / Furnishings - Monuments Structural Reinforcements / Replacement of Fasteners |
| 2024-0102 | 2024-05-17 | ROLLS-ROYCE DEUTSCHLAND Ltd & Co KG | RB211 TRENT 700 | Engine - Low Pressure Compressor Blades - Inspection / Replacement |
| 2020-0195R1 | 2024-05-15 | ROLLS-ROYCE DEUTSCHLAND Ltd & Co KG | TRENT 1000 | Engine - Low Pressure Turbine Discs - Inspection |
| US-2024-06-15 | 2024-05-14 | GENERAL ELECTRIC | GE90 | [Correction] Engine - Interstage High-Pressure Turbine Rotor Seal - Inspections |
| 2024-0088 | 2024-05-14 | LEONARDO S.p.A. HELICOPTERS, MECAER AVIATION GROUP SpA | AB139/AW139, EASA STC 10017198, EASA STC 10030095 | [Correction] Placards and Markings - Rear Facing Seat(s) - Placard Installation |



| Publ. number | Issue Date | TC Holder | Type | Subject |
|--------------|------------|--------------------------------|------|---|
| 2024-0101 | 2024-05-14 | AIRBUS S.A.S. | A380 | Fuel - Engine Low Pressure Shut Off Valve Electrical Harness Routing - Modification |
| 2024-0087 | 2024-05-14 | AIRBUS S.A.S. | A380 | [Correction] Wings - Metallic Wing Rib Feet - Inspection |
| GA8-3-Amdt4 | 2024-05-14 | GA8 AIRVAN Pty Ltd (GippsAero) | GA8 | Forward Cargo Door Slide - Inspection |