



Publ. number	Issue Date	TC Holder	Type	Subject
2022-0163-E	2022-08-05	CEAPR	DR 400	Flight Controls - Flap Control Rods - Replacement
US-2022-15-09	2022-08-05	AVIATION PARTNERS BOEING, BOEING, VT MOBILE AEROSPACE ENGINEERING	EASA STC 10015659, FAA STC ST01518SE, STC EASA.IM.A.S.01636, 757, FAA STC ST03562AT	Fuselage - Fuselage Frame Web - Inspection
2022-0162	2022-08-05	AIRBUS S.A.S.	A380	Nacelles / Pylons - Thrust Reverser Intermediate Frame Fittings - Replacement
2022-0160-CN	2022-08-04	AIRBUS S.A.S.	A320	CANCELLED: Equipment / Furnishings - Overwing Escape Slide - Inspection
2022-0159-CN	2022-08-04	AIRBUS S.A.S.	A320	CANCELLED: Communications - Passenger Address System / Cabin Intercommunication Data System - Director 1 Replacement
2022-0157	2022-08-04	AIRBUS S.A.S.	A350	Fuel - Engine / Auxiliary Power Unit Low Pressure Shut-Off Valves and Auxiliary Power Unit Isolation Valve - Inspection / Replacement
2022-0158	2022-08-04	PILATUS AIRCRAFT LTD	PC-12	Landing Gear - Nose and Main Landing Gear Actuators - Replacement
US-2022-16-04	2022-08-04	GULFSTREAM AEROSPACE CORPORATION	GV	Horizontal Stabilizer Structure - Horizontal Stabilizer Lower Skin and Associated Bonded Doublers and Stringers - Inspections / Repair
2022-0161-E	2022-08-04	DASSAULT AVIATION	Falcon 7X	Aeroplane Flight Manual - Amendment
US-2022-16-01	2022-08-02	EMBRAER S.A.	ERJ 170, ERJ 190	Windows - NORDAM Passenger Windows - Inspections / Replacement
2022-0156	2022-08-02	AIRBUS S.A.S.	A350	Pneumatic - Bleed Gimbals at Wing to Pylon Interfaces - Modification
US-2022-16-03	2022-08-01	CONTINENTAL AEROSPACE TECHNOLOGIES, INC., LYCOMING ENGINES	GTSIO-520, IO-346, IO-470, IO-520, IO-550, LTSIO-520, O-470, TSIO-520, TSIOL-550, AEIO-320, AEIO-360, AEIO-540, AIO-320, AIO-360, GO-480, GSO-480, HIO-360, HIO-540, IGO-480, IGO-540, IGSO-480, IGSO-540, IO-320, IO-360, IO-540, IO-720, LIO-360, LTIO-540, O-235, O-320, O-360, O-540, TIGO-541, TIO-360, TIO-540, TIO-541, TVO-435, VO-435, VO-540	Ignition - Magneto Roller Bearings - Inspection / Replacement
2022-0155	2022-08-01	VULCANAIR S.p.A.	V1	Fuselage - Lower Fuselage Truss - Inspection
CF-2021-32R1	2022-08-01	MHI RJ Aviation ULC	CL-600 (Regional Jet)	Oxygen - Third Crew Member Oxygen Mask - Introduction of Chafing Protection for Flex Hose and Rerouting of Electrical Harness



Publ. number	Issue Date	TC Holder	Type	Subject
2022-0154	2022-08-01	LEONARDO S.p.A. HELICOPTERS	AB139/AW139	Tail Rotor - Damper Bracket - Inspection
2022-0032R1	2022-07-29	AIRBUS S.A.S.	A318, A319, A320, A321	Landing Gear - Braking and Steering Control Unit - Replacement / Master Minimum Equipment List - Amendment
2022-0153	2022-07-28	LEONARDO S.p.A. HELICOPTERS	A109/A119	Fuselage - Centre Fuselage Frame Assembly - Inspection / Repair
G-2022-0014	2022-07-28	BAE SYSTEMS (OPERATIONS) LTD	ATP	Engine Controls - Flight Idle Baulk Actuator and Rollover Lever Pawl - Inspection / Replacement
CF-2010-29R2	2022-07-26	BELL TEXTRON CANADA LTD (BTCL)	222, 230, 430	Hydraulic Power - Servo Actuator Piston Rod - Corrosion and Cracking
2022-0151	2022-07-26	AIRBUS S.A.S.	A318, A319, A320, A321	Fuselage - Lateral Cockpit Window Frame Upper Stiffener - Inspection
US-2022-15-03	2022-07-26	PRATT & WHITNEY	PW1500G, PW1900G	Engine - Low Pressure Compressor Rotor 1 - Inspection / Installation / Replacement
2022-0152-E	2022-07-26	LEONARDO S.p.A. HELICOPTERS	AB139/AW139	Tail Rotor - Duplex Bearings - Inspection / Replacement
CF-2022-40	2022-07-25	BOMBARDIER	BD-700	Wings - Revised Non-Destructive Testing Manual Procedure for Airworthiness Limitation Task Number 57-51-00-109
US-2022-15-01	2022-07-25	BOEING	787	Stabilizers - Vertical Fin Tension Bolt Holes - Inspection / Maintenance or Inspection Program - Revision