



Publ. number	Issue Date	TC Holder	Type	Subject
US-2023-13-05	2023-09-29	BOEING	737	Fuselage - Skin Lap Splices - Inspection / Repair
2023-0171-CN	2023-09-27	AIRBUS S.A.S., ELBE FLUGZEUGWERKE GmbH	A321, EASA STC 10071994	Cancelled: Wings - Centre Wing Box Rear Lower Spar and Slanted Beam - Inspection
2022-0241R1	2023-09-26	ROLLS-ROYCE DEUTSCHLAND Ltd & Co KG	TRENT 1000	Engine - High Pressure Turbine Seal - Inspection
US-2023-17-04	2023-09-22	CONTINENTAL AEROSPACE TECHNOLOGIES, INC., STRATUS TOOL TECHNOLOGIES, LLC	C-125, C145, GO-300, IO-360, IO-470, IO-520, IO-550, O-300, O-300 (RR), O-470, TSIO-360, TSIO-520, EASA STC 10040938, EASA STC 10040939, FAA STC SE09356SC, FAA STC SE10348SC, FAA STC SE8409SW	Engine - Oil Filter Adapter Gasket - Replacement
2023-0173	2023-09-20	AIRBUS S.A.S.	A310	Time Limits / Maintenance Checks - Airworthiness Limitations Section Part 1 / Safe Life Airworthiness Limitation Items - Amendment
2023-0172	2023-09-20	AIRBUS HELICOPTERS	SA 330 / AS 332 / EC 225	Equipment / Furnishings - Cabin Hoist Shear Toggle Switch Equipped Support - Replacement / Modification
US-2023-17-08	2023-09-19	GENERAL ELECTRIC	GE _{nx}	Engine - Stages 6-10 Compressor Rotor Spools and Forward Seals - Replacement
CF-2023-64	2023-09-19	AIRBUS CANADA LP	BD-500 (A220 Series)	Fuel Distribution - Twisted Motive Flow Flexible Fuel Line