



| Publ. number | Issue Date | TC Holder | Type | Subject |
|-----------------|------------|--------------------------------|----------------------|---|
| CF-2022-58 | 2022-10-13 | AIRBUS CANADA LP | BD-500 (A220 Series) | Time Limits / Maintenance Checks - Airworthiness Limitations - Implementation |
| US-2022-18-13 | 2022-10-12 | BOEING | 737 | Fuselage - Aft Pressure Bulkhead - Inspection |
| 2021-0253R1 | 2022-10-12 | AIRBUS S.A.S. | A340 | Time Limits / Maintenance Checks - Fuel Airworthiness Limitations - ALS Part 5 - Amendment |
| 2021-0252R1 | 2022-10-12 | AIRBUS S.A.S. | A330 | Time Limits / Maintenance Checks - Fuel Airworthiness Limitations - ALS Part 5 - Amendment |
| 2021-0251R1 | 2022-10-12 | AIRBUS S.A.S. | A340 | Time Limits / Maintenance Checks - System Equipment Maintenance Requirements - ALS Part 4 - Amendment |
| 2022-0209-E | 2022-10-12 | LEONARDO S.p.A. HELICOPTERS | AB139/AW139 | Harness Installation - Forward Roof Area - Inspection |
| 2021-0249R1 | 2022-10-12 | AIRBUS S.A.S. | A340 | Time Limits / Maintenance Checks - Airworthiness Limitations Section Part 3 - Certification Maintenance Requirements - Implementation |
| 2021-0248R1 | 2022-10-12 | AIRBUS S.A.S. | A330 | Time Limits / Maintenance Checks - Airworthiness Limitations Section Part 3 - Certification Maintenance Requirements - Implementation |
| 2021-0247R1 | 2022-10-12 | AIRBUS S.A.S. | A340 | Time Limits / Maintenance Checks - Safe Life Airworthiness Limitations Items - ALS Part 1 - Amendment |
| 2021-0246R1 | 2022-10-12 | AIRBUS S.A.S. | A330 | Time Limits / Maintenance Checks - Safe Life Airworthiness Limitations Items - ALS Part 1 - Amendment |
| BR-2011-02-01R1 | 2022-10-12 | EMBRAER S.A. | ERJ 190 | Main Landing Gear Retraction Actuators - Inspection / Replacement |
| BR-2022-09-01 | 2022-10-12 | EMBRAER S.A. | ERJ 190 | Flight Controls - Elevator / Rudder Power Control Units - Replacement |
| 2021-0250R1 | 2022-10-12 | AIRBUS S.A.S. | A330 | Time Limits / Maintenance Checks - System Equipment Maintenance Requirements - ALS Part 4 - Amendment |
| 2022-0208 | 2022-10-11 | AIRBUS HELICOPTERS DEUTSCHLAND | MBB-BK 117 | Rotorcraft Flight Manual - Emergency and Malfunction Procedures - Amendment |



| Publ. number | Issue Date | TC Holder | Type | Subject |
|---------------|------------|--------------------------------|--|--|
| US-2022-16-09 | 2022-10-10 | BOEING | 737 | Wings - Center Fuel Tank Fastener Locations - Preparation of Adequate Sealant Adhesion |
| 2022-0207 | 2022-10-10 | PILATUS AIRCRAFT LTD | PC-24 | Time Limits / Maintenance Checks - Airworthiness Limitations Section - Amendment |
| 2022-0206 | 2022-10-07 | ATR | ATR42, ATR72 | Instruments - New Avionics Suite - Replacement |
| 2015-0081-CN | 2022-10-07 | AIRBUS S.A.S. | A300-600, A300-600ST (Beluga), A310 | CANCELLED: Flight Controls - Trimmable Horizontal Stabilizer Actuator - Identification / Replacement |
| CF-2022-57 | 2022-10-06 | BOMBARDIER | BD-100 | Landing Gear - Nose Landing Gear Door Hinge Fitting Failure |
| CF-2022-54R1 | 2022-10-05 | MHI RJ Aviation ULC | CL-600 (Regional Jet) | Fuselage - Forward Engine Support Frame Fuselage Station 1051.30 - Inspection |
| US-2022-18-16 | 2022-10-05 | GENERAL ELECTRIC | CT7-8 | Time Limits / Maintenance Checks - Airworthiness Limitations Section - Amendment |
| US-2022-19-15 | 2022-10-05 | INTERNATIONAL AERO ENGINES LLC | PW1100 / PW1400 | Engine - High Pressure Turbine Stage 1 / 2 Disks - Inspection / Replacement |
| G-2022-0017 | 2022-10-04 | BRITTEN-NORMAN AIRCRAFT LTD | BN2, BN2A (Islander), BN2A Mark III (Trislander), BN2B (Islander), BN2T (Turbine Islander) | Flight Control - Primary Flight Controls - Inspection |
| US-2022-14-05 | 2022-10-04 | BOEING | 777 | [Correction] Flight Controls - Elevators, Rudder, and Rudder Tab - Inspections and Lubrication |
| 2022-0205 | 2022-10-04 | LEONARDO S.p.A. HELICOPTERS | AB139/AW139 | Tail Rotor - Damper Bracket - Inspection |