

### GALAXY AEROSPACE (M) SDN. BHD. [1040262-D]

Suite 11-14, Helicopter Centre, Malaysia International Aerospace Centre, Sultan Abdul Aziz Shah Airport, 47200 Subang, Selangor, Malaysia.

Tel: +603 7734 7226 | Fax: +603 7734 7526 www.galaxyaerospace.my | enquiry@galaxyaerospace.my

# **WORK ORDER**



To: SYSTEMATIC AVIATION SERVICES SDN. BHD.

Address: SAS Hangar Work Order Number: 2021-6513

Sultan Abdul Aziz Shah Airport
Subang Malaysia

Work Pack Reference: 9M-PEC-6513

Date Issued: 16/04/2021

Mr. Hairudeen bin Mat

Engineering Manager A/C Registration / SN: 9M-PEC/57060 hairudeen@sassb.com.my

**Sheet:** 1 **of** 3

# Description:

Attention:

Item	Description/Task/Inspection	Reference	Man Hours
1	6 M DAFR - CVR SYSTEM CHECK	BHT-429-CMM-V, CURTISS WRIGHT CONTROLS; PIM434-I, REV 21 DATE JAN 07/21 PARA 6.2, TABLE 7	(PLEASE ADVISE)
2	6 M ULB - CHECK / FUNCTIONAL TEST	BHT-429-CMM-V, CURTISS WRIGHT CONTROLS; PIM434-I, REV 21 DATE JAN 07/21 PARA 6.2, TABLE 7	(PLEASE ADVISE)
3	EVERY 6 M - TCCA AD CF-2016-11R2 PART II (ASB 429-15-21 REV B PART II)	TCCA AD CF-2016-11R2 PART II (ASB 429-15-21 REV B PART II)	(PLEASE ADVISE)
4	100 FH // 6M - ASB 429-19-47 REV B PART II COMPLIANCE.	SB 429-19-47 REV B PART II	(PLEASE ADVISE)
5	600 FH // 6 M BATTERY CAPACITY CHECK	GILL COMPONENT MAINTENANCE MANUAL (TELEDYNE BATTERY PRODUCT ABMM SEC. 6	(PLEASE ADVISE)
6	AF 12M INSPECTION	DMC-429-A-05-40-00-00A-028A-A, ISSUE 003 - 2020/07/15, ECCN EAR99	(PLEASE ADVISE)
7	ENG 12M INSPECTION (ENG 1)	MM PW207D1 05-20-00	(PLEASE ADVISE)
8	ENG 12M INSPECTION (ENG 2)	MM PW207D1 05-20-00	(PLEASE ADVISE)
9	12 M - FIRST AID KIT INSPECTION	CAAM FOD NO: 60CA-16; CAT. IDE. A. 220	(PLEASE ADVISE)
10	12 M - HF ANTENNA INSPECTION	AERONAUTICAL ACCESSORIES (INSTRUCTIONS TO CONTINUED AIRWORTHINESS), REPORT NO. AA-11020, REV A, PARA 4.	(PLEASE ADVISE)
11	12 M DAFR - FDR SYSTEM CHECK	BHT-429-CMM-V, CURTISS WRIGHT CONTROLS; PIM434-1, REV 21 DATE JAN 07/21 PARA 6.2, TABLE 7	(PLEASE ADVISE)
12	ANNUAL CABIN HEATER SYSTEM STC NO. SR00692DE	AIR COMM CORPORATION (INSTRUCTIONS FOR CONTINUED AIRWORTHINESS), HEATER SERVICE MANUAL 429H -201M-1, REV 3 CHAP 2 - INSPECTIONS.	(PLEASE ADVISE)
13	12 M - FIRE PROTECTION INSPECTION	DMC-429-A-26-00-00-00A-310A-A, ISSUE 003 - 2020/07/15, ECCN EAR99	(PLEASE ADVISE)

## Remark/Notes:

- 1. State this Work Order reference on your Work Package. Should there is any additional job/defect (unless specified in the work package) the maintenance organization must notify GAM Continuing Airworthiness Manager prior to proceed with rectification.
- 2. Work must be carried out in accordance with approved data and perform by qualified personnel/ approved LAE from the maintenance organization.
- 3. Parts used must be written in Parts Report Form and accompanied by ARC, Serviceable Label or equivalent document.
- 4. Test report, parameter reading or any supporting data must be attached with the worksheet if applicable.
- 5. The maintenance organization shall be responsible for any damages made on the aircraft/ components during maintenance.
- 6. Softcopy of completed Work Package shall be submitted or as mutual agreed and GAM Continuing Airworthiness Manager must be informed once the aircraft is Release to Service.
- 7. Completed Work Package (original) must be submitted to GAM Continuing Airworthiness Manager office within 3 days of date of completion.

I hereby declare that an approved and up to date maintenance data has been referred for the issuance of this work order.

Thank you. Best Regards,

Zaty Nadhira Mohamed Zuhari

Continuing Airworthiness Management Manager

Email: zaty@galaxyaerospace.my



# GALAXY AEROSPACE (M) SDN. BHD. [1040262-D]

Suite 11-14, Helicopter Centre, Malaysia International Aerospace Centre, Sultan Abdul Aziz Shah Airport, 47200 Subang, Selangor, Malaysia. Tel: +603 7734 7226 | Fax: +603 7734 7526 www.galaxyaerospace.my | enquiry@galaxyaerospace.my

# **WORK ORDER**



Address:	SAS Hangar		Work Orde	r Number:			2021-6513	
	Sultan Abdul Aziz Shah Airport						OM DEO 0540	
	Subang Malaysia		Work Pack Reference:		e:	9M-PEC-6513		
Attention			Date Issue	ed:			16/04/2021	
Attentior	Mr. Hairudeen bin Mat Engineering Manager		A/C Registration / SN:		9M-PEC/57060			
	hairudeen@sassb.com.my		A/O negistration / SN:					
			Sheet:	2	of	3		
14	ANNUAL INSPECTION - AUTOMATIC DOOR OPENER KITS STC NO. SR00707DE	AERONAUTICAL ACCESSOF FOR CONTINUED AIRWORT ACCESSORIES PACKAGE 1 REPORT NO. AA-09074, REV	HINESS ), STC NO. SR	00707DE			(PLEASE ADVISE)	
	ANNUAL CABIN AIR CONDITIONING SYSTEM STC NO. SR00693DE	AIR COMM CORPORATION ( CONTINUED AIRWORTHINE CONDITIONER SERVICE MA 13 CHAP 3 - INSPECTIONS A	SS), AIR NUAL 429EC-	200M-1 REV			(PLEASE ADVISE)	
	ANNUAL // 200 FH CABIN AIR CONDITIONING SYSTEM STC NO. SR00693  AIR COMM CORPORAT CONTINUED AIRWORT CONDITIONER SERVIC		(INSTRUCTIO SS), AIR NUAL 429EC-	NS FOR 200M-1 REV			(PLEASE ADVISE)	
	200 FH // 12 M - TCCA AD CF-2018-35 PARA B (ASB 429-18-41) COMPLIANCE	13 CHAP 3 - INSPECTIONS AT TCCA AD CF-2018-35 PARA					(PLEASE ADVISE)	
	AF 200FH // 12M INSPECTION	DMC-429-A-05-40-00-00A-028 2020/07/15, ECCN EAR99	•				(PLEASE ADVISE)	
19	AF 600FH // 12M INSPECTION	DMC-429-A-05-40-00-00A-028 2020/07/15, ECCN EAR99	8A-A, ISSUE 0	03 -			(PLEASE ADVISE)	
20	AF 800FH // 12M INSPECTION	DMC-429-A-05-40-00-00A-02 2020/07/15, ECCN EAR99	8A-A, ISSUE 0	03 -			(PLEASE ADVISE)	
21	AF 2 Y INSPECTION	DMC-429-A-05-40-00-00A-02 2020/07/15, ECCN EAR99	28A-A, ISSUE (	003 -			(PLEASE ADVISE)	
22	2 Y CREW DOOR ASSIST HANDLE INSPECTION	AERONAUTICAL ACCESSO DOOR ASSIST HANDLE STO SR00716DE, REPORT NO. A					(PLEASE ADVISE)	
23	24 M DAFR - FDR REPLAY	BHT-429-CMM-V, CURTISS V PIM434-I, REV 21 DATE JAN					(PLEASE ADVISE)	
24 :	24 M DAFR - CVR REPLAY	BHT-429-CMM-V, CURTISS W PIM434-I, REV 21 DATE JAN					(PLEASE ADVISE)	
5 ,	AF 800FH // 24M INSPECTION	DMC-429-A-05-40-00-00A-028	8A-A, ISSUE 0	03 -			(PLEASE ADVISE)	

# Remark/Notes:

1. State this Work Order reference on your Work Package. Should there is any additional job/defect (unless specified in the work package) the maintenance organization must notify GAM Continuing Airworthiness Manager prior to proceed with rectification.

2020/07/15, ECCN EAR99

- 2. Work must be carried out in accordance with approved data and perform by qualified personnel/ approved LAE from the maintenance organization.
- 3. Parts used must be written in Parts Report Form and accompanied by ARC, Serviceable Label or equivalent document.
- 4. Test report, parameter reading or any supporting data must be attached with the worksheet if applicable.
- 5. The maintenance organization shall be responsible for any damages made on the aircraft/ components during maintenance.
- 6. Softcopy of completed Work Package shall be submitted or as mutual agreed and GAM Continuing Airworthiness Manager must be informed once the aircraft is Release to Service.
- 7. Completed Work Package (original) must be submitted to GAM Continuing Airworthiness Manager office within 3 days of date of completion.

I hereby declare that an approved and up to date maintenance data has been referred for the issuance of this work order.

Thank you. Best Regards,

Zaty Nadhira Mohamed Zuhari

Continuing Airworthiness Management Manager

Email: zaty@galaxyaerospace.my



### GALAXY AEROSPACE (M) SDN. BHD. [1040262-D]

Suite 11-14, Helicopter Centre, Malaysia International Aerospace Centre, Sultan Abdul Aziz Shah Airport, 47200 Subang, Selangor, Malaysia. Tel: +603 7734 7226 | Fax: +603 7734 7526 www.galaxyaerospace.my | enquiry@galaxyaerospace.my

# **WORK ORDER**



(PLEASE ADVISE)

To: SYSTEMATIC AVIATION SERVICES SDN. BHD.

Address: SAS Hangar Work Order Number: 2021-6513

> Sultan Abdul Aziz Shah Airport 9M-PEC-6513 Work Pack Reference: Subang Malaysia

**Date Issued:** 16/04/2021

Attention: Mr. Hairudeen bin Mat

**Engineering Manager** 9M-PEC/57060 A/C Registration / SN: hairudeen@sassb.com.my

3 3 Sheet: of

		Shooti	01
26	EVERY 24 M - ASB 429-16-33 INITIAL ISSUE PART II COMPLIANCE	ASB 429-16-33 INITIAL ISSUE - ACCOMPLISHMENT INSTRUCTIONS: PART II	(PLEASE ADVISE)
27	AF 5Y INSPECTION	DMC-429-A-05-40-00-00A-028A-A, ISSUE 003 - 2020/07/15, ECCN EAR99	(PLEASE ADVISE)
28	AF 10Y INSPECTION	DMC-429-A-05-40-00-00A-028A-A, ISSUE 003 - 2020/07/15, ECCN EAR99	(PLEASE ADVISE)
29	VISUAL CORROSION INSPECTION	CORROSION CONTROL GUIDE, CHAP 30, CSSD-PSE-001, PARA NO. 30-7 DATE 1 FEB 2016, SECTION 30-20-20	(PLEASE ADVISE)
30	100FH // 90 DAYS CORROSION INSPECTION	CORROSION CONTROL GUIDE, CHAP 30, CSSD-PSE-001, PARA NO. 30-8 DATE 1 FEB 2016, SECTION 30-20-20	(PLEASE ADVISE)
31	IL 429-21-14 NEW ISSUE COMPLIANCE	IL 429-21-14 NEW ISSUE DATE 17 MAR 2021	(PLEASE ADVISE)

TB 429-21-65 NEW ISSUE DATE 01 APR 2021

## Remark/Notes:

32

- 1. State this Work Order reference on your Work Package. Should there is any additional job/defect (unless specified in the work package) the maintenance organization must notify GAM Continuing Airworthiness Manager prior to proceed with rectification.
- 2. Work must be carried out in accordance with approved data and perform by qualified personnel/ approved LAE from the maintenance organization.
- 3. Parts used must be written in Parts Report Form and accompanied by ARC, Serviceable Label or equivalent document.
- 4. Test report, parameter reading or any supporting data must be attached with the worksheet if applicable.
- 5. The maintenance organization shall be responsible for any damages made on the aircraft/ components during maintenance.
- 6. Softcopy of completed Work Package shall be submitted or as mutual agreed and GAM Continuing Airworthiness Manager must be informed once the aircraft is Release to Service.
- 7. Completed Work Package (original) must be submitted to GAM Continuing Airworthiness Manager office within 3 days of date of completion.

I hereby declare that an approved and up to date maintenance data has been referred for the issuance of this work order.

Thank you. Best Regards,

Zaty Nadhira Mohamed Zuhari

Continuing Airworthiness Management Manager

TB 429-21-65 NEW ISSUE COMPLIANCE

Email: zaty@galaxyaerospace.my