


History of Coupler CDV 155 PN CDV15506-04 installed in aircraft M70-03 SN 6741

LOG BOOK ENTRY					M70-03
	A/C Type	A/C SN	A/C T.T	Landing	For details of work performed, refer to BRICAS Work Order no.:  2019-298
	Airbus Helicopters AS 365N3	6741	3589.9	5462	
	Engine Type & S/Ns	Engine T.T	NG	HP	
	ARRIEL 2C #1 : 24401	1037.1	1938.6	1153.9	
	ARRIEL 2C #2 : 24359	3462.5	2812.3	897.9	
Airframe Inspection		Engine Inspection		CRS-SM # / EWR #	
N/A		N/A		N/A	
Defect / Rectification / Out of Phase Inspection performed :-					
Coupler Computer P/N: CDV15506-04 replaced. S/N Off: 958 S/N On: 347					
Airframe AD / SB performed during this inspection :-			Engine AD / SB performed during this inspection :-		
N/A			N/A		
THE WORK RECORDED ABOVE HAS BEEN CARRIED OUT IN ACCORDANCE WITH THE REQUIREMENTS OF THE <small>(Check in the appropriate box only)</small>		<input checked="" type="checkbox"/> DIRECTORATE GENERAL TECHNICAL AIRWORTHINESS (DGT4) <input type="checkbox"/> MALAYSIAN CIVIL AVIATION REGULATIONS (MCAR) <input type="checkbox"/>		FOR THE TIME BEING IN FORCE AND IN THAT RESPECT THE AIRCRAFT/EQUIPMENT IS CONSIDERED FIT FOR RELEASE TO SERVICE.	
Place and date		MMEA Subang , 20 FEB 2020		Sgt and stamp 