

**ATTACHMENT FOR TIC-GEN-24-0016**

NOT APPLICABLE TO AS365N3 MMEA'S FLEET. THE AFFECTED PART (OCCUPANT RESTRAIN HARNESSSES) ARE KNOWN TO BE INSTALLED ON HOT AIR BALLOONS.

AERONET HAS BEEN UPDATED. REFER ATTACHMENT BELOW:

AD/SB ID: 4752 Close Update Save & Close

General | Config List | Aircraft List | Task/Check List | Linked To | BOM

Type: ADS  Repetitive

Reference/Number: ATA 25 EQUIPMENT / FURNISHINGS RESTRAINT SYSTEMS / OCCUPANT RESTRAINT HARNESSSES INSPECTION

Title/Subject: EASA AD No.: 2024-0094

Version No:

Reason For Raising:

URL:

Date: 26 04 2024

Tolerance: 0 % (Whole numbers only)

Creep Type: Creep on Completion Unit

Document:

	Title	Filename
	EASA AD No.: 2024-0094	4752-2229.pdf

AD/SB ID: 4752 Close Update Save & Close

General | Config List | Aircraft List | Task/Check List | Linked To | BOM

@	Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status	
	M70-01	Date (Years)	- Years		0	-	-	NOT APPLICABLE	
	M70-02	Not Applicable	-		0	-	-	NOT APPLICABLE	
	M70-03	Not Applicable	-		0	-	-	NOT APPLICABLE	