

ATTACHMENT FOR TIC-AS365N3-24-0021

APPLICABILITY:

APPLICABLE TO ALL HOIST FITTED ON MMEA'S AIRCRAFT DUE TO AIRCRAFT FITTED WITH HOIST PN: 76378-260D.

COMPLIANCE:

RECOMMENDS THAT YOU COMPLY WITH THIS SERVICE BULLETIN DURING ONE OF THE NEXT MAINTENANCE INSPECTIONS ALIGNED WITH YOUR OPERATIONAL AVAILABILITIES / CONSTRAINTS.

EFFECTIVITY:

TASK EVERY 1 Y // 500 HC IN MSM REVISION 012 : 2023.02.20 (25/63/02/680/000/000) UPDATED INTERVAL TO 1000 HC // 12 MONTHS.

STATUS:

SB AS365-25-97-0002 HAS BEEN ADDED ON AERONET SB LIST. REFER ATTACHMENT.

AD/SB ID: 4764 Close Update Save & Close

General Config List Aircraft List Task/Check List Linked To BOM

Type: SBS Repetitive

Reference/Number: EXTERNAL LOAD SYSTEM - ALTERNATIVE METHOD OF COUNTING CYCLES FOR GOODRICH 763XX FAMILY HOISTS

Title/Subject: SB AS365-25-97-0002

Version No:

Reason For Raising:

URL:

Date: 25 04 2024

Tolerance: 0 % (Whole numbers only)

Creep Type: Creep on Completion Unit

Document	Title	Filename
SB AS365-25-97-0002		4764-2240.pdf

AD/SB ID: 4764 Close Update Save & Close

General Config List Aircraft List Task/Check List Linked To BOM

Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status
M70-01	Date (Months)	- Months		3	-	-	RECOMMENDED
M70-01	Airframe Hoist Cycles	- Cycles		0	-	-	RECOMMENDED
M70-02	Airframe Hoist Cycles	- Cycles		0	-	-	RECOMMENDED
M70-02	Date (Months)	- Months		0	-	-	RECOMMENDED
M70-03	Airframe Hoist Cycles	- Cycles		0	-	-	RECOMMENDED
M70-03	Date (Months)	- Months		0	-	-	RECOMMENDED