

ATTACHMENT FOR TIC-AS365N3-24-0041

APPLICABILITY:

FOR INFORMATION ONLY. NOT APPLICABLE DUE TO ALL AS365N3 AIRCRAFT FITTED WITH TGB P/N 365A33600509 (POST MOD 0765B63).

STATUS:

AD HAS BEEN UPDATED ON AERONET AD LISTING FOR RECORD PURPOSES. REFER ATTACHMENT.

AD/SB ID: 4778 Close Update Save & Close

General | Config List | Aircraft List | Task/Check List | Linked To | BOM

Type: ADS Repetitive

Reference/Number: ATA 65 TAIL ROTOR PITCH CONTROL ROD BEARING INSPECTION / REPLACEMENT

Title/Subject: EASA AD No.: 2021-0171R1

Version No:

Reason For Raising:

URL:

Date: 01 / 07 / 2024

Tolerance: 0% (Whole numbers only)

Creep Type: Creep on Completion Unit

Document:

	Title	Filename
	EASA AD No.: 2021-0171R1	4778-2252.pdf

AD/SB ID: 4778 Close Update Save & Close

General | Config List | Aircraft List | Task/Check List | Linked To | BOM

@	Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status	
	M70-01	Not Applicable	-		0	-	-	NOT APPLICABLE	
	M70-02	Not Applicable	-		0	-	-	NOT APPLICABLE	
	M70-03	Not Applicable	-		0	-	-	NOT APPLICABLE	