

# ATTACHMENT FOR TIC-AS365N3-24-0038

## APPLICABILITY:

NOT APPLICABLE BY AIRCRAFT VERSION.

## STATUS:

SB HAS BEEN ADDED ON AERONET SB LISTING FOR RECORD PURPOSES. REFER ATTACHMENT.

AD/SB ID: 4783 Close Update Save & Close

General | Config List | Aircraft List | Task/Check List | Linked To | BOM

Type : SBS  Repetitive

Reference/Number: INTERIOR PLACARDS AND MARKINGS - CORRECTION OF THE DISCREPANCY BETWEEN THE FLIGHT MANUAL AND THE NG LIMITS (%) LABEL (IN THE COCKPIT) IN THE EVENT OF

Title/Subject: SB AS365-11-31-0001

Version No:

Reason For Raising:

URL:

Date: 21 06 2024

Tolerance: 0 % (Whole numbers only)

Creep Type: Creep on Completion Unit

| Document            | Title | Filename      |
|---------------------|-------|---------------|
| SB AS365-11-31-0001 |       | 4783-2255.pdf |

AD/SB ID: 4783 Close Update Save & Close

General | Config List | Aircraft List | Task/Check List | Linked To | BOM

| @ | Aircraft | Based On       | Period | Warning Unit | Warning | Last Done | Next Due | Status         |  |
|---|----------|----------------|--------|--------------|---------|-----------|----------|----------------|--|
|   | M70-01   | Not Applicable | -      |              | 0       | -         | -        | NOT APPLICABLE |  |
|   | M70-02   | Not Applicable | -      |              | 0       | -         | -        | NOT APPLICABLE |  |
|   | M70-03   | Not Applicable | -      |              | 0       | -         | -        | NOT APPLICABLE |  |