

**ATTACHMENT FOR TIC-AS365N3-24-0032**

**ORION REV 009.01 UPD 003**

**APPLICABILITY:** APPLICABLE TO AIRCRAFT TYPE.

**REASON:** PREPRINT VERSION OF MET - REPLACEMENT OF THE SWASHPLATE BEARING - MAIN ROTOR SHAFT HAS BEEN INCLUDED IN THE LATEST ORION UPDATE

**COMPLIANCE:** FOR INFO ONLY

**ACTION REQUIRED:** MAINTENANCE TO USE THE LATEST VERSION FOR REPLACEMENT OF THE SWASHPLATE BEARING - MAIN ROTOR SHAFT.

**STATUS:** WORKPACK AND WORKSHEET TO BE RAISED IN ACCORDANCE WITH ORION REV. 009.01 (DTD 2023-11-06) UPDATE 03 (DTD 2024-05-24). REFER ATTACHMENT.

INSPECTION ID: 1418 Close Update Save & Close

General Config List Aircraft List Task/Check List ATA History Linked To BOM Special Tasks

Inspection Type: Scheduled Inspections

Title/Subject: 50 FH INSPECTION

Reference/Number: ALS 04-20-00 MSM 05-20-00

Version No:

Details/Instructions: TO BE CARRIED OUT IN ACCORDANCE WITH AS365N3 AMP MMEA/CAMO/AMP/AS365N3 ISSUE 1 REV 0B DATE 16 APRIL 2024 AND ORION AS365 N-N1-N2-N3, REV 009.01 DATED 2023-11-06 (UPDATE 03 DATED 2024-05-24).

URL:

Date: -- -- -- --

Tolerance: 0 % (Whole numbers only)

Creep Type: Creep on Completion Unit

Document: + \* Title Filename \*

No Documents currently linked to the inspection