ATTACHMENT FOR TIC-AS365N3-24-0057

TITLE:

SERVICE AND MISCELLANEOUS - NEW COMPENSATOR ROD FOR BATTERY DOOR AND/OR ELECTRICAL COMPARTMENT DOOR

APPLICABILITY: APPLICABLE DUE TO ALL AIRCRAFT IS PRE MOD 0752C81.

REASON:

THIS OPTIONAL SERVICE BULLETIN (PRODUCT IMPROVEMENT) IS TO REPLACE THE COMPENSATOR ROD, WHICH IS NO LONGER SUPPLIED, WITH A NEW COMPENSATOR ROD. THE MOUNTING ORIENTATION OF THE NEW COMPENSATOR ROD IS CHANGED TO ALLOW FOR BETTER LUBRICATION AND PERFORMANCE.

COMPLIANCE:

RECOMMENDED TO COMPLY ONCE THE CURRENT COMPENSATOR ROD IS NO LONGER SUPPLIED.

STATUS:

AERONET SB LISTING HAS BEEN UPDATED FOR RECORDING PURPOSES. REFER ATTACHMENT.

5	galaxyaerospac	e2.aeronet.nz/index.htm	l?function=aircraft_te	mplates&opener_nam	e=aircraft&mode	eedit&templat	e=no&opener	r_form_nam	1e
/SE	B ID: 4790						🗙 Close 🛭 🗲 Upo	date 🔚 Save	e & (
G	eneral Config List	Aircraft List Task/Check	List Linked To BOM						
0	Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status	ľ
_	Aircraft M70-01	Based On	Period -	Warning Unit	Warning 0	Last Done -	Next Due	Status OPTIONAL	1
0 7 7		Based On	Period -	Warning Unit	Warning 0	Last Done - -	-		