

ATTACHMENT FOR TIC-AS365N3-24-0043

AIRBUS HELICOPTERS - AS365N3 AIRWORTHINESS LIMITATIONS SECTION (ALS)

REVISION 009 DTD 2024-04-19

STATUS:

AERONET TASK HAS BEEN AMENDED AS PER ALS REVISION 009 DTD 2024-04-19. REFER PICTURE BELOW.

500 FH INSP

INSPECTION ID: 1424 Close Update Save & Close

General | Config List | Aircraft List | Task/Check List | ATA History | Linked To | BOM | Special Tasks

Create Task Task Work Order Task ID

| Template ID | Title | Reference | Type | Priority | |
|-------------|--|-----------|------|----------|--|
| 5368 | ALS 04-20, 53-10 PRIMARY STRUCTURE 53/10/00/602/000/075 9 FRAME (LATCH SUPPORT) | | Task | 1.00 | |
| 5369 | ALS 04-20, 53-10 PRIMARY STRUCTURE 53/10/00/602/000/085 9 FRAME (STRETCHER SUPPORT) | | Task | 2.00 | |
| 5370 | ALS 04-20, 62-20 MAIN ROTOR HEAD 62/20/00/000/000/215 SPHERICAL THRUST BEARING - ATTACH BEAM PIN | | Task | 3.00 | |
| 5371 | ALS 04-20, 62-30 MAIN ROTOR MAST 62/30/00/000/000/110 SWASHPATE - BEARING | | Task | 4.00 | |

110 FH INSP

INSPECTION ID: 1937 Close Update Save & Close

General | Config List | Aircraft List | Task/Check List | ATA History | Linked To | BOM | Special Tasks

Create Task Task Work Order Task ID

| Template ID | Title | Reference | Type | Priority | |
|-------------|--|-----------|------|----------|--|
| 7025 | ALS 04-20, 53 - 10 PRIMARY STRUCTURE 53/10/00/602/000/090 9 FRAME (LATCH SUPPORT AREA) | | Task | 1.00 | |
| 7026 | ALS 04-20, 53 - 10 PRIMARY STRUCTURE 53/10/00/602/000/098 9 FRAME (LATERAL AREAS) | | Task | 2.00 | |

75 FH INSP

INSPECTION ID: 1935 Close Update Save & Close

General | Config List | Aircraft List | Task/Check List | ATA History | Linked To | BOM | Special Tasks

Create Task Task Work Order Task ID

| Template ID | Title | Reference | Type | Priority | |
|-------------|---|-----------|------|----------|--|
| 7019 | ALS 04-20, 53 - 10 PRIMARY STRUCTURE 53/10/00/602/000/103 9 FRAME (UPPER SECTION AREAS) | | Task | 1.00 | |