

# MALAYSIAN MARITIME ENFORCEMENT AGENCY (MMEA)

<b>DOCUMENT TITLE</b>	AIRCRAFT MAINTENANCE PROGRAMME	<b>AIRCRAFT TYPE</b>	AIRBUS HELICOPTERS AS365N3		
<b>AMP REF.</b>	MMEA/CAMO/AMP/AS365N3	<b>ISSUE</b>	1	<b>REVISION</b>	0B
				<b>DATE</b>	16 APRIL 2024


## 0.1.10 LIST OF EFFECTIVE PAGES

*Table 1 List of Effective Pages*

	SECTION	PAGE NO.	REVISION NO.	DATE
0	INTRODUCTION	1 – 11	0B	16 APRIL 2024
1	GENERAL INSTRUCTIONS	1 - 33	0	21 JUNE 2023
2	MAINTENANCE CHECKS INTERVALS	1 - 7	0	21 JUNE 2023
3	MAINTENANCE, USE AND STORAGE METHODS FOR COMPONENTS, EQUIPMENT AND ASSEMBLIES	1 - 5	0	21 JUNE 2023
4	SPECIAL MAINTENANCE CHECKS	1 - 10	0	21 JUNE 2023
5	FUNCTIONAL CHECK FLIGHT	1 - 4	0	21 JUNE 2023
6	MAINTENANCE TASK TABLE	1 - 52	0	21 JUNE 2023
<b>REVIEWED BY:</b>		<b>APPROVED BY:</b>		
<b>DESIGN ACCEPTANCE REPRESENTATIVE</b>		<b>DIRECTORATE GENERAL TECHNICAL AIRWORTHINESS</b>		
<b>SIGNATURE</b>	Refer LOEP AS365N3 Revision 0 date 21 June 2023 for DAR endorsement	<b>SIGNATURE</b>	Refer LOEP AS365N3 Revision 0 date 21 June 2023 for DAR endorsement	
<b>NAME</b>		<b>NAME</b>		
<b>DATE</b>		<b>DATE</b>		

# MALAYSIAN MARITIME ENFORCEMENT AGENCY (MMEA)

<b>DOCUMENT TITLE</b>	AIRCRAFT MAINTENANCE PROGRAMME	<b>AIRCRAFT TYPE</b>	AIRBUS HELICOPTERS AS365N3				
<b>AMP REF.</b>	MMEA/CAMO/AMP/AS365N3	<b>ISSUE</b>	1	<b>REVISION</b>	0B	<b>DATE</b>	16 APRIL 2024

ISSUE NO.	REV. NO	REV DATE	REASON FOR REVISION	EFFECTIVE DATE	QM APPROVAL	INCORPORATED BY
1	0B	16/04/2024	<p><u>Section 0.1.9</u></p> <p>i. Updated page number for the inspection of task 6.1.44 until task 6.1.53 due to deletion of several tasks in 6.1.44.</p> <p><u>Section 0.1.10</u></p> <p>i. Changed page number for LOEP Section 1</p> <p><u>Section 0.1.11.2</u></p> <p>i. Minor amendments - Rephrase sentences of reason for revision in minor amendments Rev 0A.</p> <p>ii. Minor amendments - Added Rev 0B and updated the changes in Table 2.</p> <p><u>Section 6.1.44</u></p> <p>i. Deleted task No.1 EMM 05-20-10-201-835-A01 and task No.2 EMM 05-20-10-201-835-A01 in 300FH Engine Inspection for ATA 72 due to inapplicability to the aircraft as the aircraft do not operate in erosion environment.</p>	14 days after QM approval date		Aishah