



LOG CARD

NOTICE: WHEN THIS ASSY IS RETURNED FOR ANY REASON TO AN AGUSTA GROUP FACILITY, PLEASE SEND THIS FORM UPDATED.


Section 1



Chapter n° 55
Part n°

DESCRIPTION (1) ROD ASSY <i>22010</i>	P/N (2) 3G5510A02733 ✓	S/N (3) 633 ✓	MANUFACTURER NAME (4) MECAER	ASSEMBLY DATE (5) APRIL 10	RETIREMENT LIFE (6) ON CONDITION
	P/N (7)	S/N (8)	MANUFACTURER NAME (9)	DATE OF CHANGE (10)	RETIREMENT LIFE (11)
	P/N (7)	S/N (8)	MANUFACTURER NAME (9)	DATE OF CHANGE (10)	RETIREMENT LIFE (11)

NOTES (12)

ASSEMBLY HISTORICAL RECORD

INSTALLATION							REMOVAL							
DATE (13)	A/C		ASSY			ORGANIZATION (19)	STAMP AND SIGNATURE (20)	DATE (21)	A/C TOTAL TIME (22)	ASSY		REASON OF REMOVAL (25)	ORGANIZATION (26)	STAMP AND SIGNATURE (27)
	R. MARKS (14)	N/C (15)	TOTAL TIME (16)	TOTAL TIME (17)	TIME SINCE OH (18)					TOTAL TIME (23)	TIME SINCE OH (24)			
JUL. 10		31316	00.00	00.00	NEW	AGUSTA								



LOG CARD

Section 2

Chapter n° 55

Part n°

NOTICE: WHEN THIS ASSY IS RETURNED FOR ANY REASON TO AN AGUSTA GROUP FACILITY, PLEASE SEND THIS FORM UPDATED.

REF. P/N: 3G5510A02733 S/N: 633

LIMITED LIFE COMPONENTS INSTALLED ON ASSY

COMPONENT DATA				INSTALLATION				REMOVAL			
DESCRIPTION (28)	P/N (29)	S/N (30)	RETIREMENT LIFE (31)	ASSY TOTAL TIME (32)	COMP. TOTAL TIME (33)	COMP. TIME SINCE OH (34)	STAMP AND SIGNATURE (35)	ASSY TOTAL TIME (36)	COMP. TOTAL TIME (37)	COMP. TIME SINCE OH (38)	STAMP AND SIGNATURE (39)
ROD END RL010C	3G5510A04053 ✓	825 ✓	10000 FH	00.00	00.00	NEW					
PITCH LINK SLEEVE RL010B	3G5510A04152 ✓	843 ✓	10000 FH	00.00	00.00	NEW					
ROD END RL010A	3G5510A03931 ✓	1819 ✓	4600 FH	00.00	00.00	NEW					

