



# LOG CARD

NOTICE: WHEN THIS ASSY IS RETURNED FOR ANY REASON TO AN AGUSTA GROUP FACILITY, PLEASE SEND THIS FORM UPDATED.

Section 1

Chapter n° ..... 55

Part n° .....

DESCRIPTION (1) <b>ROD ASSY</b>  22010	P/N (2) <b>3G5510A02733</b>	S/N (3) <b>614</b>	MANUFACTURER NAME (4) <b>MECAER</b>	ASSEMBLY DATE (5) <b>MARCH 10</b>	RETIREMENT LIFE (6) <b>ON CONDITION</b>
	P/N (7)	S/N (8)	MANUFACTURER NAME (9)	DATE OF CHANGE (10)	RETIREMENT LIFE (11)
	P/N (7)	S/N (8)	MANUFACTURER NAME (9)	DATE OF CHANGE (10)	RETIREMENT LIFE (11)

NOTES (12)

## ASSEMBLY HISTORICAL RECORD

INSTALLATION							REMOVAL							
DATE (13)	A/C		ASSY			ORGANIZATION (19)	STAMP AND SIGNATURE (20)	DATE (21)	A/C TOTAL TIME (22)	ASSY		REASON OF REMOVAL (25)	ORGANIZATION (26)	STAMP AND SIGNATURE (27)
	R. MARKS (14)	N/C (15)	TOTAL TIME (16)	TOTAL TIME (17)	TIME SINCE OH (18)					TOTAL TIME (23)	TIME SINCE OH (24)			
JUL. 10	M72-02	31315	00.00	00.00	NEW	AGUSTA								



UNA SOCIETA' DI AGUSTAWESTLAND

# LOG CARD

## Section 2

55

Chapter n° .....

Part n° .....

NOTICE: WHEN THIS ASSY IS RETURNED FOR ANY REASON TO AN AGUSTA GROUP FACILITY, PLEASE SEND THIS FORM UPDATED.

REF. P/N: 3G5510A02733 S/N: 614

### LIMITED LIFE COMPONENTS INSTALLED ON ASSY

COMPONENT DATA				INSTALLATION				REMOVAL			
DESCRIPTION (28)	P/N (29)	S/N (30)	RETIREMENT LIFE (31)	ASSY TOTAL TIME (32)	COMP. TOTAL TIME (33)	COMP. TIME SINCE OH (34)	STAMP AND SIGNATURE (35)	ASSY TOTAL TIME (36)	COMP. TOTAL TIME (37)	COMP. TIME SINCE OH (38)	STAMP AND SIGNATURE (39)
ROD END RL0106	3G5510A04053	918	10000 FH	00.00	00.00	NEW					
PITCH LINK SLEEVE RL0108	3G5510A04152	955	10000 FH	00.00	00.00	NEW					
ROD END RL010A	3G5510A03931	1711	4600 FH	00.00	00.00	NEW		4499.6	4499.6	NEW	<i>Al.</i>
ROD END	3G5510A03931	MCR09132	4600FH	4499.6	00.00	NEW	<i>Al.</i>				

m72-02  
-4379



