



SERVICE INFORMATION LETTER

SIL N° S-139-24-005

DATE: April 05, 2024

REV.: /

To: Leonardo Helicopters products
AB/AW139 Owners / Operators / Service Centres

SUBJECT: Inspection of Main Landing Gear (MLG) Shock Absorber – Update on release date of SB139-783 “MLG Shock Absorber Inspection”

Helicopters Affected: All AW139 equipped with Main Shock Absorber Assy
P/N 3G3210V00333 (Liebherr P/N 1654B0000-01)
P/N 3G3210V01031 (Liebherr P/N 1654C0000-01)

References:

- [1] S-139-24-003 – “Inspection of Main Landing Gear (MLG) Shock Absorber - Notice of release of SB”
- [2] S-139-24-004 – “Inspection of Main Landing Gear (MLG) Shock Absorber - Update on SB139-783 “MLG Shock Absorber Inspection””

Dear Customer,

Leonardo Helicopters (LH) hereby provides additional information regarding the Service Bulletin (SB) 139-783 “MLG Shock Absorber Inspection”, in addition to the latest communications at Ref. [1] and Ref. [2].


The SB details are currently under finalization and discussion with the Authority. This is delaying of few days the release of the SB, that was initially expected within the current week and that we are currently targeting to issue on Tuesday 9th April COB. The related EASA AD is also delayed accordingly and will follow soon after the SB.

We take this opportunity to inform that we are processing with priority the Purchase Orders (PO) for the tools received so far, we kindly invite all Customers/Operators impacted by the SB to place orders if not already done.

Inspection of Main Landing Gear (MLG) Shock Absorber – Update on release date of SB139-783 “MLG Shock Absorber Inspection”

Should you need any additional information, please do not hesitate to refer to your usual contact within the LH Engineering Support team.

Yours Sincerely



Francesco Bellardi
Leonardo Helicopters
Customer Support Services & Training
VP Customer Support & Services