

AW139 Air vehicle maintenance planning information Chapter 00, Issue 010: 2022-09-08

No.	Data module code	Issue date	Reason for change	Applicability (YES /N/A)			Remarks
				M72-01	M72-02	M72-03	
1	39-A-00-00-00-00A-005E-P	C 2021-12-13	Changed - Deleted abbreviations UMC and SMC	N/A	N/A	N/A	For Info Only

AW139 Air vehicle maintenance planning information Chapter 04, Issue 014: 2021-05-26

No.	Data module code	Issue date	Reason for change	Applicability (YES /N/A)			Remarks
				M72-01	M72-02	M72-03	
1	39-A-04-00-00-00A-018E-P	C 2021-03-18	Changed - Updated para 3	N/A	N/A	N/A	For Info Only
2	39-A-04-00-00-00A-028E-P	C 2021-05-26	Changed - Added approval of Fourteenth issue	N/A	N/A	N/A	For Info Only
3	39-A-04-10-00-00A-028E-P	C 2021-04-14	Changed - Added RL056 in Table 2	N/A	N/A	N/A	For info only due aircraft M72-01 fitted with Single Hoist PN 3G2591V01532 / 44316-12-104 S/N 40077 For info only due aircraft M72-02 fitted with Single Hoist PN 3G2591V01532 / 44316-12-104 S/N 40100 For info only due aircraft M72-03 fitted with Single Hoist PN 3G2591V01532/ 44316-12-104 SN: 40096
			Changed - Added RL057 in Table 2	N/A	N/A	N/A	For info only due aircraft M72-01 fitted with Single Hoist PN 3G2591V01532 / 44316-12-104 S/N 40077 For info only due aircraft M72-02 fitted with Single Hoist PN 3G2591V01532 / 44316-12-104 S/N 40100 For info only due aircraft M72-03 fitted with Single Hoist PN 3G2591V01532/ 44316-12-104 SN: 40096
			Changed - Added Notes 16 in Table 2	N/A	N/A	N/A	For Info Only
			Changed - Added Notes 17 in Table 2	N/A	N/A	N/A	For Info Only
			Changed - Added RL012 in Table 5	YES			Applicable to aircraft M72-01 due fitted with Qty 05 MRB P/N 3G6210A00131 S/N 2722E, S/N R1991E, S/N 2690E, S/N V224E & S/N R1990E. Life Penalty Factor 0.1 to be included in Amp, Aeronet and Log Card.
					YES		Applicable to aircraft M72-02 due fitted with Qty 05 P/N MRB 3G6210A00131 S/N R1998E, S/N V182E, S/N R1937E, S/N R2001E, S/N V111E. Life Penalty Factor 0.1 to be included in Amp, Aeronet and Log Card.
						YES	Applicable to aircraft M72-03 due fitted with Qty 05 P/N MRB 3G6210A00131 S/N P915E, S/N P833E, S/N Q1517E, S/N Q1291E & V159E. Life Penalty Factor 0.1 to be included in Amp, Aeronet and Log Card.
			Changed - Updated RL012 in Table 2	YES			Applicable to aircraft M72-01 due fitted with Qty 05 MRB P/N 3G6210A00131 S/N 2722E, S/N R1991E, S/N 2690E, S/N V224E & S/N R1990E. Life Penalty Factor 0.1 to be included in Amp, Aeronet and Log Card.
					YES		Applicable to aircraft M72-02 due fitted with Qty 05 P/N MRB 3G6210A00131 S/N R1998E, S/N V182E, S/N R1937E, S/N R2001E, S/N V111E. Life Penalty Factor 0.1 to be included in Amp, Aeronet and Log Card.
						YES	Applicable to aircraft M72-03 due fitted with Qty 05 P/N MRB 3G6210A00131 S/N P915E, S/N P833E, S/N Q1517E, S/N Q1291E & V159E. Life Penalty Factor 0.1 to be included in Amp, Aeronet and Log Card.
			Changed - Updated RL016 in Table 2	YES			Aircraft M72-01 fitted with Main Rotor Scissors Attachment Flange Assembly P/N 3G6220A00632 S/N 466. Retirement life 41700 FH to be included in Amp, Aeronet and Log Card.
					YES		Aircraft M72-02 fitted with Main Rotor Scissors Attachment Flange Assembly P/N 3G6220A00632 S/N 591. Retirement life 41700 FH to be included in Amp, Aeronet and Log Card.
						YES	Aircraft M72-03 fitted with Main Rotor Scissors Attachment Flange Assembly P/N 3G6220A00632 S/N R410. Retirement life 41700 FH to be included in Amp, Aeronet and Log Card.
			Changed - Updated RL019 in Table 2	YES			Aircraft M72-01 fitted with Upper Scissor Lever Assembly P/N 3G6230A00833 S/N V563 and S/N 1384. Retirement life 14280 FH to be included in Amp, Aeronet and Log Card.
					YES		Aircraft M72-02 fitted with Upper Scissor Lever Assembly P/N 3G6230A00833 S/N 1092 and S/N 1616. Retirement life 14280 FH to be included in Amp, Aeronet and Log Card.
		YES		Aircraft M72-03 fitted with Upper Scissor Lever Assembly P/N 3G6230A00832 S/N Q1008 and S/N Q1048. Retirement life 14280 FH to be included in Amp, Aeronet and Log Card.			

			Changed - Updated RL022 in Table 5	YES			Aircraft M72-01 fitted with MGB Shaft, Main Rotor PN 3G6320A01854 S/N R32. Life Penalty Factor 1 to be included in Amp, Aeronet and Log Card.
					YES		Aircraft M72-02 fitted with MGB Shaft, Main Rotor PN 3G6320A01854 S/N R38. Life Penalty Factor 1 to be included in Amp, Aeronet and Log Card.
						YES	Aircraft M72-03 fitted with MGB Shaft, Main Rotor PN 3G6320A01854 S/N R58. Life Penalty Factor 1 to be included in Amp, Aeronet and Log Card.
			Changed - Updated Note 1 in Table 5	N/A	N/A	N/A	For Info Only
			Changed - Deleted Note 2 in Table 5	N/A	N/A	N/A	For Info Only
4	39-A-04-30-00-00A-028E-P	C 2021-03-18	Changed - Updated CM71-03	N/A	N/A	N/A	For info only. Updates only applicable for PT6C-67C1
			Changed - Updated Note 3	N/A	N/A	N/A	For info only. Updates only applicable for PT6C-67C1

AW139 Air vehicle maintenance planning information Chapter 05, Issue 026: 2024-01-08

No.	Data module code	Issue date	Reason for change	Applicability (YES /N/A)			Remarks
				M72-01	M72-02	M72-03	
1	39-A-05-00-00-00A-028E-P	C 2023-09-01	Changed - Added Note	N/A	N/A	N/A	For Info Only
2	39-A-05-21-00-00A-028E-P	C 2023-09-01	Changed - Updated ref DMC to task 63-29	YES			To include in 4 Years inspection and to updates AMP, aeronet and log card as applicable.
					YES		Aircraft M72-02 fitted with MGB Shaft, Main Rotor PN 3G6320A01854 S/N R38. Life Penalty Factor 1 to be included in Amp, Aeronet and Log Card.
						YES	Aircraft M72-03 fitted with MGB Shaft, Main Rotor PN 3G6320A01854 S/N R58. Life Penalty Factor 1 to be included in Amp, Aeronet and Log Card.