

TIC-AS365N3-24-0034

No.	Description	SB NO	Applicability (YES /N/A)						Remarks
			ENGINE M70-01		ENGINE M70-02		ENGINE M70-03		
			SN 24223	SN 24125	SN 24453	SN 24275	SN 24401	SN 24422	
1	SAFRAN ENGINES - ARRIEL 2C SERVICE BULLETIN MODULE M01 - MODIFICATION TO THE ROUGHNESS ON THE STARTER GEAR AND TO THE MODULE M01 AXIAL CLEARANCE MODIFICATION TU 236	TU236 / SB 292722236	YES						APPLICABLE TO #1 MODULE P/N 70BM011710 S/N 1353 DUE TO PRE-MOD TU 236. RECOMMENDED TO COMPLY DURING REPLACEMENT MODULE 1 OR OVERHAUL AT SAFRAN HELICOPTER ENGINES-APPROVED REPAIR CENTER.
				YES					APPLICABLE TO #1 MODULE P/N 70BM011710 S/N 684 DUE TO PRE-MOD TU 236. RECOMMENDED TO COMPLY DURING REPLACEMENT MODULE 1 OR OVERHAUL AT SAFRAN HELICOPTER ENGINES-APPROVED REPAIR CENTER.
					YES				APPLICABLE TO #1 MODULE P/N 70BM011710 S/N 4246 DUE TO PRE-MOD TU 236. RECOMMENDED TO COMPLY DURING REPLACEMENT MODULE 1 OR OVERHAUL AT SAFRAN HELICOPTER ENGINES-APPROVED REPAIR CENTER.
						YES			APPLICABLE TO #1 MODULE P/N 70BM011710 S/N 1598 DUE TO PRE-MOD TU 236. RECOMMENDED TO COMPLY DURING REPLACEMENT MODULE 1 OR OVERHAUL AT SAFRAN HELICOPTER ENGINES-APPROVED REPAIR CENTER.
								YES	APPLICABLE TO #1 MODULE P/N 70BM011710 S/N 4161 DUE TO PRE-MOD TU 236. RECOMMENDED TO COMPLY DURING REPLACEMENT MODULE 1 OR OVERHAUL AT SAFRAN HELICOPTER ENGINES-APPROVED REPAIR CENTER.
									YES