

TIC-AW139-23-0032

NOT APPLICABLE TO ALL MMEA AW139 FLEET

AD/SB ID: 4618 Close Update Save & Close

General | Config List | Aircraft List | Task List | Linked To | BOM

Type : SBS Repetitive

Reference/Number: TURBOSHAFT ENGINE T1 SENSOR WIRING HARNESS- INSPECTION/
REPLACEMENT OF

Title/Subject: P&WC S.B. No.41106

Version No:

Reason For Raising:

URL:

Date: 03 11 2023

AD/SB ID: 4618 Close Update Save & Close

General | Config List | Aircraft List | Task List | Linked To | BOM

@	Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status	
	M72-01		-		0	-	-	NOT APPLICABLE	
	M72-02		-		0	-	-	NOT APPLICABLE	
	M72-03		-		0	-	-	NOT APPLICABLE	