

TIC-AS365N3-24-0013

ASB NO. AS365-53.00.59 REV 1

ASB HAS BEEN ADDED ON AERONET. REFER ATTACHED PICTURE.

COMPLIANCE:

FOR INFORMATION ONLY. NOT APPLICABLE BY AIRCRAFT VERSION.

AD/SB ID: 4678 Close Update Save & Close

General | Config List | Aircraft List | Task/Check List | Linked To | BOM

Type: SBS Repetitive

Reference/Number: CORRECTIVE MEASURE REINFORCED STRUCTURE - 9° FRAME REPLACEMENT OF THE 9° FRAME LATERAL PARTS

Title/Subject: ASB NO. AS365-53.00.59 REV 1

Version No:

Reason For Raising:

URL:

Date: 15 02 2024

Tolerance: 0% (Whole numbers only)

Creep Type: Creep on Completion Unit

Document:

	Title	Filename
ASB NO. AS365-53.00.59 REV 1		4678-2212.pdf

AD/SB ID: 4678 Close Update Save & Close

General | Config List | Aircraft List | Task/Check List | Linked To | BOM

@	Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status	
	M70-01	Not Applicable	-		0	-	-	NOT APPLICABLE	
	M70-02	Not Applicable	-		0	-	-	NOT APPLICABLE	
	M70-03	Not Applicable	-		0	-	-	NOT APPLICABLE	