

TIC-AW139-24-0018

APPLICABLE TO ALL MMEA'S AW139 FLEET

AD/SB ID: 4686 Close Update Save & Close

General | Config List | Aircraft List | Task/Check List | Linked To | BOM

Type: SBS Repetitive

Reference/Number: ATA 56 - WINDOW GASKET UPGRADE

Title/Subject: SB NO. 139-694 NEW ISSUE

Version No:

Reason For Raising:

URL:

Date: 28 02 2024



AD/SB ID: 4686 Close Update Save & Close

General | Config List | Aircraft List | Task/Check List | Linked To | BOM

@	Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status	
	M72-01	Date (Months)	-	Months	3	28/02/2024	20/08/2025	TO BE COMPLIED	
	M72-02	Date (Months)	-	Months	3	28/02/2024	23/09/2025	TO BE COMPLIED	
	M72-03	Date (Months)	-	Months	3	28/02/2024	05/08/2025	TO BE COMPLIED	

M72-01 :

Edit Limitation (A/C: M72-01)



Edit Limitation SB NO. 139-694 NEW ISSUE -ATA 56 - WINDOW GASKET UPGRADE		Cancel	Save
Based On:	Date (Months) ▾		
Warning:	<input type="text" value="3"/>		
Warning Unit:	Months ▾		
Completed:	28 ▾ 02 ▾ 2024 ▾ 		
Due At:	20 ▾ 08 ▾ 2025 ▾ 		
Status:	TO BE COMPLIED ▾		
Limitation Notes:	<div style="border: 1px solid black; padding: 5px;"><p>WINDOWS GASKETS DUE TO DISCARD TIME : 20/08/2025</p><p>NOTE :</p><p>PARA 1.F - FOR HELICOPTERS REGISTERED UNDER OTHER AVIATION AUTHORITIES, BEFORE APPLYING THE SERVICE BULLETIN, APPLICABLE AVIATION AUTHORITY APPROVAL MUST BE CHECKED WITHIN LEONARDO HELICOPTERS CUSTOMER PORTAL.</p><p>PARA. 2C - CUSTOMER IS REQUESTED TO CONTACT THE CUSTOMER SUPPORT ACCOUNT MANAGER FOR FURTHER DETAILS ON THE COMMERCIAL POLICY.</p></div>		

M72-02 :

Edit Limitation (A/C: M72-02)	
Edit Limitation SB NO. 139-694 NEW ISSUE -ATA 56 - WINDOW GASKET UPGRADE <input type="button" value="Cancel"/> <input type="button" value="Save"/>	
Based On:	Date (Months) ▾
Warning:	<input type="text" value="3"/>
Warning Unit:	Months ▾
Completed:	<input type="text" value="28"/> ▾ <input type="text" value="02"/> ▾ <input type="text" value="2024"/> ▾ <input type="button" value="Calendar"/>
Due At:	<input type="text" value="23"/> ▾ <input type="text" value="09"/> ▾ <input type="text" value="2025"/> ▾ <input type="button" value="Edit"/>
Status:	TO BE COMPLIED ▾
Limitation Notes:	<p>COMPLIANCE AT FIRST REPLACEMENT OF THE EMERGENCY EXITS WINDOWS GASKETS DUE TO DISCARD TIME : 23/09/2025</p> <p>NOTE :</p> <p>PARA 1.F - FOR HELICOPTERS REGISTERED UNDER OTHER AVIATION AUTHORITIES, BEFORE APPLYING THE SERVICE BULLETIN, APPLICABLE AVIATION AUTHORITY APPROVAL MUST BE CHECKED WITHIN LEONARDO HELICOPTERS CUSTOMER PORTAL.</p> <p>PARA. 2C - CUSTOMER IS REQUESTED TO CONTACT THE CUSTOMER SUPPORT ACCOUNT MANAGER FOR FURTHER DETAILS ON THE COMMERCIAL POLICY.</p>

M72-03 :

Edit Limitation (A/C: M72-03)

Edit Limitation SB NO. 139-694 NEW ISSUE -ATA 56 - WINDOW GASKET UPGRADE		Cancel	Save
Based On:	Date (Months) ▾		
Warning:	3		
Warning Unit:	Months ▾		
Completed:	28 ▾ 02 ▾ 2024 ▾ 		
Due At:	05 ▾ 08 ▾ 2025 ▾ 		
Status:	TO BE COMPLIED ▾		
Limitation Notes:	<div style="border: 1px solid black; padding: 5px;"><p>COMPLIANCE AT FIRST REPLACEMENT OF THE EMERGENCY EXITS WINDOWS GASKETS DUE TO DISCARD TIME : 05/08/2025</p><p>NOTE :</p><p>PARA 1.F - FOR HELICOPTERS REGISTERED UNDER OTHER AVIATION AUTHORITIES, BEFORE APPLYING THE SERVICE BULLETIN, APPLICABLE AVIATION AUTHORITY APPROVAL MUST BE CHECKED WITHIN LEONARDO HELICOPTERS CUSTOMER PORTAL.</p><p>PARA. 2C - CUSTOMER IS REQUESTED TO CONTACT THE CUSTOMER SUPPORT ACCOUNT MANAGER FOR FURTHER DETAILS ON THE COMMERCIAL POLICY.</p></div>		