

TIC-AW139-24-0048

NOT APPLICABLE TO ALL MMEA'S AW139 FLEET

AD/SB ID: 4771 Close Update Save & Close

General | Config List | Aircraft List | Task/Check List | Linked To | BOM

Type : SBS Repetitive

Reference/Number: ATA 95 - EMERGENCY FLOATATION CONTROL PANEL REPLACEMENT

Title/Subject: ASB NO. 139-777 NEW ISSUE

Version No:

Reason For Raising:

URL:

Date: 23 05 2024

AD/SB ID: 4771 Close Update Save & Close

General | Config List | Aircraft List | Task/Check List | Linked To | BOM

| @ | Aircraft | Based On | Period | Warning Unit | Warning | Last Done | Next Due | Status | |
|---|----------|----------|--------|--------------|---------|-----------|----------|----------------|--|
| | M72-01 | | - | | 0 | - | - | NOT APPLICABLE | |
| | M72-02 | | - | | 0 | - | - | NOT APPLICABLE | |
| | M72-03 | | - | | 0 | - | - | NOT APPLICABLE | |