

TIC-AW139-24-0067

APPLICABLE TO:

M72-02 ENGINE NO. 1 (SN PCE-KB0740) AND ENGINE NO. 2 (SN PCE-KB0732)

M72-03 ENGINE NO. 1 (SN PCE-KB0715) AND ENGINE NO. 2 (SN PCE-KB0707)

ENGINE NO. 1

AD/SB ID: 4795 Close Update Save & Close

General | Config List | Aircraft List | Task/Check List | Linked To | BOM

Type: SBS  Repetitive

Reference/Number: TURBOSHAFT ENGINE - OIL NOZZLE ASSEMBLY, ACCESSORY DRIVE  
- REPLACEMENT OF

Title/Subject: SB NO. 41105 REV 1 (ENG #1)

Version No:

Reason For Raising:

URL:

Date: 05 08 2024

AD/SB ID: 4795 Close Update Save & Close

General | Config List | Aircraft List | Task/Check List | Linked To | BOM

@	Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status	
	M72-01		-		0	-	-	NOT APPLICABLE	
	M72-02		-		0	-	-	Category 5	
	M72-03		-		0	-	-	Category 5	

ENGINE NO. 2

AD/SB ID: 4794 Close Update Save & Close

General | Config List | Aircraft List | Task/Check List | Linked To | BOM

Type: SBS  Repetitive

Reference/Number: TURBOSHAFT ENGINE - OIL NOZZLE ASSEMBLY, ACCESSORY DRIVE  
- REPLACEMENT OF

Title/Subject: SB NO. 41105 REV 1 (ENG #2)

Version No:

Reason For Raising:

URL:

Date: 05 08 2024

AD/SB ID: 4794 Close Update Save & Close

General | Config List | Aircraft List | Task/Check List | Linked To | BOM

@	Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status	
	M72-01		-		0	-	-	NOT APPLICABLE	
	M72-02		-		0	-	-	Category 5	
	M72-03		-		0	-	-	Category 5	