

Document Reference

Document ID	PSE/TQ/2023/133585	Contact	SITI AISHAH MANSOR
Your Code Reference	FT/MMEA	Subject	Chart A amendment - Auxiliary Fuel Tank
Topic	TECHNICAL	Subtopic	SUPPORT
Issue	TECHNICAL ADVICE	Team Legal Entity	Italy

Contact Details

Customer Description	GALAXY HELICOPTERS(M) SDN BHD	Customer ID	0006005700
Email	aishah@galaxyaerospace.my		

Contacts List

First Name	Last Name	Email	User Type
Shazalie	Ramli	shazalie@galaxyaerospace.my	Engineering Officer

Customer Service

Priority	Routine	Creation On (UTC)	27/11/2023
Resolve By (UTC)	12/12/2023	Leonardo Closure Date (UTC)	
Additional Note			

Helicopter Data

ATA Code	28	Description	FUEL
Helicopter S/N	NC0031307	Aircraft Tail Number	M72-01
Helicopter Line	AW139	Helicopter Model	AW139
Repair Instruction Query	False		

Part Number	Component S/N	Component F/H	On (Date)(UTC)
-			

Flight Hours	FH Last Update	Create date
4901,60	27/11/2023	27/11/2023

Ticket Description

Good Day,

After tracing back all the record and chart A we did not found compliance of sb 139-021 on aircraft M72-01 (SN 31307) and M72-02 (SN 31315).

Physical check found that both aircraft equipped with auxiliary tank, refer to picture attached.

Could you clarify the evidence of this compliance and help us to determine the Part Number and Serial Number of the auxiliary fuel tank that currently fitted in the aircraft.

Thank You.

History Log

MANSOR SITI AISHAH : 1/12/2023 08:06:53 (UTC) :

Hi Dhana,

Any update on the request.

Thank You.

MANSOR SITI AISHAH : 30/11/2023 02:36:27 (UTC) :

Good Day Dhana,

Sorry for any misunderstanding.

We reconfirm after the physical check, only aircraft 31307 and 31315 are fitted auxiliary fuel tank. Aircraft 31316 remain fitted main fuel tank only.

Thank You.

MANSOR SITI AISHAH : 28/11/2023 04:31:08 (UTC) :

Dear Dhana,

Indeed only both aircraft H/C 31307 and 31316 was installed Aux fuel tank in production. We confirmed the aircraft H/C 31315 not fitted with Aux fuel tank in service. Could you give us any record from production for evidence of compliance for both aircraft H/C 31307 and 31316.

Thank a lots.

Dhanaraj Eliyathamby : 28/11/2023 03:33:21 (UTC) :

Dear Siti,

Based on preliminary production evidence and contract, only H/C 31307 and 31316 was installed Aux fuel tank in production.

Hence, H/C 31315 should have been fitted with Aux fuel tank in service. Could you check and let us know?

Regards,

Dhana

Closing Note

Ticket Attachments

Attachment's Name	Uploading Date
ferry tank M72-01.jpeg	27/11/2023

3 W&B M72-02 9.pdf	27/11/2023
3 W&B M72-01 9.pdf	27/11/2023
ferry tank M72-02.jpeg	27/11/2023
Ticket_PSE_TQ_2023_133585.pdf	04/12/2023