

| | | | |
|-----------------------|--------|------------------|------------|
| Pesawat: Aircraft: | AS555N | Tarikh: Date: | 25/11/2023 |
|-----------------------|--------|------------------|------------|

BAHAGIAN 2 - STATUS HARIAN PESAWAT
Part 2 - Daily Aircraft Status
Kedaaan Pesawat pada jam 0800H
Aircraft State at 0800H

Bahagian ini diisi oleh MC
 This parts to be filled by MC

| Pesawat Tail Number | Jam Enjin Eng TSN | Jam Pesawat A/C TSN | Kedaaan Semasa Current Status | | | Penangguhan Kerosakan (Jika ada) Deferred Defect (If any) | | | | Rawatan Barisan Kedua Second Line Servicing | | | | Catatan Remarks | | |
|---|----------------------|------------------------|----------------------------------|----------------------|---|--|-----------------------------|----------------------|------------------------------|---|------------------------|------------------------|----------------------|--------------------|--|-------------|
| | | | Kedaaan State | Tarikh Rosak Date | Butir Kerosakan Details of Unserviceable | Jangka Masa Slap Estimate | Perkara Description | Tarikh Rosak Date | Jangka Masa Slap Estimate | Had Operasi (Jika ada) Operational Restrictions | Perkara Description | Tarikh Pada Date of | | | Baki Balance | |
| | | | | | | | | | | | | Jam Time | Kalendar Calendar | | Jam Time | Hari Day |
| M502-1 5709 | ENG #1 SN: 2408 | 4196.1 | US | 19/11/23 | TORQUE GAUGE READING SPLIT INFLIGHT. RECTIFICATION IN PROGRESS. | 27/11/23 | SCHEDULE INSPECTION | | | | | | | SEAT CONFIGURATION | | |
| | | | | | | | 25 FH INSP. | 4202.4 | | 6.3 | | | | | STANDARD SEATS | |
| | | | | | | | 30 FH INSP. | 4200.3 | | 4.2 | | | | | INSTALLED | |
| | | | | | | | 50 FH INSP. | 4214.7 | | 18.6 | | | | | ITEM: FLIR | |
| | | | | | | | 100 FH INSP. (AF) | 4220.5 | | 24.4 | | | | | STATUS: REMOVED | |
| | | | | | | | 100 FH INSP. (ENG NO 1) | 4220.5 | | 24.4 | | | | | P/NO.: 10406-06-410 / 10406-06-210 | |
| | | | | | | | 100 FH INSP. (ENG NO 2) | 4220.5 | | 24.4 | | | | | S/NO.: N/A | |
| | | | | | | | 150 FH INSP. (AF) | 4255.5 | | 59.4 | | | | | ITEM: MOUNTING GUN | |
| | | | | | | | 150 FH INSP. (ENG NO 1) | 4255.5 | | 59.40 | | | | | STATUS: REMOVED | |
| | | | | | | | 150 FH INSP. (ENG NO 2) | 4255.5 | | 59.40 | | | | | P/NO.: 3628931480 | |
| | | | | | | | 300 FH INSP. | 4463.4 | | 267.3 | | | | | S/NO.: N/A | |
| | | | | | | | 500 FH INSP. (AF) | 4620.5 | | 424.4 | | | | | ITEM: FLOATATION GEAR | |
| | | | | | | | 500 FH INSP. (ENG NO 1) | 4620.5 | | 424.4 | | | | | STATUS: REMOVED | |
| | | | | | | | 500 FH INSP. (ENG NO 2) | 4620.5 | | 424.4 | | | | | P/NO.: 218570-0(RH) / 218569-0(LH) | |
| | | | | | | | 600 FH INSP. (AF) | 4720.5 | | 524.4 | | | | | S/NO.: N/A | |
| | | | | | | | 600 FH INSP. (ENG NO 1) | 4720.5 | | 524.4 | | | | | ITEM: SPECTROLAB ASSY | |
| | | | | | | | 600 FH INSP. (ENG NO 2) | 4720.5 | | 524.4 | | | | | STATUS: REMOVED | |
| | | | | | | | 50 FH/6M INSP. | 4220.5 | 27/12/2023 | 24.4 | 32 D | | | | P/NO.: 017500-111(GIMBAL) / 30039(CONTROL BOX) | |
| | | | | | | | 150 FH/3M INSP. | 4227.4 | 26/12/2023 | 31.3 | 31 D | | | | S/NO.: N/A | |
| | | | | | | | 150 FH/6M INSP. | 4270.5 | 27/12/2023 | 74.4 | 32 D | | | | ITEM: RESCUE HOIST ASSY | |
| | | | | | | | 150 FH/12M INSP. | 4270.5 | 27/06/2024 | 74.4 | 215 D | | | | STATUS: REMOVED | |
| | | | | | | | 500 FH/24M INSP. | 4483.2 | 27/06/2025 | 287.1 | 580 D | | | | P/NO.: 704A-41-815-056 | |
| | | | | | | | 600 FH/6M INSP. | 4676.2 | 27/12/2023 | 480.1 | 32 D | | | | S/NO.: N/A. HOIST CYCLE: N/A | |
| | | | | | | | 600 FH/24M INSP. (AF) | 4720.5 | 27/06/2025 | 524.4 | 580 D | | | | ITEM: CARGO SWING | |
| | | | | | | | 600 FH/24M INSP. (ENG NO 1) | 4720.5 | 27/06/2025 | 1813.8 | 580 D | | | | STATUS: REMOVED | |
| | | | | | | | 600 FH/24M INSP. (ENG NO 2) | 4720.5 | 27/06/2025 | 1011.6 | 580 D | | | | P/NO.: 704A-4181-1027 | |
| | | | | | | | 7 D INSP. | | 27/11/2023 | | 2 D | | | | S/NO.: N/A | |
| | | | | | | | 1 M INSP. | | 26/11/2023 | | 1 D | | | | | |
| | | | | | | | 6 M INSP. | | 27/12/2023 | | 32 D | | | | | |
| | | | | | | | 12 M INSP. | | 27/06/2024 | | 215 D | | | | | |
| 24 M INSP. | | 16/06/2025 | | 569 D | | | | | | | | | | | | |
| 30 M INSP. | | 27/12/2025 | | 763 D | | | | | | | | | | | | |
| 48 M INSP. | | 15/11/2024 | | 356 D | | | | | | | | | | | | |
| 60 M INSP. | | 15/11/2025 | | 721 D | | | | | | | | | | | | |
| CORROSION CONTROL PROGRAMME (CCP) | | | | | | | | | | | | | | | | |
| 25 FH - ENG. CLEANING (BOTH ENG) | 4202.4 | | 6.3 | | | | | | | | | | | | | |
| SERVICE BULLETIN / AIRWORTHINESS DIRECTIVE / PERFORMED ONCE | | | | | | | | | | | | | | | | |
| 10 HRS - AEOO 30/22 | 4199.4 | | 3.3 | | | | | | | | | | | | | |
| COMPONENT | | | | | | | | | | SERVICING / ANNUAL | | TBO / SLL / OTP | | | | |
| MGB OIL FILTER, PN: FA01315AV | | | | 15/11/2022 | | | | | | | -375 D | | | | | |
| TAIL SERVO, PN: SCS072 | | | | 1/1/2023 | | | | | | | -328 D | | | | | |

| | | | |
|---------------------------|------|------------------------|-----|
| HOURS FLIGHT OF THE DAY | 0.0 | HOURS CTF OF THE DAY | 0.0 |
| CARRY FORWARD | 10.0 | CARRY FORWARD | 3.1 |
| HOURS FLIGHT OF THE MONTH | 10.0 | HOURS CTF OF THE MONTH | 3.1 |

| |
|---------------------|
| WARNING OVERDUE |
| WARNING NEARING DUE |

AC LANDING CYCLE
 11,757
 FUEL
 TBA

| | | | |
|-----------------------|---------|------------------|------------|
| Pesawat: Aircraft: | ASS555N | Tarikh: Date: | 25/11/2023 |
|-----------------------|---------|------------------|------------|

BAHAGIAN 2 - STATUS HARIAN PESAWAT
 Part 2 - Daily Aircraft Status
 Keadaan Pesawat pada jam 0800H
 Aircraft State at 0800H

Bahagian ini diisi oleh MC
 This parts to be filled by MC

| Pesawat Tail Number | Jam Enjin Eng TSN | Jam Pesawat A/C TSN | Keadaan Semasa Current Status | | | | Penangguhan Kerosakan (Jika ada) Deferred Defect (If any) | | | | Rawalan Barisan Kedua Second Line Servicing | | | | Catatan Remarks | | | | |
|------------------------|----------------------|------------------------|----------------------------------|---|---|------------------------------|--|------------------------------------|------------------------------|--|--|----------------------|-------------------|-----------------|--------------------|-----------|------------------------------------|--|------------------|
| | | | Keadaan State | Tarikh Rosak Date Unserviceable | Butir Kerosakan Details of Unserviceable | Jangka Masa Slap Estimate | Perkara Description | Tarikh Rosak Date Unserviceable | Jangka Masa Slap Estimate | Had Operasi (Jika ada) Operational Limitation | Perkara Description | Tamat Pada Due at | | Baki Balance | | | | | |
| | | | | | | | | | | | | Jam Hrs | Kalender Calendar | Jam Hrs | | Hari Day | | | |
| M502-2 5711 | ENG #1 SN: 2013 | 3826.1 | S | SCHEDULE INSPECTION | | | | | | | | | | | SEAT CONFIGURATION | | | | |
| | | | | 25 FH INSP. | 3828 | | | | | | | | | | 1.9 | | STANDARD SEATS | | |
| | | | | 30 FH INSP. | 3827.9 | | | | | | | | | | 1.8 | | INSTALLED | | |
| | | | | 50 FH INSP. | 3828 | | | | | | | | | | 1.9 | | ITEM: FJR | | |
| | | | | 100 FH INSP. (AF) | 3865.3 | | | | | | | | | | 39.2 | | STATUS: REMOVED | | |
| | | | | 100 FH INSP. (ENG NO 1) | 3865.3 | | | | | | | | | | 39.2 | | P/NO.: 10404-06-410 / 10406-06-210 | | |
| | | | | 100 FH INSP. (ENG NO 2) | 3865.3 | | | | | | | | | | 39.2 | | S/NO.: N/A | | |
| | | | | 150 FH INSP. (AF) | 3942.3 | | | | | | | | | | 116.2 | | ITEM: MOUNTING GUN | | |
| | | | | 150 FH INSP. (ENG NO 1) | 3864.2 | | | | | | | | | | 38.1 | | STATUS: REMOVED | | |
| | | | | 150 FH INSP. (ENG NO 2) | 3864.2 | | | | | | | | | | 38.1 | | P/NO.: 3628931480 | | |
| | | | | 300 FH INSP. | 3947.3 | | | | | | | | | | 121.2 | | S/NO.: N/A | | |
| | | | | 500 FH INSP. (AF) | 4146.9 | | | | | | | | | | 320.8 | | ITEM: FLOATATION GEAR | | |
| | | | | 500 FH INSP. (ENG NO 1) | 4146.9 | | | | | | | | | | 320.8 | | STATUS: REMOVED | | |
| | | | | 500 FH INSP. (ENG NO 2) | 4146.9 | | | | | | | | | | 320.8 | | P/NO.: 218570-0(RH) / 218569-0(LH) | | |
| | | | | 600 FH INSP. (AF) | 4246.9 | | | | | | | | | | 420.8 | | S/NO.: N/A | | |
| | | | | 600 FH INSP. (ENG NO 1) | 4314.2 | | | | | | | | | | 488.1 | | ITEM: SPECTROLAB ASSY | | |
| | | | | 600 FH INSP. (ENG NO 2) | 4314.2 | | | | | | | | | | 488.1 | | STATUS: REMOVED | | |
| | | | | 50 FH/6M INSP. | 3828 | 17/2/2024 | | | | | | | | | 1.9 | 84 D | | P/NO.: 017500-111(GIMBAL) / 30039(CONTROL BOX) | |
| | | | | 150 FH/3M INSP. | 3928 | 12/12/2023 | | | | | | | | | 101.9 | 17 D | | S/NO.: N/A | |
| | | | | 150 FH/6M INSP. | 3838.8 | 14/05/2024 | | | | | | | | | 12.7 | 171 D | | ITEM: RESCUE HOIST ASSY | |
| | | | | 150 FH/12M INSP. | 3942.3 | 14/02/2024 | | | | | | | | | 116.2 | 81 D | | STATUS: REMOVED | |
| | | | | 500 FH/24M INSP. | 4010.3 | 19/07/2024 | | | | | | | | | 184.2 | 237 D | | P/NO.: 704A-41-815-056 | |
| | | | | 600 FH/6M INSP. | 4312.1 | 17/12/2023 | | | | | | | | | 486 | 22 D | | S/NO.: N/A | |
| | | | | 600 FH/24M INSP. (AF) | 4266.9 | 20/03/2025 | | | | | | | | | 440.8 | 481 D | | ITEM: CARGO SWING | |
| | | | | 600 FH/24M INSP. (ENG NO 1) | 4266.9 | 20/03/2025 | | | | | | | | | 440.8 | 481 D | | STATUS: REMOVED | |
| | | | | 600 FH/24M INSP. (ENG NO 2) | 4266.9 | 20/03/2025 | | | | | | | | | 440.8 | 481 D | | P/NO.: 704A-4181-1027 | |
| | | | | 7 D INSP. | | 30/11/2023 | | | | | | | | | | 5 D | | S/NO.: N/A | |
| | | | | 1 M INSP. | | 24/12/2023 | | | | | | | | | | 29 D | | | |
| | | | | 6 M INSP. | | 14/05/2024 | | | | | | | | | | 171 D | | | |
| | | | | 12 M INSP. | | 20/06/2024 | | | | | | | | | | 208 D | | | |
| | | | | 24 M INSP. | | 21/06/2025 | | | | | | | | | | 574 D | | | |
| | | | | 30 M INSP. | | 17/02/2025 | | | | | | | | | | 450 D | | | |
| | | | | 48 M INSP. | | 20/07/2026 | | | | | | | | | | 968 D | | | |
| | | | | 60 M INSP. | | 31/12/2027 | | | | | | | | | | 1497 D | | | |
| | | | | CORROSION CONTROL PROGRAMME (CCP) | | | | | | | | | | | | | | | |
| | | | | AFS - ENG. RINSING & ENG. WASHING (BOTH ENG) | | | | | | | | | | | | | | | |
| | | | | 25 FH - ENG. CLEANING (BOTH ENG) | | | | | | | | | | | 3828 | | 1.9 | | |
| | | | | SERVICE BULLETIN / AIRWORTHINESS DIRECTIVE | | | | | | | | | | | | | | | |
| | | | | 10 HRS - AEOO 30/22 | | | | | | | | | | | 3834.4 | | 8.3 | | |
| | | | | 660 FH INSP EASB 05.00.56 #3 | | | | | | | | | | | 4340.3 | | 514.2 | | |
| | | | | 50 HRS INSP AEO TM 22/05 | | | | | | | | | | | 3828 | | 1.9 | | |
| | | | | COMPONENT | | | | | | | | | | | SERVICING / ANNUAL | | TBO / SLL / OTP | | |
| | | | | RDR ANTENNA SLAVING UNIT, PN: 017-01593-0100, SN: T2004 | | | | | | | | | | | | 12/3/2026 | | 838 D | |
| | | | | | | | | | | | | | | | | | | | AC LANDING CYCLE |
| | | | | | | | | | | | | | | | | | | | 10,870 |
| | | | | | | | | | | | | | | | FUEL | | | | |
| | | | | | | | | | | | | | | | TBA | | | | |

| | | | |
|---------------------------|-----|------------------------|-----|
| HOURS FLIGHT OF THE DAY | 0.0 | HOURS CTF OF THE DAY | 0.0 |
| CARRY FORWARD | 9.6 | CARRY FORWARD | 1.3 |
| HOURS FLIGHT OF THE MONTH | 9.6 | HOURS CTF OF THE MONTH | 1.3 |

| | |
|--|---------------------|
| | WARNING OVERDUE |
| | WARNING NEARING DUE |

| | | | |
|-----------------------|---------|------------------|------------|
| Pesawat: Aircraft: | AS555SN | Tarikh: Date: | 25/11/2023 |
|-----------------------|---------|------------------|------------|

BAHAGIAN 2 - STATUS HARIAN PESAWAT
Part 2 - Daily Aircraft Status
 Keadaan Pesawat pada jam 0800H
 Aircraft State at 0800H

Bahagian ini diisi oleh MC
 This parts to be filled by MC

| Pesawat Tail Number | Jam Enjin Eng ISN | Jam Pesawat A/C ISN | Keadaan Semasa Current Status | | | Penangguhan Kerosakan (Jika ada) Deferred Defect (If any) | | | | Rawatan Barisan Kedua Second Line Servicing | | | | Catatan Remarks | | | | | |
|---|----------------------|------------------------|----------------------------------|----------------------|---|--|------------------------------|----------------------|------------------------------|--|----------------------------|---------------------|----------------|--------------------|--|----------------|--|--|--|
| | | | Keadaan State | Tarikh Rosak Date | Bulir Kerosakan Details of Unserviceable | Jangka Masa Slap Estimate | Perkara Description | Tarikh Rosak Date | Jangka Masa Slap Estimate | Had Operasi (Jika ada) Operational | Perkara Description | Tarikh Pada Date | Isi Content | | Isi Content | Isi Content | | | |
| M502-3 5714 | ENG #1 SN: 2408 | 3429.3 | NON OP | 28/6/21 | AIRCRAFT EXPERIENCE HARD LANDING AT RMN BASE | TBN | | | | | SCHEDULE INSPECTION | | | | SEAT CONFIGURATION STANDARD SEATS INSTALLED ITEM: FLIR STATUS: REMOVED P/NO.: 10406-06-410 / 10406-06-210 S/NO.: N/A ITEM: MOUNTING GUN STATUS: REMOVED P/NO.: 3628931480 S/NO.: N/A ITEM: FLOATION GEAR STATUS: INSTALL P/NO.: 218570-0(RH) / 218569-0(LH) S/NO.: 2742 (LH) & 2785 (RH) ITEM: SPECTROLAB ASSY STATUS: REMOVED P/NO.: 017500-111(GIMBAL) / 30039(CONTROL BOX) S/NO.: N/A ITEM: RESCUE HOIST ASSY STATUS: REMOVED P/NO.: 704A-41-815-056 S/NO.: N/A ITEM: CARGO SWING STATUS: REMOVED P/NO.: 704A-4181-1027 S/NO.: N/A | | | | |
| | | | | | | | 25 FH INSP. | 3449.1 | | 19.8 | | | | | | | | | |
| | | | | | | | 30 FH INSP. | 3436 | | 6.7 | | | | | | | | | |
| | | | | | | | 50 FH INSP. | 3447.5 | | 18.2 | | | | | | | | | |
| | | | | | | | 100 FH INSP. (AF) | 3449.5 | | 20.2 | | | | | | | | | |
| | | | | | | | 100 FH INSP. (ENG NO 1) | 3601.6 | | 23.1 | | | | | | | | | |
| | | | | | | | 100 FH INSP. (ENG NO 2) | 3498.1 | | 23.1 | | | | | | | | | |
| | | | | | | | 150 FH INSP. (AF) | 3434.1 | | 4.8 | | | | | | | | | |
| | | | | | | | 150 FH INSP. (ENG NO 1) | 3648.7 | | 70.2 | | | | | | | | | |
| | | | | | | | 150 FH INSP. (ENG NO 2) | 3545.2 | | 70.2 | | | | | | | | | |
| | | | | | | | 300 FH INSP. | 3647.8 | | 218.5 | | | | | | | | | |
| | | | | | | | 500 FH INSP. (AF) | 3726.6 | | 297.3 | | | | | | | | | |
| | | | | | | | 500 FH INSP. (ENG NO 1) | 3998.7 | | 420.2 | | | | | | | | | |
| | | | | | | | 500 FH INSP. (ENG NO 2) | 3895.2 | | 420.2 | | | | | | | | | |
| | | | | | | | 600 FH INSP. (AF) | 3582 | | 152.7 | | | | | | | | | |
| | | | | | | | 600 FH INSP. (ENG NO 1) | 4098.7 | | 520.2 | | | | | | | | | |
| | | | | | | | 600 FH INSP. (ENG NO 2) | 3995.2 | | 520.2 | | | | | | | | | |
| | | | | | | | 150 FH//3M INSP. | 3499.5 | 29/06/2021 | 70.2 | -879 D | | | | | | | | |
| | | | | | | | 150 FH//6M INSP. | 3499.5 | 29/09/2021 | 70.2 | -787 D | | | | | | | | |
| | | | | | | | 150 FH//12M INSP. | 3499.5 | 29/03/2022 | 70.2 | -606 D | | | | | | | | |
| | | | | | | | 500 FH//24M INSP. | 3847.8 | 06/01/2022 | 418.5 | -688 D | | | | | | | | |
| | | | | | | | 600 FH//6M INSP. | 3949.5 | 29/09/2021 | 520.2 | -787 D | | | | | | | | |
| | | | | | | | 600 FH//24M INSP. (AF) | 3947.8 | 06/01/2022 | 518.5 | -688 D | | | | | | | | |
| | | | | | | | 600 FH//24M INSP. (ENG NO 1) | 4098.7 | 06/04/2023 | 520.2 | -233 D | | | | | | | | |
| | | | | | | | 600 FH//24M INSP. (ENG NO 2) | 3995.2 | 06/04/2023 | 520.2 | -233 D | | | | | | | | |
| | | | | | | | 7 D INSP. | | 28/06/2021 | | -880 D | | | | | | | | |
| | | | | | | | 1 M INSP. | | 28/06/2021 | | -880 D | | | | | | | | |
| | | | | | | | 6 M INSP. | | 02/09/2021 | | -814 D | | | | | | | | |
| | | | | | | | 12 M INSP. | | 02/03/2022 | | -633 D | | | | | | | | |
| | | | | | | | 24 M INSP. | | 29/03/2023 | | -241 D | | | | | | | | |
| 30 M INSP. | | 06/01/2022 | | -688 D | | | | | | | | | | | | | | | |
| 48 M INSP. | | 06/01/2024 | | -42 D | | | | | | | | | | | | | | | |
| 60 M INSP. | | 18/04/2026 | | 875 D | | | | | | | | | | | | | | | |
| CORROSION CONTROL PROGRAMME (CCP) | | | | | | | | | | | | | | | | | | | |
| 25 FH - ENG. CLEANING (BOTH ENG) | 3449.1 | | 19.8 | | | | | | | | | | | | | | | | |
| SERVICE BULLETIN / AIRWORTHINESS DIRECTIVE / PERFORMED ONCE | | | | | | | | | | | | | | | | | | | |
| EASB 05.00.56 REV 1 | 3434.1 | | 4.8 | | | | | | | | | | | | | | | | |
| EASB 67.00.33 REV.0 | 3497.8 | | 68.5 | | | | | | | | | | | | | | | | |
| COMPONENT SERVICING / ANNUAL TBO / SLL / OTP | | | | | | | | | | | | | | | | | | | |
| BATTERY [P/N 151CH-1, 6M, POST: RIGHT&LEFT] | | 2/9/2021 | | -814 D | | | | | | | | | | | | | | | |

| | | | |
|---------------------------|-----|------------------------|-----|
| HOURS FLIGHT OF THE DAY | 0.0 | HOURS CTF OF THE DAY | 0.0 |
| CARRY FORWARD | 0.0 | CARRY FORWARD | 0.0 |
| HOURS FLIGHT OF THE MONTH | 0.0 | HOURS CTF OF THE MONTH | 0.0 |

| |
|---------------------|
| WARNING OVERDUE |
| WARNING HEARING DUE |

AC LANDING CYCLE
 9.251
 FUEL
 TBA

| | | | |
|------------------------------|----------------|-------------------------|------------|
| Pesawat: Aircraft: | ASS55SN | Tarikh: Date: | 25/11/2023 |
|------------------------------|----------------|-------------------------|------------|

BAHAGIAN 2 - STATUS HARIAN PESAWAT
Part 2 - Daily Aircraft Status
Keadaan Pesawat pada jam 0800H
Aircraft State at 0800H

Bahagian ini diisi oleh MC
This parts to be filled by MC

| Pesawat Tail Number | Jam Enjin Eng TSN | Jam Pesawat A/C TSN | Keadaan State | Keadaan Semasa Current Status | | | Penangguhan Kerosakan (jika ada) Deferred Defect (if any) | | | | Rawatan Barisan Kedua Second Line Servicing | | | | Catatan Remarks | | |
|--|----------------------|------------------------|------------------|--|---|------------------------------|--|------------------------------------|------------------------------|---|--|-----------------------|----------------------|-----------------|---------------------------|-------------|--|
| | | | | Tarikh Rosak Date Unserviceable | Butir Kerosakan Details of Unserviceable | Jangka Masa Slap Estimate | Perkara Description | Tarikh Rosak Date Unserviceable | Jangka Masa Slap Estimate | Had Operasi (jika ada) Operational Limitation | Perkara Description | Tempat Pada Due at | | Beri Remarks | | | |
| | | | | | | | | | | | | Jam Hrs | Kalendar Calendar | Jam Hrs | | Hari Day | |
| M502-4 5716 | ENG #1 SN: 2011 | 4067.6 | S | SCHEDULE INSPECTION | | | | | | | | | | | SEAT CONFIGURATION | | |
| | | | | 25 FH INSP. | 4072.0 | | | | | | | | | | | | STANDARD SEATS INSTALLED |
| | | | | 30 FH INSP. | 4072.6 | | | | | | | | | | | | ITEM: FLIR |
| | | | | 50 FH INSP. | 4092.6 | | | | | | | | | | | | STATUS: REMOVED |
| | | | | 100 FH INSP. (AF) | 4147.0 | | | | | | | | | | | | P/NO.: 10406-06-410 / 10406-06-210 |
| | | | | 100 FH INSP. (ENG NO 1) | 4147.0 | | | | | | | | | | | | S/NO.: N/A |
| | | | | 100 FH INSP. (ENG NO 2) | 4147.0 | | | | | | | | | | | | ITEM: MOUNTING GUN |
| | | | | 150 FH INSP. (AF) | 4186.2 | | | | | | | | | | | | STATUS: REMOVED |
| | | | | 150 FH INSP. (ENG NO 1) | 4197 | | | | | | | | | | | | P/NO.: 3628931480 |
| | | | | 150 FH INSP. (ENG NO 2) | 4197 | | | | | | | | | | | | S/NO.: N/A |
| | | | | 300 FH INSP. | 4086.7 | | | | | | | | | | | | ITEM: FLOATATION GEAR |
| | | | | 500 FH INSP. (AF) | 4351.0 | | | | | | | | | | | | STATUS: REMOVED |
| | | | | 500 FH INSP. (ENG NO 1) | 4351.0 | | | | | | | | | | | | P/NO.: 218570-Q(RH) / 218569-Q(LH) |
| | | | | 500 FH INSP. (ENG NO 2) | 4351.0 | | | | | | | | | | | | S/NO.: N/A |
| | | | | 600 FH INSP. (AF) | 4083.8 | | | | | | | | | | | | ITEM: SPECTROLAB ASSY |
| | | | | 600 FH INSP. (ENG NO 1) | 4083.8 | | | | | | | | | | | | STATUS: REMOVED |
| | | | | 600 FH INSP. (ENG NO 2) | 4083.8 | | | | | | | | | | | | P/NO.: 017500-111(GIMBAL) / 30039(CONTROL BOX) |
| | | | | 50 FH//6M INSP. | 4092.6 | 12/2/2024 | | | | | | | | | | | S/NO.: N/A |
| | | | | 150 FH//3M INSP. | 4197 | 14/01/2024 | | | | | | | | | | | ITEM: RESCUE HOIST ASSY |
| | | | | 150 FH//6M INSP. | 4197 | 11/04/2024 | | | | | | | | | | | STATUS: REMOVED |
| | | | | 150 FH//12M INSP. | 4081 | 09/08/2024 | | | | | | | | | | | P/NO.: 704A-41-815-056 |
| | | | | 500 FH//24M INSP. | 4117.3 | 08/07/2024 | | | | | | | | | | | S/NO.: N/A |
| | | | | 600 FH//6M INSP. | 4414.9 | 24/01/2024 | | | | | | | | | | | ITEM: CARGO SWING |
| | | | | 600 FH//24M INSP. (AF) | 4083.8 | 02/03/2024 | | | | | | | | | | | STATUS: REMOVED |
| | | | | 600 FH//24M INSP. (ENG NO 1) | 4083.8 | 02/03/2024 | | | | | | | | | | | P/NO.: 704A-4181-1027 |
| | | | | 600 FH//24M INSP. (ENG NO 2) | 4083.8 | 02/03/2024 | | | | | | | | | | | S/NO.: N/A |
| | | | | 7 D INSP. | | 27/11/2023 | | | | | | | | | | | 2 D |
| | | | | 1 M INSP. | | 18/12/2023 | | | | | | | | | | | 23 D |
| | | | | 6 M INSP. | | 28/01/2024 | | | | | | | | | | | 64 D |
| | | | | 12 M INSP. | | 22/02/2024 | | | | | | | | | | | 89 D |
| | | | | 24 M INSP. | | 17/11/2025 | | | | | | | | | | | 723 D |
| | | | | 30 M INSP. | | 14/12/2024 | | | | | | | | | | | 385 D |
| | | | | 48 M INSP. | | 18/11/2025 | | | | | | | | | | | 724 D |
| | | | | 60 M INSP. | | 28/01/2027 | | | | | | | | | | | 1160 D |
| | | | | CORROSION CONTROL PROGRAMME (CCP) | | | | | | | | | | | | | |
| 25 FH - ENG. CLEANING (BOTH ENG) | 4072.0 | | | | | | | | | | | | | 4.4 | | | |
| SERVICE BULLETIN / AIRWORTHINESS DIRECTIVE / PERFORMED ONCE | | | | | | | | | | | | | | | | | |
| 10 HRS - AEOO 30/22 | 4072.7 | | | | | | | | | | | | | 5.1 | | | |
| 15 HRS INSP EASB 05.00.0001 REV. 0 | 4072.1 | | | | | | | | | | | | | 4.5 | | | |
| COMPONENT SERVICING / ANNUAL TBO / SLL / OTP | | | | | | | | | | | | | | | | | |
| SERVO CONTROL -MAIN SERVO (TBO), PN-SC 8043, SN-694 | | 24/2/2024 | | | | | | | | | | | | 91 D | | | |
| BATTERY RH (201806007) & LH (201902059), DUE 6 MTH | | 15/02/2024 | | | | | | | | | | | | 82 D | | | |

| | | | |
|---------------------------|------|------------------------|-----|
| HOURS FLIGHT OF THE DAY | 0.0 | HOURS CTF OF THE DAY | 0.0 |
| CARRY FORWARD | 10.5 | CARRY FORWARD | 0.0 |
| HOURS FLIGHT OF THE MONTH | 10.5 | HOURS CTF OF THE MONTH | 0.0 |

| |
|---------------------|
| WARNING OVERDUE |
| WARNING HEARING DUE |

AC LANDING CYCLE
11.072
FUEL
TBA

