

A First Aviation Services Inc. Company

1919 E. Northern St. Wichita, KS 67216 Ph: (316) 943-6100 Sales@turbinerotables.com

Work Order Quote

Quote #: WI169066 Work Order #: WO175567

Part#: 101-820020-7015

Alt Part #:

Serial #: CO3351-1

Date Printed: 12/6/2021

Page: 1

101-820020-7015

	OVER & ABOVE			2	
	O&AParts	Description	Fault	Qty	
	101-820074-1 PISTO	DNAXLE ASSY N/G	Cad & Chrome worn, wil need recad & rechrome	1	
	50-820229-1 SUPPO	ORT ASSEMBLY	Cad worn, will need recad	1	
	99-820100-5 CYLINDER		Internal pitting and corrosion beyond allowable lin	Internal pitting and corrosion beyond allowable limits.will need replaced	
Repairs			Qt	Qty	
RO RO6990: 101-820024-15 BRACE			CE	1	
Quote Instructions - Parts rejected from this unit will be mutilated and discarded upon completion of the repair unless we are otherwise instructed here in. Please check here if you want the rejected parts returned to you. If your airline has any unique air carrier manual requirements other than the O.E.M. specifications, pertaining to the maintenance of this component, you are requested to provide a copy to Aerospace Turbine Rotables. Please provide any EASA approved instructions, specifications, and Airworthiness Directives if applicable. This Quotation is valid for 30 days.					
I approve this quote:			Date:		
By accepting this offer you are accepting AeTR's General Terms and Conditions. These may be found at: http://www.turbinerotables.com/pdf/AeTr-General-Terms-and-Conditions-Oct-14-13.pdf					
AeTR WO Quote, (06/19/15)			A First	Aviation Services, Inc. Company	