

**GALAXY AEROSPACE (M) SDN BHD**  
SUITE 11-14, HELICOPTER CENTRE  
MALAYSIA INTERNATIONAL AEROSPACE CENTRE  
SULTAN ABDUL AZIZ SHAH AIRPORT  
47200 SUBANG. SELANGOR.  
MALAYSIA.

## QUOTATION

Your Ref	: YOUR REQUEST.	Ref No	: GALAXY/SZB/10528/2020
Attn	: EN. MUHAMMAD MOHD TAIB.	Date	: 21 SEPTEMBER 2020
Designation	: ENGINEER IN-CHARGE	Contact	: Nizuyir Buyong
E-mail	: muhammad@galaxyaerospace.my	Mobile	: 019-288 3155
Telephone	: +6013-905-4556		

### REF: GUIANAULT GPU UNABLE TO START – FUEL QUANTITY INDICATION DEFECT – SZB.

NO.	DESCRIPTION	QTY	U. PRICE (RM)	TTL PRICE (RM)
1.	GUINAULT GPU MODEL: GB60/20V04D1100; S/N: 17454. REPORTED GPU UNABLE TO START. FUEL QTY INDICATION @15%. TO CARRY OUT DEFECT TROUBLE SHOOTING AND RETIFICATION.			
1.1.	CARRY OUT TROUBLE SHOOTING, CONFIRMED FUEL QUANTITY TRANSMITTER UNSERVICEABLE. TO REPLACE. P/N: CTCA00120.	01 EA.	761.50	761.50
2.	LABOUR TO CARRY OUT DEFECT TROUBLE SHOOTING & RECTIFICATION. (21 & 28 SEPT 2020).	LUM SUM.	800.00	800.00
<b>TOTAL</b>				<b>1,561.50</b>


**Terms & Conditions** :

Price validity : 30 days from date of this offer.  
Delivery : 2 weeks.  
Payment Terms : Nett 30 days.  
Warranty : 3 months.

We trust the above meets your requirements. Please do not hesitate to contact us should you need further information.

Thank you.

For NN IDAMAN SDN BHD

  
Nizuyir Buyong  
Managing Director

