

**GALAXY AEROSPACE (M) SDN BHD**  
SUITE 11-14, HELICOPTER CENTRE  
MALAYSIA INTERNATIONAL AEROSPACE CENTRE  
SULTAN ABDUL AZIZ SHAH AIRPORT  
47200 SUBANG. SELANGOR.

## QUOTATION

Your Ref	:		Ref No	:	GALAXY/SZB/10870/2022
Attn	:	EN. FADZLIE ADAM	Date	:	14 APRIL 2022
Designation	:	HPM PLANNER	Contact	:	Nizuyir Buyong
E-mail	:	fadlieadam@galaxyaerospace.my	Mobile	:	019-288 3155
Telephone	:	+6017-398-9835			

**REF: TO CARRY OUT RECTIFICATION OF TRONAIR ECW P/N: 08-4048-0013.**

NO.	DESCRIPTION	QTY	U. PRICE (RM)	TTL PRICE (RM)
	TRONAIR ENGINE COMPRESSOR WASH; MODEL: 08-4048-0013; S/N: 5020111101. REPORTED AIR/FLUID LEAKING. TO TROUBLE SHOOT & RECTIFY.			
1.	SOLUTION SELECTOR VALVE CLEAN LEAKING. TO REPLACE. P/N: HC-2350-03.	01 EA.	862.75	862.75
2.	FLUID TANK AIR REGULATOR LEAKING. TO REPLACE. P/N: H-3033.	01 EA.	1,672.00	1,672.25
<b>TOTAL</b>				<b>2,535.00</b>

Terms & Conditions : The above work scope is based on the conditions of the equipment as reported. It does not include additional defect rectification of the equipment. Any additional job will be charged in addition to the above work scope.

Price validity : 30 days from date of this offer.


Delivery : 4 weeks ARO.

Payment Terms : CASH ON DELIVERY.

We trust the above meets your requirements. Please do not hesitate to contact us should you need further information.

Thank you.

For NN IDAMAN SDN BHD

  
Nizuyir Buyong  
Managing Director

