

GALAXY AEROSPACE (M) SDN BHD
 SUITE 11-14, HELICOPTER CENTRE
 MALAYSIA INTERNATIONAL AEROSPACE CENTRE
 SULTAN ABDUL AZIZ SHAH AIRPORT
 47200 SUBANG. SELANGOR.

QUOTATION

Your Ref	: YUR REQ.	Ref No	: GALAXY/SZB/10888/2022
Attn	: EN. FADZLIE ADAM	Date	: 11 MAY 2022
Designation	: HPM PLANNER	Contact	: Nizuyir Buyong
E-mail	: fadlieadam@galaxyaerospace.my	Mobile	: 019-288 3155
Telephone	: +6017-398-9835		

REF: TO CARRY OUT JACKS RECTIFICATION & LOAD TEST:

NO.	DESCRIPTION	QTY	U. PRICE (RM)	TTL PRICE (RM)
1.	TYPE: AIRCRAFT JACK. MODEL: GB900-214-060; S/N: 01 09 337. REPORTED JACK LEAKING FROM CYLINDER.	01 EA.		
1.1.	TO REPLACE SEAL KIT.	01 KIT	420.00	420.00
1.2.	TO TOP UP HYDRAULIC FLUID.	2L	80.00	160.00
1.3.	TO CARRY OUT ANNUAL JACK LOAD TEST.	01 EA.	975.00	975.00
2.	TYPE: AIRCRAFT JACK. MODEL: GB900-214-060; S/N: 01 09 316. TO CARRY OUT JACK LOAD TEST.	01 EA.	975.00	975.00
3.	TYPE: AIRCRAFT JACK. MODEL: GB900-214-060; S/N: 01 09 315. TO CARRY OUT JACK LOAD TEST.	01 EA.	975.00	975.00
4.	TYPE: AIRCRAFT JACK. MODEL: GB900-214-060; S/N: 01 09 240. TO CARRY OUT JACK LOAD TEST.	01 EA.	975.00	975.00
TOTAL				4,480.00

Terms & Conditions : The above quotation is based on the conditions of the jack during visual inspection. Any additional defects rectification will be charged in addition to the above work scope.

Price validity : 30 days from date of this offer.


Delivery : 3 weeks.

Payment Terms : CASH ON DELIVERY.

We trust the above meets your requirements. Please do not hesitate to contact us should you need further information.

Thank you.

For NN IDAMAN SDN BHD


 Nizuyir Buyong
 Managing Director

