

NN IDAMAN SDN BHD (860809W)

LOT 12971 A, JALAN BBN 1/7E, PUTRA NILAI, 71800 NILAI. NEGERI SEMBILAN. MALAYSIA.

TEL: +606-856 9155; H/P: +6019-288 3155 / +6012-400 4132 EMAIL: nizuyir.nnidaman@yahoo.com / nora.nnidaman@yahoo.com

GALAXY AEROSPACE (M) SDN BHD

SUITE 11-14, HELICOPTER CENTRE
MALAYSIA INTERNATIONAL AEROSPACE CENTRE
SULTAN ABDUL AZIZ SHAH AIRPORT
47200 SUBANG. SELANGOR.

QUOTATION

Your Ref : YOUR REQUEST 10/5/22. Ref No : GALAXY/SZB/10895/2022

Attn: EN. FADZLIE ADAMDate: 13 MAY 2022Designation: HPM PLANNERContact: Nizuyir BuyongE-mail: fadlieadam@galaxyaerospace.myMobile: 019-288 3155

Telephone : +6017-398-9835

REF: GPU UNABLE TO START - GUINAULT MODEL: GB/60/20V04D1100; S/N: 17454.

NO.	DESCRIPTION	QTY	U. PRICE (RM)	TTL PRICE (RM)
	TYPE: GUINAULT GPU MODEL: GB60/20V04D1100; S/N: 17454.			
	REPORTED UNABLE TO START.			
	OBSERVED OPERATION STEP INDICATOR REMAINED AT LOG			
	ON. TO CARRY OUT TROUBLE SHOOTING OF THE DEFECT.			
1.	BOTH MAIN BATTERY VOLTAGE LOW @ 5.8VDC. TO SUPPLY	02 EA.	2,185.00	4,370.00
	BATTERY. P/N: BTBT00271.			
2	LABOUR TO CARRY OUT TROUBLE SHOOTING, REPLACEMENT	LUM	600.00	600.00
	OF BATTERIES AND FUNCTIONAL TEST OF THE GPU.	SUM		
	TOTAL			4,970.00

Terms & : The above quotation is based on the conditions of the GPU during inspection & trouble

Conditions shooting. Any additional defects found will be charged in addition to the above work

scope.

Price validity : 30 days from date of this offer.

Delivery : 1 week.

Payment Terms : 100% IN ADVANCE.

We trust the above meets your requirements. Please do not hesitate to contact us should you need further information.

Thank you.

For NN IDAMAN SDN BHD

Nizuyir Buyong Managing Director