

NN IDAMAN SDN BHD (860809W)

LOT 12971 A, JALAN BBN 1/7E, PUTRA NILAI, 71800 NILAI. NEGERI SEMBILAN. MALAYSIA.

TEL: +606-856 9155; H/P: +6019-288 3155 / +6012-400 4132 EMAIL: nizuyir.nnidaman@yahoo.com / nora.nnidaman@yahoo.com

GALAXY AEROSPACE (M) SDN BHD

SUITE 11-14, HELICOPTER CENTRE
MALAYSIA INTERNATIONAL AEROSPACE CENTRE
SULTAN ABDUL AZIZ SHAH AIRPORT
47200 SUBANG. SELANGOR.

QUOTATION

Your Ref : YOUR REQUEST 19/1/2024 Ref No : GALAXY/SZB/11252/2024

Attn : EN. FADZLIE ADAM Date : 19 JANUARY 2024
Designation : HPM PLANNER Contact : Nizuyir Buyong
E-mail : fadlieadam@galaxyaerospace.my Mobile : 019-288 3155

Telephone : +6017-398-9835

REF: 400HZ UNABLE TO START - GUINAULT MODEL: GB60/20V04D1100; S/N: 17026.

NO.	DESCRIPTION	QTY	U. PRICE (RM)	TTL PRICE (RM)
	TYPE: GUINAULT GPU MODEL: GB60/20V04D1100; S/N: 17026.			
	OPTG HOUR: HOURS.			
	REPORTED HIGH TEMPERATURE & ALTERNATOR FAULT MESSAGE.			
	GPU UNABLE TO START.			
	TO CARRY OUT TROUBLE SHOOTING OF THE REPORTED DEFECT.			
1.	LABOUR TO CARRY OUT TROUBLE SHOOTING OF THE DEFECT ON	01 EA	1 200 00	1 200 00
	THE GPU.	01 EA.	1,200.00	1,200.00
	TOTAL			1,200.00

Terms & : The above quotation is only for trouble shooting of the defect. Any defects found will

Conditions be charged in addition to the above work scope.

Price validity : 30 days from date of this offer.

Delivery : 1 week.

Payment Terms : 100% IN ADVANCE.

We trust the above meets your requirements. Please do not hesitate to contact us should you need further information.

Thank you.

For NN IDAMAN SDN BHD

Nizuyir Buyong Managing Director