

406 Dividend Drive

Peachtree City, GA 30269

Tel: (770) 632-1851 Fax: (770) 632-1852

www.primeindustriesusa.com

**UNITED STATES** 

FEIN 65-1020927



Management System AS9120B

#### **QUOTATION**

#### For: Account No. [GALAXY]

GALAXY AEROSPACE (M) SDN BHD Attn: Nor Izzati Azmi, Executive SUITE 11-14, HELICOPTER CENTER

MALAYSIA INTERNATIONAL AEROSPACE CENTRE

SULTAN ABDUL AZIZ SHAH AIRPORT

SELANGOR, SUBANG 47200

MALAYSIA

Tel.: 011 603 7887 0426 Fax: 011 603 7887 0526

In response to your request, we are pleased to quote you the following:

### No. 117899

Pg:1/5

Our Ref : 117899-ML
Terms : NET-30 DAYS
Our Contact : Marc Lacourly

eMail : mlacourly@primeindustriesusa.com

Valid Until : Aug-13-2022 F.O.B. : EX-WORKS Quote Date : Jul-14-2022

Line	P/N & Description	Cnd	Qty Bid	Delivery	Unit Price	Amount
01	12085-01 FIRE EXTINGUISHER I/W: S262A10T1001 ECCN: 84.24.10.00.90 Serial No.: ACW06220	FN	1 EA	Stock	\$ 2,000.00000 EA	\$ 2,000.00
02	Trace To: OEM Tag Info: 10/26/2021 EASA F1 MFG: (F9211) COLLINS AEROSPACE / L'HOTELI Note: *** HAZ-MAT FEE \$350.00 *** 158991-3 FLOAT CYLINDER ASSEMBLY I/W: 704A42-693-015 ECCN: EAR99 UN CODE 1046 Trace To: OEM	LIER FN	1 EA	180 Days	\$ 12,000.00000 EA	\$ 12,000.00
03	Tag Info: OEM EASA FORM 1 MFG: (70167) AIR CRUISERS COMPANY INC. 158991-3 FLOAT CYLINDER ASSEMBLY I/W: 704A42-693-015 ECCN: EAR99 UN CODE 1046	ОН	1 EA	30 Days	\$ 7,500.00000 EA	\$ 7,500.00
04	MFG: (70167) AIR CRUISERS COMPANY INC. Note: ** Flat Exchange Charge, Return Core As Is 158991-3 FLOAT CYLINDER ASSEMBLY	** AR	1 EA	15 Days	\$ 10,000.00000 EA	* No Charge *

- 1. Prime Industries' Standard Terms & Conditions of Sale apply. Delivery is quoted in Business Days only,
- 2. Prices & deliveries herein quoted are applicable to the quantities as covered by this quotation.
- 3. All materials quoted from stock or with deliveries of 15 days or less are subject to prior sale.
- 4. In the event of an order, the above commodities are not to be shipped to any country that has an embargo placed against it by the U.S. Government. Should these commodities require an export license, it shall be your responsibility to comply with the United States Department of State/Commerce Export Regulations.
- 5. If an Export License is required, a \$250.00 processing fee will apply for each occurrence
- 6. Hazardous Material (HAZMAT) Shipments shall be subject to a minimum Haz-Mat handling fee of \$250.00 per package.

FN=Factory New/NS=New Surplus/OH=Overhaul Certified/SV=Serviceable/RP=Repaired/AR=As Removed



406 Dividend Drive

Peachtree City, GA 30269 Tel: (770) 632-1851 UNITED STATES
Fax: (770) 632-1852

www.primeindustriesusa.com

FEIN 65-1020927



Quotation No. 117899

Page : 2/5

# QUOTATION

Our Ref : 117899-ML

Line	P/N & Description	Cnd	Qty Bid	Delivery	Unit Price	Amount
05	I/W: 704A42-693-015 ECCN: EAR99 UN CODE 1046 MFG: (70167) AIR CRUISERS COMPANY INC. Note: ** Core Value ** 863080-00 PYROTECHNIC CARTRIDGE I/W: 704A38-710-040 ECCN: UN0323, CLASSIFICATION 1.4S Serial No.: 8735	FN	1 EA	Stock	\$ 2,250.00000 EA	\$ 2,250.00
06	Trace To: OEM Tag Info: 09/09/2021 EASA F1 MFG: (F9211) COLLINS AEROSPACE / L'HOTELL Note: *** HAZ-MAT FEE \$350.00 *** 863085-00 PYROTECHNIC CARTRIDGE I/W: 704A38-710-041 ECCN: UN0323, CLASSIFICATION 1.4S Serial No.: 8589	JIER FN	1 EA	Stock	\$ 2,250.00000 EA	\$ 2,250.00
07	Trace To: OEM Tag Info: 10/13/2021 EASA F1 MFG: (F9211) COLLINS AEROSPACE / L'HOTELL Note: *** HAZ-MAT FEE \$350.00 *** 524-031 STARTER GENERATOR I/W: 704A46-101-011 Serial No.: 3505 Trace To: LOG CARDS	JIER OH	1 EA	14 Days	\$ 3,900.00000 EA	\$ 3,900.00
08	Tag Info: FRESH 2022 FAA/EASA MFG: (AUXILEC) THALES UK LTD AVIONICS Note: ** Standard Exchange Charge with exclusion 524-031 STARTER GENERATOR I/W: 704A46-101-011 MFG: (AUXILEC) THALES UK LTD AVIONICS	s subj AR	ect to bill backs ** 1 EA	15 Days	\$ 10,000.00000 EA	* No Charge *

- 1. Prime Industries' Standard Terms & Conditions of Sale apply. Delivery is quoted in Business Days only,
- 2. Prices & deliveries herein quoted are applicable to the quantities as covered by this quotation.
- 3. All materials quoted from stock or with deliveries of 15 days or less are subject to prior sale.
- 4. In the event of an order, the above commodities are not to be shipped to any country that has an embargo placed against it by the U.S. Government. Should these commodities require an export license, it shall be your responsibilty to comply with the United States Department of State/Commerce Export Regulations.
- 5. If an Export License is required, a \$250.00 processing fee will apply for each occurrence
- 6. Hazardous Material (HAZMAT) Shipments shall be subject to a minimum Haz-Mat handling fee of \$250.00 per package.

FN=Factory New/NS=New Surplus/OH=Overhaul Certified/SV=Serviceable/RP=Repaired/AR=As Removed



406 Dividend Drive

Peachtree City, GA 30269 Tel: (770) 632-1851 UNITED STATES
Fax: (770) 632-1852

www.primeindustriesusa.com

FEIN 65-1020927



Quotation No. 117899 F

# **QUOTATION**

Our Ref : 117899-ML

Line	P/N & Description	Cnd	Qty Bid	Delivery	Unit Price	Amount
	Note: ** Core Value **					
09	SC8033-2	OH	1 EA	75 Days	\$ 19,500.00000 EA	\$ 19,500.00
	M/R SERVO CONTROL					
	I/W: 704A44-831-146					
	Trace To: LOG CARDS					
	Tag Info: FRESH 2022 EASA F1					
	MFG: (F1688) COLLINS AEROSPACE					
	Note: ** Flat Exchange Charge with the return of a					
10	SC8033-2	AR	1 EA	15 Days	\$ 30,000.00000 EA	* No Charge *
	M/R SERVO CONTROL					
	I/W: 704A44-831-146					
	MFG: (F1688) COLLINS AEROSPACE					
	Note: ** Core Value **					
11	863080-00	FN	1 EA	Stock	\$ 2,250.00000 EA	\$ 2,250.00
	PYROTECHNIC CARTRIDGE					
	I/W: 704A38-710-040					
	ECCN: UN0323, CLASSIFICATION 1.4S					
	Serial No.: 8717					
	Trace To: OEM					
	Tag Info: 09/09/2021 EASA F1					
	MFG: (F9211) COLLINS AEROSPACE / L'HOTELI	IER				
12	10230-01	ОН	1 EA	Stock	\$5,500.00000 EA	\$ 5,500.00
	FIRE EXTINGUISHER					
	I/W: 704A42-820-049					
	Serial No.: UR66173					
	Trace To: LOG CARDS					
	Tag Info: 03/24/2021 FAA/EASA					
	MFG: (F9211) COLLINS AEROSPACE / L'HOTELI	IFR				
	Note: ** Standard Exchange Charge with the return		complete and normal core	**		
13	10230-01	AR	1 EA	15 Days	\$ 15,000.00000 EA	* No Charge *
10	FIRE EXTINGUISHER	, \		Days	Ψ 10,000.00000 Ε/τ	i vo charge
	I/W: 704A42-820-049					
	MFG: (F9211) COLLINS AEROSPACE / L'HOTELI	IFR				
	Note: ** Core Value **	`				
	Note. One value					

<sup>1.</sup> Prime Industries' Standard Terms & Conditions of Sale apply. Delivery is quoted in Business Days only,

FN=Factory New/NS=New Surplus/OH=Overhaul Certified/SV=Serviceable/RP=Repaired/AR=As Removed

<sup>2.</sup> Prices & deliveries herein quoted are applicable to the quantities as covered by this quotation.

<sup>3.</sup> All materials quoted from stock or with deliveries of 15 days or less are subject to prior sale.

<sup>4.</sup> In the event of an order, the above commodities are not to be shipped to any country that has an embargo placed against it by the U.S. Government. Should these commodities require an export license, it shall be your responsibilty to comply with the United States Department of State/Commerce Export Regulations.

<sup>5.</sup> If an Export License is required, a \$250.00 processing fee will apply for each occurrence

<sup>6.</sup> Hazardous Material (HAZMAT) Shipments shall be subject to a minimum Haz-Mat handling fee of \$250.00 per package.



406 Dividend Drive

Peachtree City, GA 30269 Tel: (770) 632-1851 UNITED STATES
Fax: (770) 632-1852

www.primeindustriesusa.com

FEIN 65-1020927



Quotation No. 117899

Page:4/5

_, _		 	_	_	_	-			
Our Do	F			1	17	00	ο <b>ι</b>	ΛI	

QUOTATION

Line	P/N & Description	Cnd	Qty Bid	Delivery	Unit Price	Amount			
14	524-031 STARTER GENERATOR I/W: 704A46-101-011	ОН	1 EA	14 Days	\$ 3,900.00000 EA	\$ 3,900.00			
	Trace To: LOG CARDS								
	Tag Info: FRESH 2022 FAA/EASA								
	MFG: (AUXILEC) THALES UK LTD AVIONIC:	1 1							
	Note: ** Standard Exchange Charge with excl								
15	524-031	AR	1 EA	15 Days	\$ 10,000.00000 EA	* No Charge *			
	STARTER GENERATOR								
	I/W: 704A46-101-011								
	MFG: (AUXILEC) THALES UK LTD AVIONICS Note: ** Core Value **	5							
16	SC8033-2	ОН	1 EA	75 Days	\$ 19,500.00000 EA	\$ 19,500.00			
10	M/R SERVO CONTROL	011	1 1.71	75 Days	\$ 17,500.00000 LA	ψ 17,300.00			
	I/W: 704A44-831-146								
	Trace To: LOG CARDS								
	Tag Info: FRESH 2022 EASA F1								
	MFG: (F1688) COLLINS AEROSPACE								
	Note: ** Flat Exchange Charge with the return	of a complete							
17	SC8033-2	AR	1 EA	15 Days	\$ 30,000.00000 EA	* No Charge *			
	M/R SERVO CONTROL								
	I/W: 704A44-831-146								
	MFG: (F1688) COLLINS AEROSPACE								
	Note: ** Core Value **								
	EXPORT COMPLIANCE STATEMENT								
	Products sold by PRIME INDUSTRIES, INC. m	tate,							
	the U.S. Department of Commerce, or the U.S.								
	out of the United States. PRIME INDUSTRIES	licable							
	United States Export Control Regulations including (but not limited to) the International Traffic								
	in Arms Regulations (ITAR), the Export Admini	stration Regula	ations (EAR), Office (	of Foreign					

<sup>1.</sup> Prime Industries' Standard Terms & Conditions of Sale apply. Delivery is quoted in Business Days only,

FN=Factory New/NS=New Surplus/OH=Overhaul Certified/SV=Serviceable/RP=Repaired/AR=As Removed

<sup>2.</sup> Prices & deliveries herein quoted are applicable to the quantities as covered by this quotation.

<sup>3.</sup> All materials quoted from stock or with deliveries of 15 days or less are subject to prior sale.

<sup>4.</sup> In the event of an order, the above commodities are not to be shipped to any country that has an embargo placed against it by the U.S. Government. Should these commodities require an export license, it shall be your responsibilty to comply with the United States Department of State/Commerce Export Regulations.

<sup>5.</sup> If an Export License is required, a \$250.00 processing fee will apply for each occurrence

<sup>6.</sup> Hazardous Material (HAZMAT) Shipments shall be subject to a minimum Haz-Mat handling fee of \$250.00 per package.



: 117899-ML

**QUOTATION** 

Our Ref

## PRIME INDUSTRIES, INC.

406 Dividend Drive Peachtree City, GA 30269

Tel: (770) 632-1851

Fax: (770) 632-1852 www.primeindustriesusa.com

UNITED STATES

FEIN 65-1020927





2uotation	No.	117899	Page : 5/
Zuotation	110.	11/0//	i ugo .o/

<b>Gu.</b> 1101					Quotation No. 11	17077 Tago .070
Line	P/N & Description	Cnd	Qty Bid	Delivery	Unit Price	Amount
	Assets Control (OFAC), and the Foreign Corrupt Pr	actices	Act (FCPA). The export	and re-export		
	of products requiring a license from the U.S. Depar	tment	of State, the U.S. Departr	nent of Commer	ce,	
	and/or the U.S. Department of Treasury is strictly p	rohibite	d. Additionally, PRIME II	NDUSTRIES, IN	C.	
	correspondence may contain technical data that is	control	ed and compliant with th	e International		
	Traffic in Arms Regulations (ITAR) and/or the Expo	rt Adm	nistration Regulations (E	AR). Without the	2	
	proper approval from the U.S. Department of State	or the	U.S. Department of Com	merce, the trans	fer	
	or release of this technical data to a foreign person	or enti	ity whether manufactured	within the		
	United States or abroad, is strictly prohibited.					
	THANK YOU FOR YOUR ORDER					
						·
					Sub Total:	\$ 80,550.00
1 Drimo I	ndustries' Standard Terms & Conditions of Sale apply. Delivery is	auotod	in Rusinoss Dave only		Sub Total.	\$ 60,550.00
	& deliveries herein quoted are applicable to the quantities as cove					
	erials quoted from stock or with deliveries of 15 days or less are s					
	event of an order, the above commodities are not to be shipped to against it by the U.S. Government. Should these commodities rec					
	sponsibility to comply with the United States Department of State/					
	ort License is required, a \$250.00 processing fee will apply for elous Material (HAZMAT) Shipments shall be subject to a minimum			ackage.		
	ry New/NS=New Surplus/OH=Overhaul Certified/SV=Serviceable			•		
Manage Contract of the Contrac	Manager and the second				Total: [USD]	\$ 80,550.00
Securitoria de	The state of the s				10(a). [USD]	\$ 6U,33U.UU

Marc Lacourly, President