

**AVP-AERO VOO DE PORTUGAL**

Avionics MRO Repair Facility / EASA Repair Station PT.145.039
 Rua Salvador Allende Nº 3 - 2º Piso, 2685-114 Sacavém - Portugal
 Tel: +351 219 411 208 Fax: +351 219 411 210
www.avp.com.pt email: avp@avp.com.pt
 VAT: PT503975249 D-U-N-S: 337835826 CAGE/CORG: P3082

COTAÇÃO Nº

Quotation Nº

20223990R1-2

Page 1-2

V. Ref./ Your Ref:	PL/CTS/AERO/2022/026	Data/Date:	27-Jul-22		
Para/To:	CTS-CHOPPERTECH SERVIÇOS SDN BHD				
Ao Cuidado/ Attn of:	Robin Chin	Assunto/ Subject	Repair Quote		
#	Peça número Part Number	Descrição Description	NNA/NSN	NS/SN	Condição Condition
01	0202HRA/1	RADAR ALTIMETER TRANSCEIVER (RADALT)	5841-99-717-8209	135/02	Repair


A. Avaria Reportada pelo Cliente/ Description of Discrepancy Reported by Client	A.1- PAGE 2
B. Descrição da Avaria feita pela AVP/ Description of Discrepancy found by AVP	B.1- PAGE 2
C. Teste de inspeção e de bancada/ Bench test of unit (em caso de rejeição do orçamento este é o valor até à data presente) * Broker and Customs Fee (In case of rejection this is the value at the present date)	3500.00 €
D. Abertura e desmontagem da unidade/ Open and dismount Instrument	0.00 €
E. Reparação e revisão da unidade/ Repair and Revision to Latest Configuration	11500.00 €
F. Montagem, pintura, teste final e calibração/ Assemble, retest, paint and calibrate to T.O Standards	0.00 €
G. Material substituído/ Material Replaced:	
	Description
	G.1 Material in page 2
	Broker and Custom Fees
	Included in point C
	Valor Final
	Final Value
	15000.00 €
	Discount
	0.00 €
	IVA 23%
	Taxes
	0.00 €
	Valor Final Com Iva
	Final Value With Taxes
	15000.00 €
H.Garantia/ Warranty:	O valor monetário usado é o Euros.
1 Year warranty against work done and parts replaced from date of Certificate	Currency quoted in euros.
I. Entrega/ Delivery:	
10 working days after quote approval	
J. Observações/ Observations:	
Payment Proforma Invoice before delivery	
The quote is valid for 180 days .	
The unit is sent with Certificate of Conformance and Component Condition Report .	

Aprova/ Approved _____

Assinatura:
Signature

Não Aprova/ Disapproved _____

Entregar Como Está/ Return As Is _____

	AVP-AERO VOO DE PORTUGAL Avionics MRO Repair Facility / EASA Repair Station PT.145.039 Rua Salvador Allende Nº 3 - 2º Piso, 2685-114 Sacavém - Portugal Tel: +351 219 411 208 Fax: +351 219 411 210 www.avp.com.pt email: avp@avp.com.pt <small>VAT: PT503975249 D-U-N-S: 337835826 CAGE/CORG: P3082</small>		COTAÇÃO Nº Quotation Nº 20223990R1-2 Page 2-2		
	V. Ref./ Your Ref: PL/CTS/AERO/2022/026	Data/Date: 27-Jul-22			
Para/To:	CTS-CHOPPERTECH SERVIÇOS SDN BHD				
Ao Cuidado/ Attn of: Robin Chin	Assunto/ Subject:	Repair Quote			
#	Peça número Part Number	Descrição Description	NNA/NSN	NS/SN	Condição Condition
01	0202HRA/1	RADAR ALTIMETER TRANSCEIVER (RADALT)	5841-99-717-8209	135/02	Repair

A.1 Avaria Reportada pelo Cliente/ Description of Discrepancy Reported by Customer

01-RADALT INDICATE FAIL (J3 CONNECTION LOOSE).

B.1 Avaria detectada pela AVP/ Description of defects found by AVP

1. Radalt with XMTR Module INOP
2. Power supply INOP

C.1 Teste de inspeção e de bancada/ Bench test of unit

01- Unit requires to be open, cleaned, repaired, lubricated, closed and tested to go back to work.

G.1 Material – Details

Part Number	Description	Qty	Unit Price	Total Price
2N3497	Transistor	1	Included in repair price	Included in repair price
M39062/21-0139	Capacitor	1	Included in repair price	Included in repair price
2N3716	Transistor	1	Included in repair price	Included in repair price
BTX18	Thyristor	1	Included in repair price	Included in repair price
2N3114	Transistor	1	Included in repair price	Included in repair price
2N5416	Transistor	1	Included in repair price	Included in repair price
			Total	0.00 €



AVP-AERO VOO DE PORTUGAL

Avionics MRO Repair Facility / EASA Repair Station PT.145.039
Rua Salvador Allende Nº 3 - 2º Piso, 2685-114 Sacavém - Portugal
Tel: +351 219 411 208 Fax: +351 219 411 210
www.avp.com.pt email: avp@avp.com.pt
VAT: PT503975249 D-U-N-S: 337835826 CAGE/CORG: P3082

COTAÇÃO Nº

Quotation Nº

20223990R1-2

Page 3-2

V. Ref./ Your Ref:	PL/CTS/AERO/2022/026	Data/Date:	27-Jul-22		
Para/To:	CTS-CHOPPERTECH SERVIÇOS SDN BHD				
Ao Cuidado/ Attn of:	Robin Chin	Assunto/ Subject	Repair Quote		
#	Peça número Part Number	Descrição Description	NNA/NSN	NS/SN	Condição Condition
01	0202HRA/1	RADAR ALTIMETER TRANSCIEVER (RADALT)	5841-99-717-8209	135/02	Repair