



Telephonics Corporation

Product Support
815 Broad Hollow Road
Farmingdale, NY 11735

Tel: 631-755-7007
Fax: 631-549-6406

www.telephonics.com

Repair Quotation

Page: 1

NO : 628906

Sold To : Account No. 5409		Shipped To:				
Alpine Air Support Doristrasse 8 CH-8311 Brütten Switzerland Tel: +41 52 345 3605		Alpine Air Support Doristrasse 8 CH-8311 Brütten Switzerland Tel: +41 52 345 3605				
W/O No. : 628906	RMA : 39199	Terms : CIA				
Customer P.O. : R210504-20	Ref Number : REPAIR	S/N Compl : T4128				
Issued Date : 06/02/2021	Job Number : 13229.143831					
	Freight Ac :					
Ship Via :	Part Number : 379-2011-001					
F.O.B. :	Description : RT 1601					
Shipped Date :	S/N : T4128					
Line	P/N & Description	Ord	Qty Ordered	Shipped	Unit Price	Amount
1	P/N 379-2011-001 S/N T4128 Receiver Transmitter RT 1601 Customer complaint- R/T amber messenger on MFD during WX Mode. Confirmed customer complaint. Need to replace defective Magnetron p/n 4004505-0002 and on transformer on the Modulator CCA p/n 17374-0001. LEAD TIME: 12 MONTHS ARO QUOTE VALID FOR 60 DAYS	SV	1			