



### Quote #580931

#### BILL TO -

Marc Lacourly Prime Industries, Inc. Prime Industries, Inc. Attn: Marc Locourly, President 406 Dividend Drive Peachtree City, GA 30269 United States Phone 770-632-1851 Fax 770-632-1852

PART NUMBER

3G6230A01133

#### SHIP TO -

Prime Industries, Inc. Prime Industries, Inc. Attn: Marc Lacourly, President 406 Dividend Drive Peachtree City, GA 30269 **United States** 

QTY-DESCRIPTION -

#### QUOTE INFO-

PO Number 052339

PO Line Number 1

Quote Number 580931

Quote Date 9/15/2022

7 Days ARO Turn Time

UPS 3 Day Select Shipping Terms

Net 30 Pavment Terms

DATE \_

Questions?

karleen.dirmantas@ableengineering.com

SERIAL NUMBER

AW563006

PROCESS NO.	PROCESS DESCRIPTION	COST/UNIT QTY	EXTENSION
SCRAP	Unit has been red tagged due to bearing bore exceeding limits, no further repair is available. Please provide disposition below:  Scrap on Site Return As Is	\$299.00 1	\$299.00
		TOTAL	\$299.00

1 Upper Rod End Assembly

- Able is pleased to submit this quotation for your consideration. This quotation is based on Able's initial teardown evaluation and is valid for 30 days only
   Please note, once repair and/or overhaul processing begins, unforeseen damage may be revealed which may after Able's originally quoted price and/or turnaround time. Should this occur, Able will not live quotation will be returned to you FOB Shipping Point via the method you request or ground if you do not specify.
   Components issted on the quotation will be returned to you FOB Shipping Point via the method you request or ground if you do not specify.
   Able will not place insured on your return shipment unless you specify this option in writing and provide the total dollar amount of insurance you require.
   Able will not place insurance on your return shipment unless you specify this option in writing and provide the total dollar amount of insurance, you require.
   Able will not place insurance on your return shipment unless you specify this option in writing and provide the total dollar amount of insurance, you require.
   Applies above insurance on your return shipment unless you specify this option in writing and provide the total dollar amount of insurance, you require.
   Applies above insurance of your return shipment unless you provide shipping costs, export handling fees, imposts, duties, other service fees, or insurance costs as may be required. Any afterment of the provided service in a ship date falling on a weekend or holiday, actual shipment automatically defaults to the next business day
   By signing this quotation, you acknowledge that any invoice, tendered for an Able provided service, remaining unpaid greater than 180-days shall result in ownership transfer of components quoted the provided service and by credit card or international wire transfer will incur additional fees
   This Able quote includes all discounts and volume reba



## **AEROSPACE SERVICES**

A Textron Company

# JOB# 580931 TEARDOWN REPORT

CUSTOMER
PRIME INDUSTRIES, INC.

PART NUMBER
3G6230A01133

SERIAL NUMBER
AW563006

### **Summary Report**



**PART NUMBER** 3G6230A01133

QTY

**DESCRIPTION** 

Upper Rod End Assembly

SERIAL NUMBER AW563006

#### **TEARDOWN INFO**

PO Number ..... 052339


Customer ..... Prime Industries, Inc.

Job Number ..... 580931

Date ..... 9/22/2022

#### **SERVICE TIME**

Life Limited ..... No



### **Customer Requirements**



**PART NUMBER** 3G6230A01133

QTY

**DESCRIPTION**Upper Rod End Assembly

SERIAL NUMBER AW563006

1 PO STATES: "BENCH TEST AND ADVISE"

2 REMOVAL TAG NOT RECEIVED.

### **Preliminary Workscope**



**PART NUMBER** 3G6230A01133

QTY

**DESCRIPTION**Upper Rod End Assembly

SERIAL NUMBER AW563006

1

PROCESS CODE: FL-3

### **Conditions Found**



**PART NUMBER** 3G6230A01133

QTY 1 **DESCRIPTION**Upper Rod End Assembly

SERIAL NUMBER AW563006

◀ FINAL WORKSCOPE: SCRAP/RED-TAG

2 BEARING BORE MEASURES 1.7512" WITH MECHANICAL DAMAGE .010" DEEP, EXCEEDS MANUAL LIMIT OF 1.7503" MAX. NO REPAIR AVAILABLE.