

# MTE TECHNOLOGY SDN. BHD. (Company No. 635557-M)

Mailing Address : P.O. Box88 Pejabat Pos Kelang,41670 Kelang Selangor Darul Ehsan.  
Workshop : 27A, Jalan Rengas, Taman Selatan, 41200 Klang, Selangor Darul Ehsan.  
Telephone : (603)-3372 0988

Handphone : 012-333 3895  
E-mail : [multitrade.mte@gmail.com](mailto:multitrade.mte@gmail.com)

Our Ref. : MTE/GA/Q0919

Date : 09 Aug 2019

ATTN : Azillah Bin Matap  
Senior Maintenance Manager

From : MR. AZAD WAHID

ADDRESS :  
Lot 11 MRO Center Malaysia International  
Aerospace Center  
Lapangan Terbang Sultan Abdul Aziz Shah  
47200 Subang Selangor D.E

## QUOTATION

As requested, we have pleasure to quote you as follow:

ITEM	DESCRIPTION	U/PRICE (RM)	QTY	TOTAL (RM)
1	TO Troubleshoot & Repair Cockpit Fan P/N 3G2150V00553 S/N L00119 S/N L00107 Fault: coil winding insulation arch through replace barring Realignment of the motor, check inverter circuit Cause of failure: condensation  <b>TERMS:COD</b>	5,200	2 set	10,400.00
Total Nett				<b>10,400.00</b>

Validity : 30 days

Warranty : 3 Month

We look forward to serve you better. Thank you.

Yours faithfully,

MR. AZAD WAHID