

## CHOPPERTECH SERVICES SDN BHD (1161592-X)

No.38 & 38-1, JALAN TPS 1/7 TMN PELANGI SEMENYIH 43500 SEMENYIH, SELANGOR MALAYSIA.

TEL: +6016-8402775. FAX NO. +603-21784881

## **QUOTATION**

Quotation ref.no.:	QUO/CTS/AERO/2023/249	Date:	28 Dec 2023
Your order ref.no.:	TBA		

BILL TO:-	CONTACT:-
Galaxy Aerospace (M) Sdn. Bhd. Suite 11-14, Helicopter Centre, Malaysia International Aerospace Centre, Sultan Abdul Aziz Shah Airport, 47200 Subang, Selangor, Malaysia.	Attn.: Ashila

lte m	Part Number	Description	Unit Price(USD)	Qty/Stock Available	Price(USD)	Lead Time
1.	9550178070	Ignition Exciter HE3200 EASA/FAA Std Exchange 2022	4,598.00	1	4,598.00	Stock
2.	9550178070	Ignition Exciter HE3200 EASA/FAA Outright 2022	5,980.00	1	5,980.00	Stock

## Note:

- 1. Payment : Full payment upon PO issued, termination of order is not accepted.
- 2. Quote Validity: 14 Days, price might change depend on currency, stock availability, final freight charges and taxes
- 3. Insurance coverage: Client is required to inform the amount of items that they wish to insure. Without any confirmation from client, our company will automatically insure the items based on the items repair value. If client wish to insure more than the items repair value, client would need to bear the extra insurance cost.
- 4. Sales Condition: In case of rejection of final repair quotation, **TT&E Fee** will be charged per unit and will be returned as **disassembled condition**. TT&E Fee will become void once repair estimate is provided and approved. A final repair quotation will be submitted to customer's consideration for approval after TDI. For exchange unit, client core unit required to be return to us in 2 weeks time, exchange price might change depend on client core unit condition and OEM justification. (OEM Term & Condition apply)
- 5. Warranty: 1 months or 100 hrs (Term & conditions apply).
- 6. Delivery Lead time: Delivery lead time will be influence by parts availability and export license application from original supply country.
- 7. Quoted price are exclude SST and import tax, client need to bear if any SST and import tax that impose by custom.
- 8. Shipment: Ex-work Sweden, buyer core unit need to be return to our vendor location under buyer responsibility.

FOR: CHOPPERTECH SERVICES SDN. BHD.

Mr. Robin Chin Managing Director

E-MAIL: rbnchinyt@gmail.com

Tel: +6016-8402775