

Onezack MRO & Technical Supports (SA0514868-P)
No. 12 Jalan Suria W, U5/W Sek US, Bandar Pinggiran Subang
40150 SHAH ALAM Selangor Darul Ehsan, Malaysia.
Tel: +603 78325963 Fax: +603 78325963

Email: amranmallog@gmail.com

QUOTATION

To: Galaxy Aerospace (M) Sdn. Bhd.

Suite 11-14,

Helicopter Center,

Malaysia Malaysia International Aerospace Centre

Sultan Abdul Aziz Shah Airport

47200 Subang

Selangor Darul Ehsan

Attn: Ms Nor Izzati Azmi

Quote Ref: OMTS/GA/MRO/QTE/26(R1)/23

Date: 31st Oct 2023

Your Ref No.: GAM/DO/23/209 Item 13 & 14

Date: 20th Sep 2023

PO Ref.: PO/GAM/MMA/23/783

Date: 13th Sep 2023

Re: QUOTATION FOR THE SERVICING & REPAIR OF DAVID CLARK HEADSETS P/NO.: 18282G-05 (QTY 02)

We are pleased to submit our servicing quotation and lead delivery time as below for your consideration:

ITEM	PART NO.	DESCRIPTION	QTY (EA)	U/PRICE (RM)	AMOUNT (RM)	REMARKS
	FOR THE SERV	ICING AND REPAIR OF:				
1.	18282G-05 (H10-66)	DAVID CLARK AVIATION HEADSETS Yearly Servicing (1.5 mhrs) S/No.: 1. MMEA/SUS/MMEA/N3/03 2. MMEA/SUS/MMEA/N3/05	2	153.00	306.00	
2.	-	Mandatory Part Replacement:				
	2150004	Ear White Cover	2	28.00	56.00	2 Pairs
3.		Repair works:				
		Trouble shooting & Repair works (2.0 mhrs)	2	102.00	204.00	2 Headsets
4.		Part Replacement:				
	40863G-02	Gel Ear Seal	2	185.00	370.00	2 pairs
	10H/18575	NATO Jack Plug (MMEA/N3/03 & MMEA/N3/05)	2	295.00	590.00	
	0949P	Toggle Switch (MMEA/N3/03)	1	180.00	180.00	
	12840G	Boom Guide Kit (MMEA/N3/05)	1	58.00	58.00	
1		Sub Total			1,764.00	
		Sales Service Tax	0%		0.00	
		TOTAL			1,764.00	

REMARKS:

- 1. Certificate Completion of Work (CCOW) will be issued upon completion of work
- 2. Price and delivery quoted are Ex-work Onezack MRO & Technical Supports
- 3. Validity is 30 Days
- 4. Terms: 30 Days
- 5. Price quoted are in Ringgit Malaysia

We trust our quotation will receive your favourable consideration.

for ONEZACK MRO & TECHNICAL SUPPORTS

SA0514868-F

LT GOL AMRAN MID ISA (RETIRED)



DISCREPANCY REPORT

OMTSP-A-05B

REFERENCE NO.: OMTSP-A-05B Control No.: OMTS/GA/DR/EW/10/2023						
1. Item: DAVID CLARK AVIATION HEADSET	2. Part No: 12507G-45 (H10-13H)					
3 Serial No: As Listed Below	4. Customer: GALAXY AEROSPACE (M)					
5. Customer Indent Order: GAM/DO/209 Item 13 & 14 dtd 20th Sep 2023	Work Required: 6 monthly Servicing Work Order No.: OMTS/EW/068/23 to 069/23					
S/No.: 1. MMEA/SUS/N3/03 2. MMEA/SUS/N3/05						
2150004), and Gel Ear Seal (P/N: 408 Switch (P/N: 0949P) headset S/N: MM (P/N:12840G) headset S/N: MMEA/SU	a. Physical & Visual Inspection found that both headsets Ear White Cover (P/N: 2150004), and Gel Ear Seal (P/N: 40863G-02) are dirty, torn and wear. The Toggle Switch (P/N: 0949P) headset S/N: MMEA/SUSU/N3/03 and Boom Guide Kit (P/N:12840G) headset S/N: MMEA/SUS/N3/05 are broken.					
b. Functional Test found that both the headsets operates intermittently and troubleshooting carried out found that both the NATO Jack Plug (P/N: 10H/18575) were defective.						
c. The broken Toggle Switch, Boom G been replaced and Functional Test for	c. The broken Toggle Switch, Boom Guide Kit and defective NATO Jack Plugs have been replaced and Functional Test found to be serviceable.					
8. Finding:						
a. Ear White Cover (P/N: 2150004) – b. Gel Ear Seal (P/N: 40863G-02) – B c. Toggle Switch (P/N: 0949P) - MME d. Boom Guide Kit (P/N:12840G) - MI e. NATO Jack Plug (P/N: 10H/18575)	- To be replaced (2 units) - To be replaced (1 unit) - To be replaced (1 unit) - To be replaced (1 unit)					
QAP / Workshop Supervisor: 19. 9. Probably Cause: Wear, Tear, Broken &						
10 Recommended Action Required: All Item Para 8a to 8e to be replaced 11. Customer Notified reference: N/A (To be completed by Respective Branch and the running number from QA Dept) Branch Manager: Date: 31 Oct 2023						
12. Action by Customer: Process						
Customer Representative: ROSLAN B. ISMAIL Date: .02 11						
14. Action by QA Department:						
QA Manager:	Date:					