



COMPOSITE TECHNOLOGY INTERNATIONAL PTE LTD
39, LOYANG WAY, SINGAPORE 508735
TEL : 65 65421121 FAX : 65 65425383
E-MAIL : michael_tay@composite-technology.com.sg

TO : Galaxy Aerospace (M) Sdn Bhd.
ATTN : Nur Syamim Syuhada Amdan
SUBJECT : Quotation

REF. : F21-048
PAGES : 1/3
DATE : 19/APR/2022

Order No.	: RMN22-300		
Description	: Main Rotor Blade	Serial No.	: 25136
Part No.	: 355A11-0030-02	Job No.	: 15883
Work Scope			
S01B	Receiving / Inspection	US\$	481
B02	Replace Outboard L/E strip	US\$	4,679
B06	Replace Lower Surface PU Tape	US\$	4,761
S01A	Repaint & Static Balance	US\$	4,423
		Total	US\$ 14,344
Inspection Revealed			
Outboard L/E Erosion Strip cracked. Lower Surface PU reverted Surface paint erosion Lateral vibration reported			
Terms & Condition			
Incoterms	: Ex-works		
TAT	: 4 weeks (ARO)		
Validity	: Till 31st MAY 2022		
Payment Terms	: Full payment prior to delivery		
Currency	: Quoted in United States Dollars		
Evaluation Charges if RAI	: US\$481		
C of C will be issued after repair. End User : Royal Malaysian Navy (TDLM)			
CTIPL Standard Terms and Conditions apply. Copy attached.			

Please advise cost approval. Thank you

Best Regards

Michael Tay

Dy. General Manager, Operations.

Cost Accepted	<input type="checkbox"/>
RAI (Return As Is)	<input type="checkbox"/>
_____ Name/Signature	_____ Date



COMPOSITE TECHNOLOGY INTERNATIONAL PTE LTD

39, LOYANG WAY, SINGAPORE 508735

TEL : 65 65421121

FAX : 65 65425383

E-MAIL : michael_tay@composite-technology.com.sg

TO : Galaxy Aerospace (M) Sdn Bhd.

ATTN : Nur Syamim Syuhada Amdan

SUBJECT : Quotation

REF. : F21-048

PAGES : 2/3

DATE : 19/APR/2022

Order No.	: RMN22-300		
Description	: Main Rotor Blade	Serial No.	: 29501
Part No.	: 355A11-0030-04	Job No.	: 15884
Work Scope			
S01B	Receiving / Inspection	US\$	481
B06	Replace Lower Surface PU Tape	US\$	4,761
S01A	Repaint & Static Balance	US\$	4,423
		Total	US\$ 9,665
Inspection Revealed			
Lower Surface PU reverted Surface paint erosion Lateral vibration reported			
Terms & Condition			
Incoterms	: Ex-works		
TAT	: 4 weeks (ARO)		
Validity	: Till 31st MAY 2022		
Payment Terms	: Full payment prior to delivery		
Currency	: Quoted in United States Dollars		
Evaluation Charges if RAI	: US\$481		
C of C will be issued after repair. End User : Royal Malaysian Navy (TDLM)			
CTIPL Standard Terms and Conditions apply. Copy attached.			

Please advise cost approval. Thank you

Best Regards

Michael Tay

Dy. General Manager, Operations.

Cost Accepted	<input type="checkbox"/>
RAI (Return As Is)	<input type="checkbox"/>
_____	_____
Name/Signature	Date



COMPOSITE TECHNOLOGY INTERNATIONAL PTE LTD
39, LOYANG WAY, SINGAPORE 508735
TEL : 65 65421121 FAX : 65 65425383
E-MAIL : michael_tay@composite-technology.com.sg

TO : Galaxy Aerospace (M) Sdn Bhd.
ATTN : Nur Syamim Syuhada Amdan
SUBJECT : Quotation

REF. : F21-048
PAGES : 3/3
DATE : 19/APR/2022

Order No.	: RMN22-300		
Description	: Main Rotor Blade	Serial No.	: 33588
Part No.	: 355A11-0030-04	Job No.	: 15885
Work Scope			
S01B	Receiving / Inspection	US\$ 481	
B06	Replace Lower Surface PU Tape	US\$ 4,761	
S01A	Repaint & Static Balance	US\$ 4,423	
		Total	US\$ 9,665
Inspection Revealed			
Lower Surface PU reverted Surface paint erosion Lateral vibration reported			
Terms & Condition			
Incoterms	: Ex-works		
TAT	: 4 weeks (ARO)		
Validity	: Till 31st MAY 2022		
Payment Terms	: Full payment prior to delivery		
Currency	: Quoted in United States Dollars		
Evaluation Charges if RAI	: US\$481		
C of C will be issued after repair. End User : Royal Malaysian Navy (TDLM)			
CTIPL Standard Terms and Conditions apply. Copy attached.			

Please advise cost approval. Thank you

Best Regards

Michael Tay
Dy. General Manager, Operations.

Cost Accepted	<input type="checkbox"/>
RAI (Return As Is)	<input type="checkbox"/>
_____	_____
Name/Signature	Date