



COMPOSITE TECHNOLOGY INTERNATIONAL PTE LTD
39, LOYANG WAY, SINGAPORE 508735
TEL : 65 65421121 FAX : 65 65425383
E-MAIL : michael_tay@composite-technology.com.sg

TO : Galaxy Aerospace (M) Sdn Bhd.
ATTN : Nur Syamim Syuhada Amdan
SUBJECT : Quotation

REF. : F23-068
PAGES : 1/2
DATE : 13/Jul/2023

Order No.	: RMN-23-1086		
Description	: Main Rotor Blade	Serial No.	: 21936
Part No.	: 355A11-0030-02	Job No.	: 16265
Work Scope			
Receiving / Inspection		US\$	500
Replace Lower Surface PU (Root PU & PU Wedges inclusive)		US\$	5,428
Repaint & Static Balance		US\$	4,600
	Total	US\$	10,528
Inspection Revealed			
Lower Surface PU reverted PU Wedges reverted Surface paint erosion Note : Unable to achieve lateral balance on ground reported.			
Terms & Condition			
Incoterms	: Ex-works		
TAT	: 6 weeks (ARO)		
Validity	: Till 30th Aug 2023		
Payment Terms	: Full payment prior to delivery		
Full payment shall be made within thirty (30) days from date of invoice. Late payment exceeding the next thirty (30) days shall be charged interest & store rent on outstanding amount due on a day-to-day basis from the due date to the date of payment (both dates inclusive) at a flat rate of 1.5% per month for each month or part thereof.			
Currency	: Quoted in United States Dollars		
Evaluation Charges if RAI	: US\$500		
Military use - C of C will be issued after repair			
CTIPL Standard Terms and Conditions apply. Copy attached.			

Please advise cost approval. Thank you

Best Regards

Michael Tay
Dy. General Manager, Operations.

Cost Accepted	<input type="checkbox"/>
RAI (Return As Is)	<input type="checkbox"/>
_____ Name/Signature	_____ Date



COMPOSITE TECHNOLOGY INTERNATIONAL PTE LTD
39, LOYANG WAY, SINGAPORE 508735
TEL : 65 65421121 FAX : 65 65425383
E-MAIL : michael_tay@composite-technology.com.sg

TO : Galaxy Aerospace (M) Sdn Bhd.
ATTN : Nur Syamim Syuhada Amdan
SUBJECT : Quotation

REF. : F23-068
PAGES : 2/2
DATE : 13/Jul/2023

Order No.	: RMN-23-1087		
Description	: Main Rotor Blade	Serial No.	: 25331
Part No.	: 355A11-0030-02	Job No.	: 16266
Work Scope			
Receiving / Inspection		US\$ 500	
Replace Outboard L/E Strip		US\$ 4,886	
Replace Lower Surface PU (Root PU & PU Wedges inclusive)		US\$ 5,428	
Repaint & Static Balance		US\$ 4,600	
	Total	US\$ 15,414	
Inspection Revealed			
Outboard L/E Strip eroded Lower Surface PU reverted PU Wedges reverted Surface paint erosion			
Terms & Condition			
Incoterms	: Ex-works		
TAT	: 6 weeks (ARO)		
Validity	: Till 30th Aug 2023		
Payment Terms	: Full payment prior to delivery		
Full payment shall be made within thirty (30) days from date of invoice. Late payment exceeding the next thirty (30) days shall be charged interest & store rent on outstanding amount due on a day-to-day basis from the due date to the date of payment (both dates inclusive) at a flat rate of 1.5% per month for each month or part thereof.			
Currency	: Quoted in United States Dollars		
Evaluation Charges if RAI	: US\$500		
Military use - C of C will be issued after repair			
CTIPL Standard Terms and Conditions apply. Copy attached.			

Please advise cost approval. Thank you

Best Regards

Michael Tay
Dy. General Manager, Operations.

Cost Accepted	<input type="checkbox"/>
RAI (Return As Is)	<input type="checkbox"/>
_____ Name/Signature	_____ Date